

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
01/14/2014

Document Number:
663902652

Overall Inspection:
Satisfactory

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	<input type="checkbox"/>
	311638	311638	LONGWORTH, MIKE	2A Doc Num:	

Operator Information:

OGCC Operator Number: _____

Name of Operator: ENCANA OIL & GAS (USA) INC

Address: 370 17TH ST STE 1700

City: DENVER State: CO Zip: 80202-

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Insp., General	970-285-2665	cogcc.inspections@encana.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Compliance Summary:

QtrQtr: NENW Sec: 4 Twp: 6S Range: 96W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
08/12/2013	663900642			Satisfactory	F		No

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
282774	WELL	PR	12/01/2009	GW	045-11838	N. PARACHUTE MF07C-4 C04 696	PR	<input checked="" type="checkbox"/>
282775	WELL	PA	06/07/2007	GW	045-11837	N.PARACHUTE MF13B C04 696	PA	<input checked="" type="checkbox"/>
282776	WELL	PR	04/27/2007	GW	045-11836	N.PARACHUTE MF 13D C04 696	PR	<input checked="" type="checkbox"/>
282777	WELL	PR	04/12/2007	GW	045-11835	N. PARACHUTE MF04D CO4 696	PR	<input checked="" type="checkbox"/>
282778	WELL	PR	01/23/2006	GW	045-11834	N.PARACHUTE MF02C C04 696	PR	<input checked="" type="checkbox"/>
282779	WELL	PR	01/23/2006	GW	045-11833	N.PARACHUTE MF08C C04 696	PR	<input checked="" type="checkbox"/>
282780	WELL	PR	01/23/2006	GW	045-11832	N.PARACHUTE MF03A C04 696	PR	<input checked="" type="checkbox"/>
282781	WELL	PR	11/30/2009	GW	045-11831	N. PARACHUTE MF06C-4 C04 696	PR	<input checked="" type="checkbox"/>
282784	WELL	PR	01/23/2006	GW	045-11829	N.PARACHUTE MF08A CO4 696	PR	<input checked="" type="checkbox"/>
282785	WELL	PR	01/23/2006	GW	045-11828	N.PARACHUTE MF01C CO4 696	PR	<input checked="" type="checkbox"/>

282786	WELL	PR	07/24/2009	GW	045-11827	N. PARACHUTE MF07A-4 CO4 696	PR	<input checked="" type="checkbox"/>
284640	WELL	PR	12/01/2009	GW	045-12249	N. PARACHUTE MF06B-4 CO4 696	PR	<input checked="" type="checkbox"/>
295477	WELL	PR	03/01/2010	GW	045-15766	N. PARACHUTE MF01C-4 CO4 696	PR	<input checked="" type="checkbox"/>
295478	WELL	PR	07/14/2011	GW	045-15767	N. PARACHUTE MF13D-31 C04 69	PR	<input checked="" type="checkbox"/>
295479	WELL	PR	02/20/2010	GW	045-15768	N. PARACHUTE MF04B-3 CO4 696	PR	<input checked="" type="checkbox"/>
295480	WELL	PR	02/15/2010	GW	045-15769	N. PARACHUTE MF03C-4 C04 696	PR	<input checked="" type="checkbox"/>
295481	WELL	PR	01/14/2010	GW	045-15770	N. PARACHUTE MF02C-4 CO4 696	PR	<input checked="" type="checkbox"/>
295482	WELL	PR	02/10/2010	GW	045-15771	N. PARACHUTE MF06A-4 CO4 696	PR	<input checked="" type="checkbox"/>
295483	WELL	PR	02/22/2010	GW	045-15772	N. PARACHUTE MF02B-4 CO4 696	PR	<input checked="" type="checkbox"/>
295487	WELL	PR	01/13/2010	GW	045-15777	N. PARACHUTE MF13C-31 C04 69	PR	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access	Satisfactory			

Signs/Marker:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
BATTERY	Satisfactory			
TANK LABELS/PLACARDS	Satisfactory			
CONTAINERS	Satisfactory			
WELLHEAD	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

Multiple Spills and Releases?

Equipment:					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Other	5	Satisfactory	5 Gas lift sheds		
Plunger Lift	19	Satisfactory			
Ancillary equipment	4	Satisfactory	Chemical totes 3 at wells 1 at Gas Lift sheds		

Facilities: New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
CONDENSATE	1		STEEL AST	

S/U/V: Satisfactory Comment: _____

Corrective Action: _____ Corrective Date: _____

Paint

Condition	_____
-----------	-------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action _____ Corrective Date _____

Comment _____

Venting:

Yes/No	Comment

Flaring:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 311638

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/UV: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/UV: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/UV: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 282774 Type: WELL API Number: 045-11838 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Facility ID: 282775 Type: WELL API Number: 045-11837 Status: PA Insp. Status: PA

Facility ID: 282776 Type: WELL API Number: 045-11836 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Facility ID: 282777 Type: WELL API Number: 045-11835 Status: PR Insp. Status: PR

Producing Well				
Comment: Producing well				
Facility ID:	282778	Type:	WELL	API Number: 045-11834
Status:	PR	Insp. Status:	PR	
Producing Well				
Comment: Producing well				
Facility ID:	282779	Type:	WELL	API Number: 045-11833
Status:	PR	Insp. Status:	PR	
Producing Well				
Comment: Producing well				
Facility ID:	282780	Type:	WELL	API Number: 045-11832
Status:	PR	Insp. Status:	PR	
Producing Well				
Comment: Producing well				
Facility ID:	282781	Type:	WELL	API Number: 045-11831
Status:	PR	Insp. Status:	PR	
Producing Well				
Comment: Producing well				
Facility ID:	282784	Type:	WELL	API Number: 045-11829
Status:	PR	Insp. Status:	PR	
Producing Well				
Comment: Producing well				
Facility ID:	282785	Type:	WELL	API Number: 045-11828
Status:	PR	Insp. Status:	PR	
Producing Well				
Comment: Producing well				
Facility ID:	282786	Type:	WELL	API Number: 045-11827
Status:	PR	Insp. Status:	PR	
Producing Well				
Comment: Producing well				
Facility ID:	284640	Type:	WELL	API Number: 045-12249
Status:	PR	Insp. Status:	PR	
Producing Well				
Comment: Producing well				
Facility ID:	295477	Type:	WELL	API Number: 045-15766
Status:	PR	Insp. Status:	PR	
Producing Well				
Comment: Producing well				
Facility ID:	295478	Type:	WELL	API Number: 045-15767
Status:	PR	Insp. Status:	PR	
Producing Well				
Comment: Producing well				
Facility ID:	295479	Type:	WELL	API Number: 045-15768
Status:	PR	Insp. Status:	PR	
Producing Well				
Comment: Producing well				

Facility ID: 295480 Type: WELL API Number: 045-15769 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Facility ID: 295481 Type: WELL API Number: 045-15770 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Facility ID: 295482 Type: WELL API Number: 045-15771 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Facility ID: 295483 Type: WELL API Number: 045-15772 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Facility ID: 295487 Type: WELL API Number: 045-15777 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
 Comment: _____
 Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____
 Comment: _____
 Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____
 Land Use: _____
 Comment: _____

1003a. Debris removed? Pass CM _____
 CA _____ CA Date _____
 Waste Material Onsite? Pass CM _____
 CA _____ CA Date _____
 Unused or unneeded equipment onsite? Pass CM _____
 CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors removed? Pass CM _____
 CA _____ CA Date _____
 Guy line anchors marked? _____ CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? Fail Production areas stabilized ? Pass
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Fail
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____
 Comment: Snow cover on location and reclaim areas

Overall Interim Reclamation Fail

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____
 Final Land Use: _____
 Reminder: _____
 Comment:
 Well plugged _____ Pit mouse/rat holes, cellars backfilled _____
 Debris removed _____ No disturbance /Location never built _____
 Access Roads Regraded _____ Contoured _____ Culverts removed _____
 Gravel removed _____
 Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____
 Compaction alleviation _____ Dust and erosion control _____
 Non cropland: Revegetated 80% _____ Cropland: perennial forage _____
 Weeds present _____ Subsidence _____
 Comment:

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Culverts				
Ditches		Ditches				
Berms		Compaction	Pass	MHSP	Pass	

S/U/V: Satisfactory _____ Corrective Date: _____

Comment: Snow cover on location and BMPs

CA: _____

Pits: NO SURFACE INDICATION OF PIT