

Photo Album
Calcium Chloride and Separator Pit Characterization
Roan Creek Federal 25-3
Prepared for: Maralex Resources, Inc.
Attention: Mr. Jim Graves and Naomi Azulai
For Submission To The Bureau of Land Management
Site Visit and Photography Occurred on
April 25, 2013

Prepared by:
Environmental Services, Inc.
429 Buckpoint Road
Carbondale, Colorado 81623



Photo 1 Separator Pit



Photo 2 Facility placard



Photo 3 Calcium Chloride Pit



Photo 4 Calcium Chloride Pit



Photo 5 Calcium Chloride Pit



Photo 6 Calcium Chloride Pit – sampling location



Photo 7 Separator Pit