

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



| | | | |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:

01/21/2014

Document Number:

600000673

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

| | | | | |
|---------------------|-------------|--------|------------------|--|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection |
| | 282769 | 332918 | JOHNSON, RANDELL | <input type="checkbox"/> 2A Doc Num: _____ |

Operator Information:

OGCC Operator Number:

Name of Operator: KERR-MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-----------------------------------|-------------------------|----------------------------|
| Avant, Paul | O:720-929-6457, C:720-273-2688 | paul.avant@anadarko.com | Rockies Regulatory Affairs |

Compliance Summary:

| | | | | | | | |
|---------------------|-----------|----------------|----------------|------------------------------|-------------------|----------------|-----------------|
| QtrQtr: <u>NENW</u> | | Sec: <u>14</u> | Twp: <u>2N</u> | | Range: <u>67W</u> | | |
| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Unsatisfactory | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
| 02/24/2009 | 200205546 | PR | PR | Satisfactory | | | No |

Inspector Comment:**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|--|
| 117999 | PIT | | 09/23/1999 | | - | PHILLIP MCCOY "C" | <input type="checkbox"/> |
| 118078 | PIT | | 09/23/1999 | | - | PHILLIP MCCOY 1 | <input type="checkbox"/> |
| 240093 | WELL | PR | 02/01/2011 | OW | 123-07881 | MCCOY PHILLIP 1 | PR <input type="checkbox"/> |
| 282769 | WELL | PR | 08/03/2010 | OW | 123-23554 | WELLMAN 5-14 | SI <input checked="" type="checkbox"/> |

Equipment:**Location Inventory**

| | | | |
|-----------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Motors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location**Signs/Marker:**

| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|----------|-----------------------------|---------|-------------------|---------|
| WELLHEAD | Satisfactory | | | |

Inspector Name: JOHNSON, RANDELL

| | |
|--|------------------------|
| Emergency Contact Number: (S/U/V) Satisfactory | Corrective Date: _____ |
| Comment: _____ | |
| Corrective Action: _____ | |

| | | | | |
|--|------|--------|-------------------|---------|
| Spills: | | | | |
| Type | Area | Volume | Corrective action | CA Date |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |

| | | | | |
|------------------|-----------------------------|---------|-------------------|---------|
| Fencing/: | | | | |
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| WELLHEAD | Satisfactory | | | |

| | | | | | |
|-------------------|---|-----------------------------|---------|-------------------|---------|
| Equipment: | | | | | |
| Type | # | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| Plunger Lift | 1 | Satisfactory | | | |

| | | | | |
|--------------------|--------------|-----------------------------------|---|-----------------------|
| Facilities: | | <input type="checkbox"/> New Tank | Tank ID: _____ | |
| Contents | # | Capacity | Type | SE GPS |
| | | | CENTRALIZED BATTERY | 40.140620,-104.864400 |
| S/U/V: | Satisfactory | Comment: | See related inspection document #600000671 for information concerning shared facilities and equipment | |
| Corrective Action: | | | Corrective Date: | |

| | |
|------------------------|----------|
| Paint | |
| Condition | Adequate |
| Other (Content) _____ | |
| Other (Capacity) _____ | |
| Other (Type) _____ | |

| | | | | |
|-------------------|----------|---------------------|---------------------|-------------|
| Berms | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Corrective Action | | | Corrective Date | |
| Comment | | | | |

| | |
|-----------------|---------|
| Venting: | |
| Yes/No | Comment |
| NO | |

| | | | | |
|-----------------|-----------------------------|---------|-------------------|---------|
| Flaring: | | | | |
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| | | | | |

Predrill

Location ID: 282769

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/U/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/U/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/U/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:**Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Facility**

Facility ID: 282769 Type: WELL API Number: 123-23554 Status: PR Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

S/V: _____ CA Date: _____

CA: _____

Comment: Producing intermittently

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Inspector Name: JOHNSON, RANDELL

| | | | |
|---|--|------------------------------|-------------|
| Comment: <input style="width: 700px;" type="text"/> | | | |
| Corrective Action: _____ | | Date: _____ | |
| Reportable: _____ | GPS: Lat _____ | Long _____ | |
| Proximity to Surface Water: _____ | | Depth to Ground Water: _____ | |
| Water Well: | | | |
| DWR Receipt Num: _____ | | Owner Name: _____ | GPS : _____ |
| Lat _____ | | Long _____ | |
| Field Parameters: | | | |
| <input style="width: 300px;" type="text"/> | | | |
| Sample Location: <input style="width: 400px;" type="text"/> | | | |
| Emission Control Burner (ECB): _____ | | | |
| Comment: _____ | | | |
| Pilot: _____ | Wildlife Protection Devices (fired vessels): _____ | | |

Reclamation - Storm Water - Pit

Interim Reclamation:

| | |
|---|---|
| Date Interim Reclamation Started: _____ | Date Interim Reclamation Completed: _____ |
| Land Use: _____ | |
| Comment: <input style="width: 750px;" type="text"/> | |
| 1003a. | Debris removed? <u>Pass</u> CM _____ |
| | CA _____ CA Date _____ |
| | Waste Material Onsite? <u>Pass</u> CM _____ |
| | CA _____ CA Date _____ |
| | Unused or unneeded equipment onsite? <u>Pass</u> CM _____ |
| | CA _____ CA Date _____ |
| | Pit, cellars, rat holes and other bores closed? <u>Pass</u> CM _____ |
| | CA _____ CA Date _____ |
| | Guy line anchors removed? <u>Pass</u> CM _____ |
| | CA _____ CA Date _____ |
| | Guy line anchors marked? _____ CM _____ |
| | CA _____ CA Date _____ |
| 1003b. | Area no longer in use? <u>Pass</u> Production areas stabilized ? <u>Pass</u> |
| 1003c. | Compacted areas have been cross ripped? _____ |
| 1003d. | Drilling pit closed? _____ Subsidence over on drill pit? _____ |
| | Cuttings management: _____ |
| 1003e. | Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? <u>Pass</u> |
| | Production areas have been stabilized? <u>Pass</u> Segregated soils have been replaced? _____ |

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Inspector Name: JOHNSON, RANDELL

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____ P _____

Comment: _____

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

S/U/V: Satisfactory _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT