

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
01/22/2014

Document Number:
670201184

Overall Inspection:
Satisfactory

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	<input type="checkbox"/>
	<u>279726</u>	<u>335571</u>	<u>BURGER, CRAIG</u>	2A Doc Num:	

Operator Information:

OGCC Operator Number:	
Name of Operator:	<u>WPX ENERGY ROCKY MOUNTAIN LLC</u>
Address:	<u>1001 17TH STREET - SUITE #1200</u>
City:	<u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		Shaun.Kellerby@state.co.us	NW Field Supervisor
Gardner, Michael		Michael.Gardner@wpxenergy.com	Environmental Manager
Moss, Brad		Brad.Moss@wpxenergy.com	Production Foreman

Compliance Summary:

QtrQtr:	<u>SWNW</u>	Sec:	<u>15</u>	Twp:	<u>6S</u>	Range:	<u>94W</u>
---------	-------------	------	-----------	------	-----------	--------	------------

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
03/17/2010	200237525	PR	PR	Satisfactory			No
01/16/2008	200124866	PR	PR	Satisfactory	I		No
09/25/2007	200123723	PR	PR	Satisfactory	I		No
03/05/2007	200106222	PR	PR	Satisfactory	I	Pass	No
07/05/2006	200098596	DG	WO	Satisfactory		Pass	No
03/30/2006	200088854	PR	WO	Satisfactory		Pass	No

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
275252	WELL	PR	08/29/2005	GW	045-13501	CLOUGH RWF 11-15	PR	<input checked="" type="checkbox"/>
275253	WELL	PR	08/29/2005	GW	045-13502	CLOUGH RWF 311-15	PR	<input checked="" type="checkbox"/>
279726	WELL	PR	09/02/2005	GW	045-11081	CLOUGH RWF 411-15	PR	<input checked="" type="checkbox"/>
279926	WELL	PR	10/06/2006	GW	045-11111	CLOUGH RWF 421-15	PR	<input checked="" type="checkbox"/>
279927	WELL	PR	08/08/2006	GW	045-11112	CLOUGH RWF 422-15	PR	<input checked="" type="checkbox"/>
279928	WELL	PR	08/08/2006	GW	045-11113	CLOUGH RWF 511-15	PR	<input checked="" type="checkbox"/>
279929	WELL	PR	06/08/2006	GW	045-11114	CLOUGH RWF 332-15	PR	<input checked="" type="checkbox"/>
279930	WELL	PR	06/08/2006	GW	045-11115	CLOUGH RWF 22-15	PR	<input checked="" type="checkbox"/>
279931	WELL	PR	06/08/2006	GW	045-11116	CLOUGH RWF 12-15	PR	<input checked="" type="checkbox"/>

279932	WELL	PR	06/08/2006	GW	045-11117	CLOUGH RWF 522-15	PR	<input checked="" type="checkbox"/>
279933	WELL	PR	03/06/2007	GW	045-11118	CLOUGH RWF 21-15	PR	<input checked="" type="checkbox"/>
279934	WELL	PR	09/12/2005	GW	045-11119	CLOUGH RWF 321-15	PR	<input checked="" type="checkbox"/>

Equipment: Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:				
Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access	Satisfactory	Surface poly pipeline along access road.		

Signs/Marker:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
BATTERY	Satisfactory			
TANK LABELS/PLACARDS	Satisfactory			
WELLHEAD	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory	wire fence		
TANK BATTERY	Satisfactory	wire fence		
SEPARATOR	Satisfactory	wire fence		

Equipment:					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Gathering Line	1	Satisfactory			
Ancillary equipment	1	Satisfactory	methanol unit		
Bird Protectors	8	Satisfactory			
Gas Meter Run	1	Satisfactory			
Horizontal Heated Separator	12	Satisfactory			
Plunger Lift	12	Satisfactory			

Facilities:		<input type="checkbox"/> New Tank	Tank ID: _____	
Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST	,
S/U/V:	Satisfactory	Comment: same berm as 400 bbl tank		
Corrective Action:				Corrective Date:
<u>Paint</u>				
Condition	Adequate			
Other (Content)	_____			
Other (Capacity)	_____			
Other (Type)	_____			
<u>Berms</u>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Corrective Action				Corrective Date
Comment				

Facilities:		<input type="checkbox"/> New Tank	Tank ID: _____	
Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	200 BBLS	STEEL AST	,
S/U/V:	Satisfactory	Comment: same berm as 400 bbl tank		
Corrective Action:				Corrective Date:
<u>Paint</u>				
Condition	Adequate			
Other (Content)	_____			
Other (Capacity)	_____			
Other (Type)	_____			
<u>Berms</u>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Corrective Action				Corrective Date
Comment				

Facilities:		<input type="checkbox"/> New Tank	Tank ID: _____		
Contents	#	Capacity	Type	SE GPS	
CONDENSATE	1	400 BBLS	STEEL AST	39.528050,-107.879910	
S/U/V:	Satisfactory	Comment:			
Corrective Action:				Corrective Date:	
Paint					
Condition	Adequate				
Other (Content)	_____				
Other (Capacity)	_____				
Other (Type)	_____				
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Corrective Action				Corrective Date	
Comment					
Venting:					
Yes/No	Comment				
YES	bradenhead valves open				
Flaring:					
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date	

Predrill

Location ID: 279726

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/U/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/U/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/U/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 275252 Type: WELL API Number: 045-13501 Status: PR Insp. Status: PR

Producing Well

Comment: **plunger lift**

Facility ID: 275253 Type: WELL API Number: 045-13502 Status: PR Insp. Status: PR

Producing Well

Comment: **plunger lift**

Facility ID: 279726 Type: WELL API Number: 045-11081 Status: PR Insp. Status: PR

Producing Well

Comment: **plunger lift**

Facility ID: 279926	Type: WELL	API Number: 045-11111	Status: PR	Insp. Status: PR
Producing Well				
Comment: plunger lift				
Facility ID: 279927	Type: WELL	API Number: 045-11112	Status: PR	Insp. Status: PR
Producing Well				
Comment: plunger lift				
Facility ID: 279928	Type: WELL	API Number: 045-11113	Status: PR	Insp. Status: PR
Producing Well				
Comment: plunger lift				
Facility ID: 279929	Type: WELL	API Number: 045-11114	Status: PR	Insp. Status: PR
Producing Well				
Comment: plunger lift				
Facility ID: 279930	Type: WELL	API Number: 045-11115	Status: PR	Insp. Status: PR
Producing Well				
Comment: plunger lift				
Facility ID: 279931	Type: WELL	API Number: 045-11116	Status: PR	Insp. Status: PR
Producing Well				
Comment: plunger lift				
Facility ID: 279932	Type: WELL	API Number: 045-11117	Status: PR	Insp. Status: PR
Producing Well				
Comment: plunger lift				
Facility ID: 279933	Type: WELL	API Number: 045-11118	Status: PR	Insp. Status: PR
Producing Well				
Comment: plunger lift				
Facility ID: 279934	Type: WELL	API Number: 045-11119	Status: PR	Insp. Status: PR
Producing Well				
Comment: plunger lift				

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well: _____ Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): N _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): YES _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: Snow cover limited inspection.

1003a. Debris removed? Pass CM _____

CA _____ CA Date _____

Waste Material Onsite? Pass CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? Pass Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____
 Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____
 Debris removed _____ No disturbance /Location never built _____
 Access Roads Regraded _____ Contoured _____ Culverts removed _____
 Gravel removed _____
 Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____
 Compaction alleviation _____ Dust and erosion control _____
 Non cropland: Revegetated 80% _____ Cropland: perennial forage _____
 Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Pass			
Compaction	Pass	Compaction	Pass			
		Sediment Traps	Pass			

S/U/V: Satisfactory _____ Corrective Date: _____

Comment: Snow cover limited inspection.

CA: _____

Pits: NO SURFACE INDICATION OF PIT