

**FORM  
INSP**Rev  
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

01/31/2014

Document Number:

668602045

Overall Inspection:

**Unsatisfactory****FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	212650	324795	QUINT, CRAIG	<input type="checkbox"/>	

**Operator Information:**

OGCC Operator Number:

Name of Operator: WESTERN OPERATING COMPANYAddress: 518 17TH ST STE 200City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
Hart, Dale	719-688-1638 cell	dalehartwoc@fairpoint.net	
LEONARD, MIKE		mike.leonard@state.co.us	

**Compliance Summary:**QtrQtr: NENW Sec: 15 Twp: 19S Range: 45W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
02/02/2012	664000344	PR	PR	Unsatisfactory			No
08/15/2011	200321594	ES	PR	Unsatisfactory			Yes
06/02/2011	200312528	ES	PR	Unsatisfactory			Yes
05/09/2011	200310291	PR	PR	Satisfactory			No
12/09/2010	200288471	ES	PR	Unsatisfactory			Yes
08/30/2010	200268921	PR	PR	Unsatisfactory			Yes
06/29/2010	200261214	ES	PR	Unsatisfactory			Yes
06/02/2010	200254182	PR	PR	Unsatisfactory			Yes
05/28/2010	200253252	CO	PR	Unsatisfactory			Yes
01/23/2009	200203045	PR	PR	Satisfactory			No
08/21/2007	200117935	PR	PR	Satisfactory			No
08/20/2007	200117671	ES	PR	Unsatisfactory			Yes
03/20/2007	200106770	ES	PR	Unsatisfactory	F	Fail	Yes
12/19/2001	200022590	PR	PR	Satisfactory		Pass	No
11/01/2001	200021236	CO	PR	Unsatisfactory		Fail	Yes
04/07/2000	200011618	PR	PR	Satisfactory	I	Pass	No
08/13/1998	500144492	PR	PR			Pass	No
10/30/1996	500144491	PR	PR			Pass	No
03/05/1996	500144490	PR	PR			Pass	No
10/18/1995	500144489	PR	PR			Pass	No

Inspector Name: QUINT, CRAIG

11/07/1994	500144488		PR				
04/07/1994	500144487		SI				

**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
115282	PIT		09/23/1999		-	FOSTER		<input type="checkbox"/>
212650	WELL	PR	05/15/2010	OW	061-06010	FOSTER 1	PR	<input checked="" type="checkbox"/>

**Equipment:**Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location****Lease Road:**

Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access	Satisfactory	PARTIALLY GRAVELED ROAD THROUGH PASTURE.		

**Signs/Marker:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
TANK LABELS/PLACARDS	Satisfactory	METAL SIGNS BY TANKS		
WELLHEAD	Satisfactory	LEASE SIGN BY UNIT		
BATTERY	Satisfactory	LEASE SIGN BY TANKS		

Emergency Contact Number: (S/U/V) Satisfactory

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

**Good Housekeeping:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
OTHER	Unsatisfactory	SOIL HAS BEEN STOCKPILED ON LOCATION FROM CLEAN UP IN BERMS. TESTED AND IS AWAITING APPROVAL FOR FURTHER REMOVAL PROCESS.	OPERATOR REPRESENTATIVE WAITING ON REPLY FROM COGCC AS TO APPROVAL FOR REMOVAL.	04/30/2014

<b>Spills:</b>				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing:</b>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
TANK BATTERY	Satisfactory	BATTERY FENCED WITH WIRE.		
<b>Equipment:</b>				
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action
Prime Mover	1	Satisfactory	ELEC MOTOR	
Pump Jack	1	Satisfactory	160 NATIONAL ON A CEMENT PAD	
Deadman # & Marked	4	Satisfactory		
Ancillary equipment	2	Satisfactory	ELEC PANEL, BELLOWS GAS METER	
<b>Facilities:</b>		<input type="checkbox"/> New Tank      Tank ID: _____		
Contents	#	Capacity	Type	SE GPS
CRUDE OIL	2	400 BBLS	STEEL AST	38.409660,-102.448440
S/U/V:	Satisfactory	Comment:	WILDLIFE NETTING OVER TOP OF TANK TO COVER HOLES.	
Corrective Action:				Corrective Date:
<b>Paint</b>				
Condition				
Other (Content)				
Other (Capacity)				
Other (Type)				
<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Corrective Action				Corrective Date
Comment				
<b>Venting:</b>				
Yes/No	Comment			
<b>Flaring:</b>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

**Predrill**

Location ID: 212650

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/U/V:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****S/U/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Wildlife BMPs:****S/U/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Stormwater:****Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

**Operator Rep. Contact Information:**

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

**LGD Contact Information:**

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

**Summary of Landowner Issues:****Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Facility**

Facility ID: 212650 Type: WELL API Number: 061-06010 Status: PR Insp. Status: PR

**Producing Well**

Comment: SHUT IN FOR WORK OVER.

**Workover**

Comment: CODELL WELL SERVICE RIG #1 ON WELL TRIPPING PUMP AND RODS.

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Inspector Name: QUINT, CRAIG

Corrective Action: _____		Date: _____	
Reportable: _____	GPS: Lat _____	Long _____	
Proximity to Surface Water: _____		Depth to Ground Water: _____	

<b>Water Well:</b>		Lat _____	Long _____
DWR Receipt Num: _____	Owner Name: _____	GPS : _____	_____

**Field Parameters:**

Sample Location:

Complaint:				
Tracking Num	Category	Assigned To	Description	Incident Date
200265192	OTHER	LINDBLOM, STEVE	On or about June 1, 2010, while investigatin for OTHER damages or violation of COGCC Rules and Regulations, I discovered a rather large quantity (I would estimate at LEAST five barrels) of crude oil standing inside the berm at the #1 Foster tank battery. Since Western Operating has not seen fit to properly remediate their previous two fluid spills (both outside the berm), I would request they be fined a maximum amount and have their clean-up of this spill closely monitored by a competent authority.	08/04/2010

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment:

1003a.	Debris removed?	<u>Pass</u>	CM	_____	
	CA	_____			CA Date _____
	Waste Material Onsite?	<u>Pass</u>	CM	_____	
	CA	_____			CA Date _____
	Unused or unneeded equipment onsite?	<u>Pass</u>	CM	_____	
	CA	_____			CA Date _____
	Pit, cellars, rat holes and other bores closed?	<u>Pass</u>	CM	_____	
	CA	_____			CA Date _____
	Guy line anchors removed?	_____	CM	_____	
	CA	_____			CA Date _____
	Guy line anchors marked?	<u>Pass</u>	CM	_____	
	CA	_____			CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

Inspector Name: QUINT, CRAIG

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass

Production areas have been stabilized? Pass Segregated soils have been replaced? Pass

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced Pass Recontoured Pass 80% Revegetation Pass

1003 f. Weeds Noxious weeds? P

Comment: UNUSED AREAS OF THE LOCATION ARE PASTURE.

Overall Interim Reclamation Pass

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

S/U/V: Satisfactory Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

Pits: ☒ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date	
SOIL HAS BEEN STOCKPILED ON LOCATION FROM CLEAN UP IN BERMS. TESTED AND IS AWAITING APPROVAL FOR FURTHER REMOVAL PROCESS. COMPLY WITH N.O.A.V.	quintc	01/31/2014	