

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

02/04/2014

Document Number:

670201217

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	417053	335529	BURGER, CRAIG	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:

Name of Operator: WPX ENERGY ROCKY MOUNTAIN LLCAddress: 1001 17TH STREET - SUITE #1200City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Moss, Brad		Brad.Moss@wpxenergy.com	Production Foreman
Gardner, Michael		Michael.Gardner@wpxenergy.com	Environmental Manager
Kellerby, Shaun		Shaun.Kellerby@state.co.us	NW Field Supervisor

Compliance Summary:QtrQtr: SWSE Sec: 18 Twp: 6S Range: 91W**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
256057	WELL	DA	07/09/2000	DA	045-07426	FEDERAL 18-15	DA	<input type="checkbox"/>
297017	WELL	PR	01/26/2009	GW	045-16264	KOKOPELLI FED 18-213D	PR	<input checked="" type="checkbox"/>
297018	WELL	PR	01/26/2009	GW	045-16265	KOKOPELLI FED 18-313D	PR	<input checked="" type="checkbox"/>
297019	WELL	PR	01/26/2009	GW	045-16266	KOKOPELLI FED 18-215D	PR	<input checked="" type="checkbox"/>
297020	WELL	PR	09/22/2010	GW	045-16267	KOKOPELLI FED 18-315D	PR	<input checked="" type="checkbox"/>
417052	WELL	PR	09/06/2012	GW	045-19446	Federal KP 544-18	PR	<input checked="" type="checkbox"/>
417053	WELL	PR	12/01/2012	GW	045-19447	Federal KP 344-18	PR	<input checked="" type="checkbox"/>
417057	WELL	PR	07/03/2013	GW	045-19448	Federal KP 414-18	PR	<input checked="" type="checkbox"/>
417059	WELL	PR	07/03/2013	GW	045-19449	Federal KP 523-18	PR	<input checked="" type="checkbox"/>
422639	PIT	CL	04/07/2011		-	KP 34-18	CL	<input type="checkbox"/>
422763	WELL	PR	10/17/2012	LO	045-20625	Federal KP 14-18	PR	<input checked="" type="checkbox"/>
422769	WELL	PR	10/17/2012	LO	045-20626	Federal KP 24-18	PR	<input checked="" type="checkbox"/>
422774	WELL	PR	10/17/2012	LO	045-20627	Federal KP 34-18	PR	<input checked="" type="checkbox"/>
422783	WELL	PR	10/17/2012	LO	045-20628	Federal KP 533-18	PR	<input checked="" type="checkbox"/>
422785	WELL	PR	01/02/2013	LO	045-20629	Federal KP 514-18	PR	<input checked="" type="checkbox"/>

Inspector Name: BURGER, CRAIG

422788	WELL	PR	10/17/2012	LO	045-20630	Federal KP 433-18	PR	<input checked="" type="checkbox"/>
422792	WELL	PR	11/28/2012	LO	045-20631	Federal KP 534-18	PR	<input checked="" type="checkbox"/>
422795	WELL	PR	10/17/2012	LO	045-20632	Federal KP 44-18	PR	<input checked="" type="checkbox"/>
422796	WELL	PR	01/18/2013	GW	045-20633	Federal KP 524-18	PR	<input checked="" type="checkbox"/>
422799	WELL	PR	12/20/2012	LO	045-20634	Federal KP 444-18	PR	<input checked="" type="checkbox"/>
422801	WELL	PR	10/17/2012	LO	045-20635	Federal KP 314-18	PR	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: <u>1</u>	Drilling Pits: <u> </u>	Wells: <u>20</u>	Production Pits: <u> </u>
Condensate Tanks: <u>4</u>	Water Tanks: <u>4</u>	Separators: <u>20</u>	Electric Motors: <u> </u>
Gas or Diesel Mortors: <u> </u>	Cavity Pumps: <u> </u>	LACT Unit: <u> </u>	Pump Jacks: <u> </u>
Electric Generators: <u> </u>	Gas Pipeline: <u>1</u>	Oil Pipeline: <u> </u>	Water Pipeline: <u>1</u>
Gas Compressors: <u> </u>	VOC Combustor: <u> </u>	Oil Tanks: <u> </u>	Dehydrator Units: <u> </u>
Multi-Well Pits: <u> </u>	Pigging Station: <u> </u>	Flare: <u> </u>	Fuel Tanks: <u> </u>

Location**Signs/Marker:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
BATTERY	Satisfactory			
WELLHEAD	Satisfactory			
TANK LABELS/PLACARDS	Satisfactory			

Emergency Contact Number: (S/U/V) SatisfactoryCorrective Date: Comment: Corrective Action: **Spills:**

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?**Fencing:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
IGNITOR/COMBUSTOR	Satisfactory	wire fence		
TANK BATTERY	Satisfactory	wire fence		
SEPARATOR	Satisfactory	wire fence		
WELLHEAD	Satisfactory	cattle panel		

Equipment:

Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Gathering Line	1	Satisfactory			
Horizontal Heated Separator	20	Satisfactory			
Bird Protectors	20	Satisfactory			
Gas Meter Run	1	Satisfactory			

Inspector Name: BURGER, CRAIG

Emission Control Device	1	Satisfactory			
Dehydrator	1	Satisfactory			
Ancillary equipment	2	Satisfactory	descaler units		
Plunger Lift	19	Satisfactory			
Pig Station	1	Satisfactory			

Facilities: ☐ New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
CONDENSATE	4	300 BBLS	HEATED STEEL AST	39.522080,-107.595070

S/U/V:	Satisfactory	Comment:	
Corrective Action:		Corrective Date:	

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action		Corrective Date	
Comment			

Facilities: ☐ New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	6	300 BBLS	HEATED STEEL AST	,

S/U/V:	Satisfactory	Comment:	same berm as condensate tanks
Corrective Action:		Corrective Date:	

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Corrective Action		Corrective Date	
Comment			

Venting:	
Yes/No	Comment
NO	

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Ignitor/Combustor	Satisfactory			

Predrill

Location ID: 417053

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/U/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Group	User	Comment	Date
Agency	kubeczko	Operator must implement best management practices to contain any unintentional release of fluids.	05/03/2010
Agency	kubeczko	The moisture content of any drill cuttings in a cuttings pit, trench, or pile shall be as low as practicable to prevent accumulation of liquids greater than de minimis amounts. At the time of closure, the drill cuttings must also meet the applicable standards of table 910-1.	05/03/2010
Agency	kubeczko	Location is in a sensitive area because of proximity to surface water; therefore, operator must ensure 110 percent secondary containment for any volume of fluids contained at well site during drilling and completion operations.	05/03/2010

S/U/V: Satisfactory**Comment:** No drilling or completions at time of inspection. No obvious drill cuttings on location.**CA:** _____**Date:** _____**Wildlife BMPs:****S/U/V:** _____ **Comment:** _____**CA:** _____**Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility				
Facility ID: 297017	Type: WELL	API Number: 045-16264	Status: PR	Insp. Status: PR
Producing Well				
Comment: plunger lift				
Facility ID: 297018	Type: WELL	API Number: 045-16265	Status: PR	Insp. Status: PR
Producing Well				
Comment: plunger lift				
Facility ID: 297019	Type: WELL	API Number: 045-16266	Status: PR	Insp. Status: PR
Producing Well				
Comment: plunger lift				
Facility ID: 297020	Type: WELL	API Number: 045-16267	Status: PR	Insp. Status: PR
Producing Well				
Comment: plunger lift				
Facility ID: 417052	Type: WELL	API Number: 045-19446	Status: PR	Insp. Status: PR
Producing Well				
Comment: plunger lift				
Facility ID: 417053	Type: WELL	API Number: 045-19447	Status: PR	Insp. Status: PR
Producing Well				
Comment: plunger lift				
Facility ID: 417057	Type: WELL	API Number: 045-19448	Status: PR	Insp. Status: PR
Producing Well				
Comment: plunger lift				
Facility ID: 417059	Type: WELL	API Number: 045-19449	Status: PR	Insp. Status: PR
Producing Well				
Comment: plunger lift				
Facility ID: 422763	Type: WELL	API Number: 045-20625	Status: PR	Insp. Status: PR
Producing Well				
Comment: plunger lift				
Facility ID: 422769	Type: WELL	API Number: 045-20626	Status: PR	Insp. Status: PR
Producing Well				
Comment: plunger lift				
Facility ID: 422774	Type: WELL	API Number: 045-20627	Status: PR	Insp. Status: PR
Producing Well				
Comment: plunger lift				
Facility ID: 422783	Type: WELL	API Number: 045-20628	Status: PR	Insp. Status: PR

Producing WellComment: **plunger lift**Facility ID: 422785 Type: WELL API Number: 045-20629 Status: PR Insp. Status: PR**Producing Well**Comment: **plunger lift**Facility ID: 422788 Type: WELL API Number: 045-20630 Status: PR Insp. Status: PR**Producing Well**Comment: **plunger lift**Facility ID: 422792 Type: WELL API Number: 045-20631 Status: PR Insp. Status: PR**Producing Well**Comment: **plunger lift**Facility ID: 422795 Type: WELL API Number: 045-20632 Status: PR Insp. Status: PR**Producing Well**Comment: **plunger lift**Facility ID: 422796 Type: WELL API Number: 045-20633 Status: PR Insp. Status: PR**Producing Well**Comment: **plunger lift**Facility ID: 422799 Type: WELL API Number: 045-20634 Status: PR Insp. Status: PR**Producing Well**Comment: **plunger lift**Facility ID: 422801 Type: WELL API Number: 045-20635 Status: PR Insp. Status: PR**Producing Well**Comment: **plunger lift****Environmental****Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Inspector Name: BURGER, CRAIG

Emission Control Burner (ECB): Y

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use: RANGELAND

Comment: Snow cover limited inspection.

1003a. Debris removed? Pass CM
CA CA Date
Waste Material Onsite? CM
CA CA Date
Unused or unneeded equipment onsite? Pass CM
CA CA Date
Pit, cellars, rat holes and other bores closed? CM
CA CA Date
Guy line anchors removed? CM
CA CA Date
Guy line anchors marked? CM
CA CA Date

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped?

1003d. Drilling pit closed? Pass Subsidence over on drill pit?

Cuttings management:

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing?

Production areas have been stabilized? Pass Segregated soils have been replaced?

RESTORATION AND REVEGETATION

Cropland

Top soil replaced Recontoured Perennial forage re-established

Non-Cropland

Top soil replaced Recontoured 80% Revegetation

1003 f. Weeds Noxious weeds?

Comment:

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: Date Final Reclamation Completed:

Final Land Use: RANGELAND

Reminder:

Comment:

Inspector Name: BURGER, CRAIG

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____
Debris removed _____ No disturbance /Location never built _____
Access Roads Regraded _____ Contoured _____ Culverts removed _____
Gravel removed _____
Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____
Compaction alleviation _____ Dust and erosion control _____
Non cropland: Revegetated 80% _____ Cropland: perennial forage _____
Weeds present _____ Subsidence _____

Comment:

Corrective Action:

Date

Overall Final Reclamation

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Berms		Compaction	Pass	MHSP	Pass	

S/U/V: Satisfactory _____ Corrective Date: _____

Comment:

CA:

Pits: ☐ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	422639	2213256	
	422639	2213256	