


FORM INSP <small>Rev 05/11</small>	State of Colorado				DE	ET	OE	ES
	Oil and Gas Conservation Commission				Inspection Date: <u>02/04/2014</u>			
<small>1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109</small>								
FIELD INSPECTION FORM								
Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection				
	222660	312862	Waldron, Emily	<input type="checkbox"/>	2A Doc Num: _____			
					Unsatisfactory			

Operator Information:

OGCC Operator Number: _____

Name of Operator: THREE FORKS RESOURCES LLC

Address: 1515 WAZEE STREET - SUITE #350

City: DENVER State: CO Zip: 80202

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
trugillo, irene	(303) 318-0717	irene@3forksres.com	
KELLERBY, SHAUN		shaun.kellerby@state.co.us	

Compliance Summary:

QtrQtr: NENW Sec: 21 Twp: 11N Range: 97W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
03/20/2012	662300346	PR	SI	Unsatisfactory			No
10/27/2010	200285128	PR	PR	Unsatisfactory			Yes

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
100415	PIT		09/23/1999		-	KLAENHAMMER 2	<input type="checkbox"/>
222660	WELL	PR	09/29/1967	GW	081-06020	KLAENHAMMER 2	PR <input checked="" type="checkbox"/>

Equipment: Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Signs/Marker:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
BATTERY	Satisfactory	At entrance to location.		

Inspector Name: Waldron, Emily

TANK LABELS/PLACARDS	Satisfactory		
WELLHEAD	Satisfactory		

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: **On tank label. 307-380-7616**

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WEEDS	Unsatisfactory	Weeds on location.	Implement a weed control program.	03/31/2014

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

Multiple Spills and Releases?

Equipment:

Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Deadman # & Marked	4	Satisfactory			
Bird Protectors		Satisfactory			
Pump Jack	1	Unsatisfactory	Door to pump jack is open. Wildlife can enter.	Close door and fix latch to prevent wildlife from entering.	02/21/2014
Gas Meter Run	1	Satisfactory			
Horizontal Heated Separator	1	Satisfactory	Bermed.		

Facilities:

New Tank

Tank ID: _____

Contents	#	Capacity	Type	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST	40.904560,-108.298310

S/U/V: Satisfactory

Comment: _____

Corrective Action: _____

Corrective Date: _____

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient		Adequate

Corrective Action _____

Corrective Date _____

Comment _____

Venting:

Yes/No _____ Comment _____

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 222660

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/U/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/U/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/U/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 222660 Type: WELL API Number: 081-06020 Status: PR Insp. Status: PR

Producing Well

Comment: _____

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Inspector Name: Waldron, Emily

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well: _____ Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters: _____

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

- 1003a. Debris removed? Pass CM _____
CA _____ CA Date _____
- Waste Material Onsite? Pass CM _____
CA _____ CA Date _____
- Unused or unneeded equipment onsite? Pass CM _____
CA _____ CA Date _____
- Pit, cellars, rat holes and other bores closed? Pass CM _____
CA _____ CA Date _____
- Guy line anchors removed? _____ CM _____
CA _____ CA Date _____
- Guy line anchors marked? Pass CM _____
CA _____ CA Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? Pass
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
Production areas have been stabilized? Pass Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Inspector Name: Waldron, Emily

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____ F _____

Comment: _____

Overall Interim Reclamation _____ Fail _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: Satisfactory _____ Corrective Date: _____

Comment: **No stormwater BMPs evident. No apparent soil migration; erosion or soil movement.**

CA: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673400240	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3274554