

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

02/12/2014

Document Number:

668602120

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	
	<u>206231</u>	<u>321208</u>	<u>QUINT, CRAIG</u>	2A Doc Num: _____	

Operator Information:

OGCC Operator Number:

Name of Operator: RENEGADE OIL & GAS COMPANY LLCAddress: 6155 S MAIN STREET #210City: AURORA State: CO Zip: 80016

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Ingve, Edward	303-680-4725 off	renegadeog@aol.com	

Compliance Summary:QtrQtr: SWSW Sec: 21 Twp: 21S Range: 51W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
08/03/2012	663901452	PR	SI	Violation			Yes
06/26/2012	664000663	PR	SI	Violation	P		Yes
12/28/2010	200290375	PR	SI	Unsatisfactory			Yes
11/24/2010	200285304	PR	SI	Unsatisfactory			Yes
08/05/2010	200266712	PR	SI	Unsatisfactory			Yes
09/24/2007	200119469	PR	PR	Satisfactory			No
11/16/2006	200099411	PR	PR	Unsatisfactory		Fail	Yes
04/27/2001	200019688	PR	SI	Satisfactory	I	Pass	No
07/07/1998	500136743	PR	PR			Fail	Yes
10/03/1996	500136742	ID	SI			Fail	Yes
08/31/1995	500136747	PR	SI			Fail	Yes

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
206231	WELL	PR	12/11/2006	GW	011-05055	CORDES-OBERLANDER 1	SI	<input checked="" type="checkbox"/>

Equipment:**Location Inventory**

Inspector Name: QUINT, CRAIG

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access	Satisfactory	DIRT ROAD THROUGH PASTURE.		

Signs/Marker:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory	LEASE SIGN BY UNIT.		
TANK LABELS/PLACARDS	Unsatisfactory	NO LABELING ON WATER TANK.	Install sign to comply with rule 210.	05/12/2014

Emergency Contact Number: (S/U/V) _____ Satisfactory _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
STORAGE OF SUPL	Satisfactory	WELL BY STORAGE YARD.		

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Venting:

Yes/No	Comment
NO	

Flaring:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 206231

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/U/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/U/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/U/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:**Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Facility**

Facility ID: 206231 Type: WELL API Number: 011-05055 Status: PR Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

S/V: Satisfactory CA Date: _____

CA: _____

Comment: SHUT IN, A PASSING M.I.T. WAS PERFORMED ON 12/10/2012.

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Inspector Name: QUINT, CRAIG

Comment:

Corrective Action:

Date:

Reportable:

GPS: Lat

Long

Proximity to Surface Water:

Depth to Ground Water:

Water Well:

Lat

Long

DWR Receipt Num:

Owner Name:

GPS :

Field Parameters:

Sample Location:

Emission Control Burner (ECB):

Comment:

Pilot:

Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started:

Date Interim Reclamation Completed:

Land Use:

Comment:

1003a.

Debris removed?

CM

CA

CA Date

Waste Material Onsite?

CM

CA

CA Date

Unused or unneeded equipment onsite?

CM

CA

CA Date

Pit, cellars, rat holes and other bores closed?

CM

CA

CA Date

Guy line anchors removed?

CM

CA

CA Date

Guy line anchors marked?

CM

CA

CA Date

1003b.

Area no longer in use?

Production areas stabilized ?

1003c.

Compacted areas have been cross ripped?

1003d.

Drilling pit closed?

Subsidence over on drill pit?

Cuttings management:

1003e.

Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing?

Production areas have been stabilized?

Segregated soils have been replaced?

RESTORATION AND REVEGETATION

Cropland

Top soil replaced

Recontoured

Perennial forage re-established

Inspector Name: QUINT, CRAIG

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Compaction	Pass			

S/U/V: Satisfactory _____ Corrective Date: _____

Comment: WELL IS LOCATED IN A STORAGE YARD.

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT