

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

02/18/2014

Document Number:

670201263

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	
	<u>276319</u>	<u>335441</u>	<u>BURGER, CRAIG</u>	2A Doc Num:	

Operator Information:

OGCC Operator Number:

Name of Operator: BARRETT CORPORATION* BILLAddress: 1099 18TH ST STE 2300City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED
☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		Shaun.Kellerby@state.co.us	NW Field Supervisor
Hirtler, Christina		CHirtler@billbarrettcorp.com	Regulatory Analyst

Compliance Summary:QtrQtr: NWSE Sec: 23 Twp: 6S Range: 92W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
05/02/2010	200258624	SR	PR	Satisfactory			No
05/27/2008	200190740	PR	PR	Satisfactory	I		No
03/12/2008	200127938	CO	PR	Satisfactory	I		No
09/24/2007	200123463	CO	PR	Satisfactory	I		No
08/13/2007	200117251	CO	PR	Satisfactory	I		No
04/18/2007	200109854	PR	PR	Satisfactory	I	Pass	No
04/10/2007	200114090	PR	PR	Satisfactory	I	Pass	No
08/30/2006	200102192	PR	PR	Satisfactory		Pass	No
05/31/2006	200096972	CO	PR	Satisfactory	I	Pass	No
04/10/2006	200091118	CO	PR	Satisfactory		Pass	No
03/08/2006	200087461	PR	PR	Satisfactory	I	Pass	No
02/13/2006	200088799	PR	PR	Satisfactory	I	Pass	No
12/28/2005	200086831	CO	WO	Satisfactory		Pass	No
10/27/2005	200085065	CO	WO	Satisfactory		Pass	No
10/18/2005	200084489	PR	WO	Satisfactory		Pass	No

Inspector Comment:

Follow up of unsatisfactory inspection due to guage hatches on tanks left open. Hatches shut at time of inspection.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
275527	WELL	PR	10/28/2005	GW	045-10340	WILSON 43C-23-692	PR	<input checked="" type="checkbox"/>

Inspector Name: BURGER, CRAIG

276317	WELL	PR	07/16/2009	GW	045-10440	WILSON 33D-23-692	PR	<input checked="" type="checkbox"/>
276318	WELL	PR	10/03/2005	GW	045-10441	WILSON 43A-23-692	PR	<input checked="" type="checkbox"/>
276319	WELL	PR	10/03/2005	GW	045-10442	WILSON 33B-23-692	PR	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Signs/Marker:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
BATTERY	Satisfactory			
WELLHEAD	Satisfactory			
TANK LABELS/PLACARDS	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?**Fencing/:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
TANK BATTERY	Satisfactory	cattle panel		
IGNITOR/COMBUST OR	Satisfactory	wire fence		
SEPARATOR	Satisfactory	cattle panel		
WELLHEAD	Satisfactory	cattle panel		

Equipment:

Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Gas Meter Run	1	Satisfactory			
Bird Protectors	6	Satisfactory			
Horizontal Heated Separator	4	Satisfactory			
Plunger Lift	4	Satisfactory			
Gathering Line	1	Satisfactory			
Emission Control Device	1	Satisfactory			

Facilities:		<input type="checkbox"/> New Tank		Tank ID: _____	
Contents	#	Capacity	Type	SE GPS	
CONDENSATE	4	200 BBLS	HEATED STEEL AST	39.512280,-107.630220	
S/U/V:	Satisfactory		Comment:		
Corrective Action:				Corrective Date:	
Paint					
Condition	Adequate				
Other (Content) _____					
Other (Capacity) _____					
Other (Type) _____					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Corrective Action				Corrective Date	
Comment					
Venting:					
Yes/No		Comment			
YES		Bradenhead valves open			
Flaring:					
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date	
Ignitor/Combustor	Satisfactory				

Predrill

Location ID: 276319

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/U/V: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**S/U/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/U/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 275527 Type: WELL API Number: 045-10340 Status: PR Insp. Status: PR

Producing WellComment: **plunger lift**

Facility ID: 276317 Type: WELL API Number: 045-10440 Status: PR Insp. Status: PR

Producing WellComment: **plunger lift**

Facility ID: 276318 Type: WELL API Number: 045-10441 Status: PR Insp. Status: PR

Producing WellComment: **plunger lift**

Facility ID: 276319 Type: WELL API Number: 045-10442 Status: PR Insp. Status: PR

Producing Well

Comment: **plunger lift**

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
 Comment: _____
 Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____
 DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): Y _____

Comment: _____

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: **Snow cover limited inspection.**

1003a. Debris removed? Pass CM _____
 CA _____ CA Date _____
 Waste Material Onsite? _____ CM _____
 CA _____ CA Date _____
 Unused or unneeded equipment onsite? Pass CM _____
 CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors marked? _____ CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? Pass

Production areas stabilized ? Pass

Inspector Name: BURGER, CRAIG

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? Pass Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? Pass Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Culverts	Pass			
		Compaction	Pass			

S/U/V: Satisfactory Corrective Date: _____

Comment: Snow cover limited inspection.

CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT