

**FORM  
INSP**Rev  
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

02/25/2014

Document Number:

673800466

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection
	<u>248047</u>	<u>328321</u>	<u>Gomez, Jason</u>	<input type="checkbox"/> 2A Doc Num: _____

**Operator Information:**

OGCC Operator Number:

Name of Operator: KERR-MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
Fogel, Heather		HFogel@nobleenergyinc.com	

**Compliance Summary:**QtrQtr: SESE Sec: 36 Twp: 5N Range: 67W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
02/12/2007	200104116	PR	PR	Satisfactory		Pass	No
02/15/2000	200004420	PR	PR	Satisfactory		Pass	No
05/16/1997	500172767						
01/26/1996	500172766	PR	PR			Pass	No

**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
248047	WELL	PR	07/12/1992	GW	123-15845	STATE N 36-16	SI	<input checked="" type="checkbox"/>

**Equipment:****Location Inventory**

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**

Signs/Marker:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory			

Inspector Name: Gomez, Jason

Emergency Contact Number: (S/U/V) Satisfactory

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

**Good Housekeeping:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
UNUSED EQUIPMENT	Unsatisfactory	Unused piping on location	Remove unused Piping	03/25/2014

**Spills:**

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

**Fencing/:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory	Panel		

**Equipment:**

Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Plunger Lift	1	Satisfactory			

**Venting:**

Yes/No	Comment
NO	

**Flaring:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Inspector Name: Gomez, Jason

**Predrill**

Location ID: 248047

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/U/V:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

**S/U/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**S/U/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Stormwater:**

**Comment:** \_\_\_\_\_

**Staking:**

**On Site Inspection (305):**

**Surface Owner Contact Information:**

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

**Operator Rep. Contact Information:**

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

**LGD Contact Information:**

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

**Summary of Landowner Issues:**

**Summary of Operator Response to Landowner Issues:**

**Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**

**Facility**

Facility ID: 248047 Type: WELL API Number: 123-15845 Status: PR Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: EQUIPMENT ONSITE

S/V: Satisfactory CA Date: \_\_\_\_\_

CA: SI

Comment: \_\_\_\_\_

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Inspector Name: Gomez, Jason

Comment: <input style="width:700px" type="text"/>			
Corrective Action: _____		Date: _____	
Reportable: _____	GPS: Lat _____	Long _____	
Proximity to Surface Water: _____		Depth to Ground Water: _____	
<b>Water Well:</b>			
DWR Receipt Num: _____		Owner Name: _____	GPS : _____
<b>Field Parameters:</b>			
<input style="width:300px" type="text"/>			
Sample Location: <input style="width:400px" type="text"/>			
Emission Control Burner (ECB): _____			
Comment: _____			
Pilot: _____	Wildlife Protection Devices (fired vessels): _____		

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: _____	Date Interim Reclamation Completed: _____
Land Use: _____	
Comment: <input style="width:750px" type="text"/>	
1003a.	Debris removed? _____ CM _____
	CA _____ CA Date _____
	Waste Material Onsite? _____ CM _____
	CA _____ CA Date _____
	Unused or unneeded equipment onsite? _____ CM _____
	CA _____ CA Date _____
	Pit, cellars, rat holes and other bores closed? _____ CM _____
	CA _____ CA Date _____
	Guy line anchors removed? <u>Pass</u> CM _____
	CA _____ CA Date _____
	Guy line anchors marked? _____ CM _____
	CA _____ CA Date _____
1003b.	Area no longer in use? _____ Production areas stabilized ? _____
1003c.	Compacted areas have been cross ripped? _____
1003d.	Drilling pit closed? _____ Subsidence over on drill pit? _____
	Cuttings management: _____
1003e.	Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? <u>Pass</u>
	Production areas have been stabilized? <u>Pass</u> Segregated soils have been replaced? <u>Pass</u>

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

<u>Non-Cropland</u>		
Top soil replaced	<u>Pass</u>	Recontoured <u>Pass</u>
		80% Revegetation <u>Pass</u>
1003 f. Weeds Noxious weeds?	<u>P</u>	
Comment:	<div></div>	
Overall Interim Reclamation	<u>Pass</u>	

Date Final Reclamation Started: _____	Date Final Reclamation Completed: _____
Final Land Use: _____	
Reminder: _____	
Comment: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>	
Well plugged _____	Pit mouse/rat holes, cellars backfilled _____
Debris removed _____	No disturbance /Location never built _____
Access Roads _____	Regraded _____
	Contoured _____
	Culverts removed _____
Gravel removed _____	
Location and associated production facilities reclaimed _____	
Locations, facilities, roads, recontoured _____	
Compaction alleviation _____	Dust and erosion control _____
Non cropland: Revegetated 80% _____	Cropland: perennial forage _____
Weeds present _____	Subsidence _____
Comment: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>	
Corrective Action: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>	Date _____
Overall Final Reclamation _____	Well Release on Active Location <input type="checkbox"/> Multi-Well Location <input type="checkbox"/>

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: Satisfactory                      Corrective Date: \_\_\_\_\_

Comment:

CA:

[illegible]