

13:50 on-site - NW 15 - looked  
w/ what appear to be hair  
hairs in well. ~ 10" stick up  
w/ bentonite seal @ 5ft -  
black plastic liner near well.

seeps = no sheen, algae, clear  
bottom shows algae, bacterial  
growth.

No visible signs of hydrocarbon  
no odors of hydrocarbon

13:55 off site