

Inspector Name: Sherman, Susan

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

03/10/2014

Document Number:

673701518

Overall Inspection:

Unsatisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection
	<u>427981</u>	<u>427985</u>	<u>Sherman, Susan</u>	<input type="checkbox"/> 2A Doc Num: _____

Operator Information:

OGCC Operator Number:

Name of Operator: WIEPKING-FULLERTON ENERGY LLCAddress: 4600 S DOWNING STCity: ENGLEWOOD State: CO Zip: 80113

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Halde, Kerry	(719) 340-0329	haldesand@centurytel.net	
Shalberg, Greg	(719) 688-3547	gregshalberg@aol.com	
Fincham, Jack	(303) 906-3335	fincham4@msn.com	
Herian, Tim	(316) 655-9200	tth308@hotmail.com	
Housey, Melissa		melissa.housey@state.co.us	COGCC OGLA

Compliance Summary:QtrQtr: NWSW Sec: 17 Twp: 10S Range: 55W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
09/16/2013	668601410	PR	PR	Satisfactory	P		No
10/16/2012	663901858	DG	PR	Satisfactory	I		No
08/06/2012	663901461	DG	SI	Satisfactory	I		No
07/06/2012	663901302	DG	DG	Satisfactory			No

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
427981	WELL	PR	07/27/2012	LO	073-06467	Napali # 6	PR	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: <u>1</u>	Wells: <u>1</u>	Production Pits: _____
Condensate Tanks: _____	Water Tanks: <u>1</u>	Separators: <u>1</u>	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: <u>1</u>
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: <u>1</u>	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Signs/Marker:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
CONTAINERS	Satisfactory			
WELLHEAD	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory

Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WEEDS	Unsatisfactory	At wellhead.	Maintain weeds.	03/24/2014

Spills:

Type	Area	Volume	Corrective action	CA Date
Crude Oil	WELLHEAD	<= 5 bbls	Remove and remediate stained soil.	03/24/2014

☐ Multiple Spills and Releases?**Fencing/:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
PUMP JACK	Satisfactory	steel panels		
LOCATION	Satisfactory	barbed wire		
WELLHEAD	Satisfactory	steel panels		

Equipment:

Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Pump Jack	1	Satisfactory			
Prime Mover	1	Satisfactory	Permit No. 13LI1059AIRS ID 073-0092-002Diesel		
Ancillary equipment	2	Satisfactory	gas scrubber, solar telemetry		

Inspector Name: Sherman, Susan

Facilities: <input type="checkbox"/> New Tank Tank ID: _____				
Contents	#	Capacity	Type	SE GPS
			CENTRALIZED BATTERY	39.173610,-103.577580
S/U/V:			Comment:	
Corrective Action:				Corrective Date:
Paint				
Condition				
Other (Content)				
Other (Capacity)				
Other (Type)				
Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Corrective Action				Corrective Date
Comment				
Venting:				
Yes/No	Comment			
Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Predrill				
Location ID: 427981				
Site Preparation:				
Lease Road Adeq.: _____		Pads: _____	Soil Stockpile: _____	
S/U/V: _____				
Corrective Action: _____		Date: _____	CDP Num.: _____	
Form 2A COAs:				
S/U/V: _____		Comment: _____		
CA: _____		Date: _____		
Wildlife BMPs:				

BMP Type	Comment
Storm Water/Erosion Control	<p>BMP Plan</p> <p>Wiepking-Fullerton Energy, L.L.C. 4600 S. Downing St. Englewood, CO 80113 303-789-1798 303-761-9067 (fax)</p> <p>Certification to Discharge Under CDPS General Permit COR-03000 Stormwater Discharges Associated with Construction</p> <p>Certification Number COR 39788</p> <p>Napali # 6 well T10S, R55W Sec. 17: NW1/4SW1/4 Lincoln County, Colorado</p> <p>Description of Well Site and Construction Area 1-3 acre site with access road for drilling of oil and gas well. Terrain is flat with native grass and sagebrush. No receiving waters will be affected by well pad. Surface Roughening will be used on low side of drill site to reduce speed of runoff, increase infiltration, reduce erosion, trap sediment and prepare soil for reseeding. Drilling pits closed and reclaimed within 3 months weather permitting. Topsoil will be separated and spread on drill site as final operation before reseeding operations which will be completed within 6 months weather permitting. To prevent soil erosion site will be disked and straw crimped in or manure spread.</p> <p>Stormwater Management Plan (SWMP) is on file in Wiepking-Fullerton Energy, L.L.C. office.</p> <p>Spill Prevention, Control and Countermeasure Plan is on file in Wiepking-Fullerton Energy, L.L.C. office.</p>

S/U/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Inspector Name: Sherman, Susan

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 427981 Type: WELL API Number: 073-06467 Status: PR Insp. Status: PR

Producing Well

Comment: PR
November 2013 last reported. Send updated production data to COGCC.

Environmental

Spills/Releases:

Type of Spill: Description: Estimated Spill Volume:
Comment:
Corrective Action: Date:
Reportable: GPS: Lat Long
Proximity to Surface Water: Depth to Ground Water:

Water Well:

Lat Long
DWR Receipt Num: Owner Name: GPS :

Field Parameters:

Sample Location:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use: RANGELAND

Comment:

1003a. Debris removed? Pass CM CA Date
Waste Material Onsite? Pass CM CA Date
Unused or unneeded equipment onsite? Pass CM CA Date
Pit, cellars, rat holes and other bores closed? CM CA Date
Guy line anchors removed? Pass CM CA Date

Inspector Name: Sherman, Susan

Guy line anchors marked? ☐ CM ☐
CA ☐ CA Date ☐

1003b. Area no longer in use? ☐ Pass ☐ Production areas stabilized ? ☐ Pass ☐

1003c. Compacted areas have been cross ripped? ☐

1003d. Drilling pit closed? ☐ Subsidence over on drill pit? ☐

Cuttings management: ☐

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? ☐ Fail ☐

Production areas have been stabilized? ☐ Pass ☐ Segregated soils have been replaced? ☐ Pass ☐

RESTORATION AND REVEGETATION

Cropland

Top soil replaced ☐ Recontoured ☐ Perennial forage re-established ☐

Non-Cropland

Top soil replaced ☐ Pass ☐ Recontoured ☐ 80% Revegetation ☐ Fail ☐

1003 f. Weeds Noxious weeds? ☐

Comment:

Overall Interim Reclamation ☐ Fail ☐

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: Date Final Reclamation Completed:

Final Land Use: RANGELAND

Reminder:

Comment:

Well plugged ☐ Pit mouse/rat holes, cellars backfilled ☐

Debris removed ☐ No disturbance /Location never built ☐

Access Roads ☐ Regraded ☐ Contoured ☐ Culverts removed ☐

Gravel removed ☐

Location and associated production facilities reclaimed ☐ Locations, facilities, roads, recontoured ☐

Compaction alleviation ☐ Dust and erosion control ☐

Non cropland: Revegetated 80% ☐ Cropland: perennial forage ☐

Weeds present ☐ Subsidence ☐

Comment:

Corrective Action: Date

Overall Final Reclamation ☐ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	MHSP	Pass	

S/U/V: Satisfactory ☐ Corrective Date:

Comment:

CA:

Pits:	<input type="checkbox"/> NO SURFACE INDICATION OF PIT
--------------	---

COGCC Comments

Comment	User	Date
Send Form 4 to COGCC OGLA to update battery information regarding Napali 6 and 2 by 3/28/14.	ShermaSe	03/17/2014

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673701574	WF Napali 6 well	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3301069
673701575	WF Napali 6 well	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3301070
673701576	WF Napali 6 well	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3301071
673701580	WF Napali 6 well	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3301072
673701682	WF Napali 6 wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3301073