

FORM INSP
Rev 05/11

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
03/24/2014

Document Number:
673500835

Overall Inspection:
Unsatisfactory

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>230264</u>	<u>315104</u>	<u>Covington, Dave</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number: _____
 Name of Operator: WINDSOR ENERGY GROUP LLC
 Address: 14301 CALIBER DR - SUITE 300
 City: OKLAHOMA CITY State: OK Zip: 73134

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Williamson, Craig	970-878-3800	cwilliamson@blm.gov	Petroleum Engineer
Kellerby, Shaun		shaun.kellerby@state.co.us	
Welter, Earl		ewelter@windsorenergy.com	

Compliance Summary:

QtrQtr: SWSE Sec: 19 Twp: 3S Range: 100W

Inspector Comment:

Wellhead, separator, meterhouse and pit on location.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
107222	PIT		09/23/1999		-	UNIVERSAL 2-19	<input type="checkbox"/>
107227	PIT		09/23/1999		-	UNIVERSAL 2-19	<input type="checkbox"/>
230264	WELL	PR	11/08/2000		103-07923	UNIVERSAL 2-19	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access	Satisfactory			
Main	Unsatisfactory	Rutting and channeling.	Repair and maintain road	04/25/2014

Signs/Marker:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Unsatisfactory	A wellhead sign needs to be at the wellhead.	Install sign to comply with rule 210.	04/30/2014

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WEEDS				

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
PIT	Satisfactory			

Equipment:					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Ancillary equipment	1	Satisfactory			
Gas Meter Run	1	Satisfactory			
Deadman # & Marked	4	Unsatisfactory	Deadmen are not marked	Comply with 603.G. Mark deadmen	04/30/2014
Horizontal Heated Separator	1	Satisfactory			

Venting:		Comment
Yes/No		
NO		

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 230264

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/U/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/U/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/U/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 230264 Type: WELL API Number: 103-07923 Status: PR Insp. Status: PR

Producing Well

Comment: Wellhead, separator, meterhouse and pit on location.

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Pass CM _____

CA _____ CA Date _____

Waste Material Onsite? Pass CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						

S/U/V: Unsatisfactory Corrective Date: 04/30/2014

Comment: Stormwater is not being controlled.

CA: Install stormwater BMP's

Pits: NO SURFACE INDICATION OF PIT

Pit Type: Produced Water Lined: NO Pit ID: _____ Lat: 39.767460 Long: -108.658680

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____

Fencing:

Fencing Type: Livestock Fencing Condition: Adequate

Comment: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: _____

Anchor Trench Present: _____ Oil Accumulation: NO 2+ feet Freeboard: _____

Pit (S/U/V): Unsatisfactory Comment: there is no Freeboard. The pit has been filled in by stormwater.

Corrective Action: Install 2' off freeboard and put in stormwater BMP's. Date: 04/30/2014

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673500842	Deadman, no marker	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3307567
673500843	Pit, no freeboard	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3307568
673500844	Wellhead, no sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3307569
673500845	Road rutting.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3307570