

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

04/03/2014

Document Number:

668602456

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	418136	418140	QUINT, CRAIG	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:

Name of Operator: MULL DRILLING COMPANY INCAddress: 1700 N WATERFRONT PKWY B#1200City: WICHITA State: KS Zip: 67206-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Smalley, Carl	719-767-8805 off	csmalley@mulldrilling.com	719-342-1812 cell

Compliance Summary:QtrQtr: NWSW Sec: 34 Twp: 13S Range: 44W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
02/25/2013	668600419	PR	PR	Satisfactory			No
02/21/2012	663900624	PR	PR	Satisfactory	P		No
05/25/2011	200311201	PR	PR	Satisfactory			No
11/08/2010	200283233	DG	DG	Satisfactory			No

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
418136	WELL	PR	03/01/2011	OW	017-07695	PELTON "B" 3	PR	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: <u>1</u>	Wells: <u>1</u>	Production Pits: _____
Condensate Tanks: _____	Water Tanks: <u>1</u>	Separators: <u>1</u>	Electric Motors: <u>1</u>
Gas or Diesel Motors: <u>1</u>	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: <u>1</u>
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: <u>2</u>	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: <u>1</u>

Location

Inspector Name: QUINT, CRAIG

Lease Road:				
Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access	Satisfactory	GRAVEL ROAD THROUGH FARM GROUND.		

Signs/Marker:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory	LEASE SIGN BY UNIT		
CONTAINERS	Satisfactory	STICKERS		

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Facilities: <input type="checkbox"/> New Tank Tank ID: _____				
Contents	#	Capacity	Type	SE GPS
			CENTRALIZED BATTERY	38.872000,-102.332950
S/U/V:	Satisfactory	Comment:	CENTRAL BATTERY F/(PELTON B-1, B-3) 1250` SSW	
Corrective Action:			Corrective Date:	

Paint

Condition	
-----------	--

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Corrective Action		Corrective Date	
Comment			

Venting:	
Yes/No	Comment
YES	CASING VENT ON WELLHEAD.

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill				
Location ID: 418136				
Site Preparation:				
Lease Road Adeq.:		Pads:	Soil Stockpile:	

S/U/V: _____

Corrective Action: _____

Date: _____

CDP Num.: _____

Form 2A COAs:**S/U/V:** _____ **Comment:** _____**CA:** _____**Date:** _____**Wildlife BMPs:**

BMP Type	Comment
PROPOSED BMPs	<p>BEST MANAGEMENT PRACTICES</p> <p>Pelton "B" #3</p> <p>NWSW of Section 34, T13S-R44W</p> <p>1810' FSL & 600' FWL</p> <p>Cheyenne County, Colorado</p> <p>1. Mull Drilling Company Inc. will only use such land as necessary for said drilling, completion and production operations. The access road and well pad size will be kept to the minimum that is needed, without compromising safety.</p> <p>2. Mull Drilling Company Inc. will make every reasonable effort to minimize the impact of all equipment associated with this well. MDC will ensure garbage /mud sacks, etc. is stored in a caged container during drilling operations to prevent any materials from being blown offsite.</p> <p>3. Mull Drilling Company Inc. will minimize adverse visual contrast by utilizing an appropriate color selection for completion equipment to blend in with the background and natural surroundings.</p> <p>4. Mull Drilling Company Inc. will locate tank batteries at a safe location away from the highway and well head operations. Containment berms will be constructed around water and oil tanks.</p> <p>5. The well is located in a relatively flat area and there are no streams or lakes within 1,000 feet of the location. During drilling operations there will be 24 hour /day supervision that will notice and contain any spills. During production a pumper will inspect the location daily and perform routine maintenance to prevent spills.</p> <p>6. Should excessive erosion on the location or along the access road occur, drainage patterns will be adjusted to minimize the disturbance.</p> <p>7. Company representatives will have phone numbers of local fire departments, emergency response teams, and heavy equipment operators to alert in an emergency. The COGCC will be notified in the case of a reportable spill.</p>

8. The well will be located on a dead end road in a field on private property. Only the equipment and man power required to drill and operate the well will be on location to completion. Only a minimum amount of traffic is anticipated.

9. At the end of drilling operations, Mull Drilling Company Inc. will restore the surface on unused lands as close to the original contour as possible. MDC will segregate the topsoil during the initial grading of the well site and spread it back at the surface at the conclusion of operations. We will reestablish native vegetation on the ingress /regress access area, in the

case of a dry hole. The actual drill site is on cropland, which will be re- plowed for new crops the following season, in the case of a dry hole.

1700 N. WATERFRONT PARKWAY BUILDING 1200 • WICHITA, KS 67206 - 6637.316 264
-6366 • FAX 316 264 -6440

S/U/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 418136 Type: WELL API Number: 017-07695 Status: PR Insp. Status: PR

Producing Well

Comment: PRODUCING, CENTRAL BATTERY F/(PELTON B-1, B-3) 1250' SSW @ 38.872000,-102.332950

Environmental

Spills/Releases:

Inspector Name: QUINT, CRAIG

Type of Spill: _____	Description: _____	Estimated Spill Volume: _____
Comment: _____		
Corrective Action: _____		Date: _____
Reportable: _____	GPS: Lat _____	Long _____
Proximity to Surface Water: _____		Depth to Ground Water: _____

Water Well:		Lat _____	Long _____
DWR Receipt Num: _____	Owner Name: _____	GPS : _____	_____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: DRY LAND

Comment: _____

1003a.	Debris removed?	Pass	CM	_____	CA Date _____
	CA			_____	_____
	Waste Material Onsite?	Pass	CM	_____	_____
	CA			_____	CA Date _____
	Unused or unneeded equipment onsite?	Pass	CM	_____	_____
	CA			_____	CA Date _____
	Pit, cellars, rat holes and other bores closed?	Pass	CM	_____	_____
	CA			_____	CA Date _____
	Guy line anchors removed?		CM	_____	_____
	CA			_____	CA Date _____
	Guy line anchors marked?		CM	_____	_____
	CA			_____	CA Date _____

1003b.	Area no longer in use? Pass	Production areas stabilized ? Pass
1003c.	Compacted areas have been cross ripped? _____	
1003d.	Drilling pit closed? Pass	Subsidence over on drill pit? Pass
	Cuttings management: _____	
1003e.	Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____	
	Production areas have been stabilized? Pass	Segregated soils have been replaced? Pass

RESTORATION AND REVEGETATION

Cropland

Inspector Name: QUINT, CRAIG

Top soil replaced Pass

Recontoured Pass

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? P

Comment: UNUSED AREAS OF THE LOCATION ARE FARMED.

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: DRY LAND

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass	MHSP	Pass	

S/U/V: Satisfactory Corrective Date: _____

Comment: _____

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT