

Inspector Name: Waldron, Emily

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



| | | | |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:

04/03/2014

Document Number:

673400361

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

| | | | | |
|---------------------|---------------|---------------|-----------------------|--|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection |
| | <u>259580</u> | <u>316253</u> | <u>Waldron, Emily</u> | <input type="checkbox"/> 2A Doc Num: _____ |

Operator Information:

OGCC Operator Number:

Name of Operator: KOCH EXPLORATION COMPANY, LLCAddress: 950 17TH STREET #1900City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|--------------|----------------------------|---------|
| KELLERBY, SHAUN | | shaun.kellerby@state.co.us | |
| Clark, John | 505-334-9111 | clark23@kochind.com | |

Compliance Summary:QtrQtr: SESW Sec: 25 Twp: 2N Range: 97W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Unsatisfactory | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|------------------------------|----------|----------------|-----------------|
| 03/15/2011 | 200305494 | PR | PR | Satisfactory | | | No |

Inspector Comment:**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|--|
| 259580 | WELL | PR | 10/09/2008 | GW | 103-10107 | WRD FEDERAL 25-42 | PR <input checked="" type="checkbox"/> |

Equipment:Location Inventory

| | | | |
|-----------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Motors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location**Signs/Marker:**

| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|----------------------|-----------------------------|---------------|-------------------|---------|
| BATTERY | Satisfactory | At meter run. | | |
| TANK LABELS/PLACARDS | Satisfactory | | | |
| WELLHEAD | Satisfactory | | | |

Inspector Name: Waldron, Emily

Emergency Contact Number: (S/U/V) Satisfactory

Corrective Date: _____

Comment: 877-352-4660

Corrective Action: _____

Spills:

| Type | Area | Volume | Corrective action | CA Date |
|------|------|--------|-------------------|---------|
|------|------|--------|-------------------|---------|

☐ Multiple Spills and Releases?

Equipment:

| Type | # | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|---------------------------|---|-----------------------------|---------|-------------------|---------|
| Horizontal Heater Treater | 1 | Satisfactory | | | |
| Gas Meter Run | 1 | Satisfactory | | | |
| Plunger Lift | 1 | Satisfactory | | | |
| Bird Protectors | | Satisfactory | | | |
| Deadman # & Marked | 4 | Satisfactory | | | |

Facilities:

☐ New Tank

Tank ID: _____

| Contents | # | Capacity | Type | SE GPS |
|----------------|---|----------|-----------|--------|
| PRODUCED WATER | 1 | 300 BBLS | STEEL AST | , |

S/U/V: Satisfactory Comment: _____

Corrective Action: _____

Corrective Date: _____

Paint

| | |
|-----------|----------|
| Condition | Adequate |
|-----------|----------|

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | | Adequate |

Corrective Action _____ Corrective Date _____

Comment _____

Inspector Name: Waldron, Emily

| | | | | | |
|------------------------|-----------------------------|-----------------------------------|---------------------|-----------------------|--|
| Facilities: | | <input type="checkbox"/> New Tank | | Tank ID: _____ | |
| Contents | # | Capacity | Type | SE GPS | |
| CRUDE OIL | 1 | 300 BBLS | STEEL AST | 40.107530,-108.229550 | |
| S/U/V: | Satisfactory | | Comment: | | |
| Corrective Action: | | | | Corrective Date: | |
| Paint | | | | | |
| Condition | Adequate | | | | |
| Other (Content) _____ | | | | | |
| Other (Capacity) _____ | | | | | |
| Other (Type) _____ | | | | | |
| Berms | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Metal | Adequate | Walls Sufficient | | Adequate | |
| Corrective Action | | | | Corrective Date | |
| Comment | | | | | |
| Venting: | | | | | |
| Yes/No | | Comment | | | |
| | | | | | |
| Flaring: | | | | | |
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date | |
| | | | | | |

Predrill

Location ID: 259580

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/U/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/U/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/U/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 259580 Type: WELL API Number: 103-10107 Status: PR Insp. Status: PR

Producing Well

Comment: _____

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Inspector Name: Waldron, Emily

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____
CA _____ CA Date _____
Waste Material Onsite? _____ CM _____
CA _____ CA Date _____
Unused or unneeded equipment onsite? _____ CM _____
CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? _____ CM _____
CA _____ CA Date _____
Guy line anchors removed? _____ CM _____
CA _____ CA Date _____
Guy line anchors marked? _____ CM _____
CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Inspector Name: Waldron, Emily

Comment:

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started:

Date Final Reclamation Completed:

Final Land Use:

Reminder:

Comment:

Well plugged

Pit mouse/rat holes, cellars backfilled

Debris removed

No disturbance /Location never built

Access Roads Regraded

Contoured

Culverts removed

Gravel removed

Location and associated production facilities reclaimed

Locations, facilities, roads, recontoured

Compaction alleviation

Dust and erosion control

Non cropland: Revegetated 80%

Cropland: perennial forage

Weeds present

Subsidence

Comment:

Corrective Action:

Date

Overall Final Reclamation

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Ditches | Pass | Culverts | Pass | | | |
| Berms | Pass | Compaction | Pass | | | |
| | | Gravel | Pass | | | |
| Gravel | Pass | Ditches | Pass | | | |

S/U/V: Satisfactory

Corrective Date:

Comment:

CA:

Pits: ☐ NO SURFACE INDICATION OF PIT