

**FORM  
INSP**Rev  
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

04/10/2014

Document Number:

663902946

Overall Inspection:

**Unsatisfactory****FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	335711	335711	LONGWORTH, MIKE	<input type="checkbox"/>	

**Operator Information:**

OGCC Operator Number:

Name of Operator: XTO ENERGY INC

Address: 382 CR 3100

City: AZTEC State: NM Zip: 87410

☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED☒ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED**Contact Information:**

Contact Name	Phone	Email	Comment
Dooling, Jessica		Jessica_Dooling@xtoenergy.com	
kardos, Kelly		kelly_kardos@xtoenergy.com	
Jaramillo, Diane		diane_jaramillo@xtoenergy.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Spencer, Stan		stan.spencer@state.co.us	

**Compliance Summary:**

QtrQtr: NWNE Sec: 11 Twp: 2S Range: 97W

**Inspector Comment:**

--

**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
278098	WELL	PR	06/08/2012	GW	103-10589	PICEANCE CREEK UNIT T62X-11G2	TA	<input checked="" type="checkbox"/>
278099	WELL	PR	06/06/2012	GW	103-10588	PICEANCE CREEK UNIT T62X-11G1	PR	<input checked="" type="checkbox"/>
278134	WELL	PA	02/15/2006	GW	103-10592	PICEANCE CREEK UNIT T62X-11G4	PA	<input checked="" type="checkbox"/>
278135	WELL	PR	06/06/2012	GW	103-10591	PICEANCE CREEK UNIT T62X-11G3	PR	<input checked="" type="checkbox"/>
278161	WELL	PA	10/19/2007	GW	103-10593	PICEANCE CREEK UNIT T62X 11G5	PA	<input checked="" type="checkbox"/>
278621	PIT	AC	06/30/2005		-	PCU 62X 11G5	AC	<input type="checkbox"/>
280505	WELL	AL	05/05/2011	LO	103-10639	PICEANCE CREEK UNIT T62X-11G7	AL	<input type="checkbox"/>
280506	WELL	AL	05/05/2011	LO	103-10640	PICEANCE CREEK UNIT T62X-11G6	AL	<input type="checkbox"/>
280507	WELL	AL	05/05/2011	LO	103-10641	PICEANCE CREEK UNIT T62X-11G8	AL	<input type="checkbox"/>

280508	WELL	AL	05/05/2011	LO	103-10642	PICEANCE CREEK UNIT T62X-11G9	AL	<input type="checkbox"/>
--------	------	----	------------	----	-----------	----------------------------------	----	--------------------------

**Equipment:**Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location****Lease Road:**

Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access	Satisfactory			

**Signs/Marker:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory			
BATTERY	Satisfactory			
TANK LABELS/PLACARDS	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

**Good Housekeeping:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
DEBRIS	Satisfactory	Black plastic balls around pits and on location.	Remove balls and other such debri	04/18/2014

**Spills:**

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

<b>Facilities:</b>		<input type="checkbox"/> New Tank		Tank ID: _____	
Contents	#	Capacity	Type	SE GPS	
PRODUCED WATER	1	400 BBLS	STEEL AST	39.897300,-108.245570	
S/U/V:	Satisfactory		Comment: _____		
Corrective Action:				Corrective Date: _____	
<b>Paint</b>					
Condition	Adequate				
Other (Content) _____					
Other (Capacity) _____					
Other (Type) _____					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Corrective Action				Corrective Date	
Comment					
<b>Venting:</b>					
Yes/No		Comment			
<b>Flaring:</b>					
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date	

**Predrill**

Location ID: 335711

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/U/V:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****S/U/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Wildlife BMPs:****S/U/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Stormwater:****Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 278098 Type: WELL API Number: 103-10589 Status: PR Insp. Status: TA

**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_

S/V: Satisfactory CA Date: \_\_\_\_\_

CA: \_\_\_\_\_

Comment: \_\_\_\_\_

Facility ID: 278099 Type: WELL API Number: 103-10588 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Inspector Name: LONGWORTH, MIKE

Facility ID: 278134 Type: WELL API Number: 103-10592 Status: PA Insp. Status: PA

Facility ID: 278135 Type: WELL API Number: 103-10591 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Facility ID: 278161 Type: WELL API Number: 103-10593 Status: PA Insp. Status: PA

**Environmental**

**Spills/Releases:**

Type of Spill: Description: Estimated Spill Volume:  
Comment:  
Corrective Action: Date:  
Reportable: GPS: Lat Long  
Proximity to Surface Water: Depth to Ground Water:

**Water Well:**

DWR Receipt Num: Owner Name: GPS : Lat Long

**Field Parameters:**

Sample Location:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use:

Comment: Several open pits and several soil stockpiles. Stock piles are not covered and inadequate berms. Stock were documented on Field Inspection 04/26/2012 doc#662300421

1003a. Debris removed? CM

CA CA Date

Waste Material Onsite? CM

CA CA Date

Unused or unneeded equipment onsite? CM

CA CA Date

Pit, cellars, rat holes and other bores closed? Fail CM Open rat hole on G1

CA Close rathole CA Date 05/10/2014

Guy line anchors removed? Fail CM

CA Mark or remove dead men CA Date 05/10/2014

Guy line anchors marked? Fail CM

CA **Mark or remove dead men**CA Date **05/10/2014**1003b. Area no longer in use? **Fail** Production areas stabilized ? **Pass**

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? **Fail**

Production areas have been stabilized? \_\_\_\_\_

Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_

Recontoured \_\_\_\_\_

Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_

Recontoured \_\_\_\_\_

80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation **Fail****Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_

Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_

Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_

No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_

Contoured \_\_\_\_\_

Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_

Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_

Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_

Well Release on Active Location ☐Multi-Well Location ☐**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: **Satisfactory** Corrective Date: \_\_\_\_\_Comment: **Uncovered stockpiles are a source of blowing dust.**CA: **Cover stock piles****Pits:** ☐ NO SURFACE INDICATION OF PIT

Inspector Name: LONGWORTH, MIKE

Pit Type: _____	Lined: _____	Pit ID: _____	Lat: _____	Long: _____
<b><u>Lining:</u></b>				
Liner Type: _____	Liner Condition: _____			
Comment: _____				
<b><u>Fencing:</u></b>				
Fencing Type: _____	Fencing Condition: _____			
Comment: _____				
<b><u>Netting:</u></b>				
Netting Type: _____	Netting Condition: _____			
Comment: _____				
Anchor Trench Present: _____	Oil Accumulation: <u>NO</u>	2+ feet Freeboard: _____		
Pit (S/U/V): <u>Unsatisfactory</u>	Comment: <u>Pit(s) are open and stock piles on location.</u>			
Corrective Action: <u>Submit action plan with time lines to complete pit closure.</u>				Date: <u>04/18/2014</u>

Permit:	Facility ID	Permit Num	Expiration Date
	278621	1417859	
	278621	1417859	

#### **Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
663902950	Location entrance	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3319193">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3319193</a>
663902951	Pits and stock piles	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3319194">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3319194</a>