

| | | | |
|---|--|--|---|
| FORM INSP Rev 05/11 | State of Colorado Oil and Gas Conservation Commission 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109 |  | DE ET OE ES |
| FIELD INSPECTION FORM | | | Inspection Date: <u>04/10/2014</u> Document Number: <u>663902948</u> Overall Inspection: <u>Satisfactory</u> |
| Location Identifier: _____ Facility ID: <u>336007</u> Loc ID: <u>336007</u> | Inspector Name: <u>LONGWORTH, MIKE</u> | On-Site Inspection <input type="checkbox"/> | 2A Doc Num: _____ |

Operator Information:

OGCC Operator Number: _____

Name of Operator: XTO ENERGY INC

Address: 382 CR 3100

City: AZTEC State: NM Zip: 87410

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|-------|-------------------------------|---------|
| Jaramillo, Diane | | diane_jaramillo@xtoenergy.com | |
| Dooling, Jessica | | Jessica_Dooling@xtoenergy.com | |
| kardos, Kelly | | kelly_kardos@xtoenergy.com | |

Compliance Summary:

QtrQtr: SWNE Sec: 33 Twp: 1S Range: 97W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Unsatisfactory | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|------------------------------|----------|----------------|-----------------|
| 11/16/2012 | 668100142 | | | Satisfactory | | | No |

Inspector Comment:

Related Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status | |
|-------------|------|--------|-------------|------------|-----------|------------------------|-------------|-------------------------------------|
| 299793 | WELL | SI | 04/10/2013 | GW | 103-11420 | FREEDOM UNIT 197-33B7 | SI | <input checked="" type="checkbox"/> |
| 299794 | WELL | SI | 04/10/2013 | GW | 103-11421 | FREEDOM UNIT 197-33B8 | SI | <input checked="" type="checkbox"/> |
| 299795 | WELL | SI | 04/10/2013 | GW | 103-11422 | FREEDOM UNIT 197-33B9 | SI | <input checked="" type="checkbox"/> |
| 299796 | WELL | SI | 04/10/2013 | GW | 103-11423 | FREEDOM UNIT 197-33B10 | SI | <input checked="" type="checkbox"/> |
| 299797 | WELL | SI | 04/10/2013 | GW | 103-11424 | FREEDOM UNIT 197-33B6 | SI | <input checked="" type="checkbox"/> |
| 299798 | WELL | SI | 04/10/2013 | GW | 103-11425 | FREEDOM UNIT 197-33B5 | SI | <input checked="" type="checkbox"/> |
| 299799 | WELL | SI | 04/10/2013 | GW | 103-11426 | FREEDOM UNIT 197-33B4 | SI | <input checked="" type="checkbox"/> |
| 299800 | WELL | SI | 04/10/2013 | GW | 103-11427 | FREEDOM UNIT 197-33B2 | SI | <input checked="" type="checkbox"/> |
| 299801 | WELL | SI | 04/10/2013 | GW | 103-11428 | FREEDOM UNIT 197-33B1 | SI | <input checked="" type="checkbox"/> |

| | | | | | | | | |
|--------|------|----|------------|----|-----------|-----------------------|----|-------------------------------------|
| 300296 | WELL | SI | 04/10/2013 | GW | 103-11433 | FREEDOM UNIT 197-33B3 | SI | <input checked="" type="checkbox"/> |
|--------|------|----|------------|----|-----------|-----------------------|----|-------------------------------------|

Equipment: Location Inventory

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

Lease Road:

| Type | Satisfactory/Unsatisfactory | comment | Corrective Action | Date |
|--------|-----------------------------|---------|-------------------|------|
| Access | Satisfactory | | | |

Signs/Marker:

| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|------------|-----------------------------|---------|-------------------|---------|
| BATTERY | Satisfactory | | | |
| CONTAINERS | Satisfactory | | | |
| WELLHEAD | Satisfactory | | | |

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

| Type | Area | Volume | Corrective action | CA Date |
|------|------|--------|-------------------|---------|
|------|------|--------|-------------------|---------|

Multiple Spills and Releases?

Equipment:

| Type | # | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|----------------------|---|-----------------------------|-----------------------------------|-------------------|---------|
| Flow Line | 9 | Satisfactory | | | |
| Horizontal Separator | 2 | Satisfactory | | | |
| Ancillary equipment | 2 | Satisfactory | Chemical tanks with pump stations | | |

Venting:

| Yes/No | Comment |
|--------|---------|
| | |

Flaring:

| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|------|-----------------------------|---------|-------------------|---------|
| | | | | |

Predrill

Location ID: 336007

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/U/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/U/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/U/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 299793 Type: WELL API Number: 103-11420 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

S/V: _____ CA Date: _____

CA: _____

Comment: _____

Facility ID: 299794 Type: WELL API Number: 103-11421 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____
S/V: _____ CA Date: _____
CA: _____
Comment: _____

Facility ID: 299795 Type: WELL API Number: 103-11422 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____
S/V: _____ CA Date: _____
CA: _____
Comment: _____

Facility ID: 299796 Type: WELL API Number: 103-11423 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____
S/V: _____ CA Date: _____
CA: _____
Comment: _____

Facility ID: 299797 Type: WELL API Number: 103-11424 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____
S/V: _____ CA Date: _____
CA: _____
Comment: _____

Facility ID: 299798 Type: WELL API Number: 103-11425 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____
S/V: _____ CA Date: _____
CA: _____
Comment: _____

Facility ID: 299799 Type: WELL API Number: 103-11426 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____
S/V: _____ CA Date: _____
CA: _____
Comment: _____

Facility ID: 299800 Type: WELL API Number: 103-11427 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____
S/V: _____ CA Date: _____
CA: _____
Comment: _____

Facility ID: 299801 Type: WELL API Number: 103-11428 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____
S/V: _____ CA Date: _____
CA: _____
Comment: _____

Facility ID: 300296 Type: WELL API Number: 103-11433 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____
S/V: _____ CA Date: _____
CA: _____
Comment: _____

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
Comment: _____
Corrective Action: _____ Date: _____
Reportable: _____ GPS: Lat _____ Long _____
Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____
Comment: _____
Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____
Land Use: _____
Comment: _____
1003a. Debris removed? _____ CM _____

CA _____ CA Date _____
 Waste Material Onsite? _____ CM _____
 CA _____ CA Date _____
 Unused or unneeded equipment onsite? _____ CM _____
 CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors marked? _____ CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____
 Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

| Storm Water: | | | | | | |
|---------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Check Dams | Pass | Gravel | Pass | | | |
| Ditches | Pass | | | | | |
| Blankets | | Culverts | Pass | | | |
| Gravel | Pass | | | | | |
| Seeding | Fail | | | | | |
| Compaction | Pass | Ditches | Pass | | | |
| Waddles | Pass | | | | | |
| Rip Rap | Pass | | | | | |
| Berms | Pass | Compaction | Pass | | | |

S/U/V: Satisfactory _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT