

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

04/14/2014

Document Number:

663902968

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	334745	334745	LONGWORTH, MIKE	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:

Name of Operator: WPX ENERGY ROCKY MOUNTAIN LLCAddress: 1001 17TH STREET - SUITE #1200City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Gardner, Michael	970/285-9377 ext. 2760	Michael.Gardner@WPXEnerg y.com	Principal Environmental Specialist
Moss, Brad	(970) 285-9377	Brad.Moss@WPXEnergy.com	Production foreman

Compliance Summary:QtrQtr: SWNE Sec: 26 Twp: 7S Range: 96W**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
294325	WELL	PR	01/11/2008	GW	045-15383	SPECIALTY RESTAURANTS SG 422 -26	PR	<input checked="" type="checkbox"/>
294327	WELL	PR	01/11/2008	GW	045-15384	SPECIALTY RESTAURANTS SG 322 -26	PR	<input checked="" type="checkbox"/>
294328	WELL	PR	11/20/2008	GW	045-15391	SPECIALTY RESTAURANTS SG 521 -26	PR	<input checked="" type="checkbox"/>
294330	WELL	PR	11/20/2008	GW	045-15392	SPECIALTY RESTAURANTS SG 421 -26	PR	<input checked="" type="checkbox"/>
294341	WELL	PR	01/11/2008	GW	045-15393	SPECIALTY RESTAURANTS SG 321 -26	PR	<input checked="" type="checkbox"/>
294343	WELL	PR	03/22/2009	GW	045-15394	SPECIALTY RESTAURANTS SG 431 -26	PR	<input checked="" type="checkbox"/>
294344	WELL	PR	03/10/2009	GW	045-15385	SPECIALTY RESTAURANTS SG 522 -26	PR	<input checked="" type="checkbox"/>

294347	WELL	PR	01/11/2008	GW	045-15386	SPECIALTY RESTAURANTS SG 531-26	PR	X
294349	WELL	PR	04/30/2009	GW	045-15395	SPECIALTY RESTAURANTS SG 21-26	PR	X
294352	WELL	PR	01/11/2008	GW	045-15396	SPECIALTY RESTAURANTS SG 331-26	PR	X
294353	WELL	PR	03/11/2009	GW	045-15387	SPECIALTY RESTAURANTS SG 532-26	PR	X
294355	WELL	PR	02/18/2009	GW	045-15397	SPECIALTY RESTAURANTS SG 31-26	PR	X
294356	WELL	PR	11/20/2008	GW	045-15388	SPECIALTY RESTAURANTS SG 32-26	PR	X
294357	WELL	PR	01/11/2008	GW	045-15398	SPECIALTY RESTAURANTS SG 22-26	PR	X
294358	WELL	PR	03/03/2009	GW	045-15389	SPECIALTY RESTAURANTS SG 432-26	PR	X
294359	WELL	PR	03/03/2009	GW	045-15390	SPECIALTY RESTAURANTS SG 332-26	PR	X

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Signs/Marker:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
BATTERY	Satisfactory			
CONTAINERS	Satisfactory			
TANK LABELS/PLACARDS	Satisfactory			
WELLHEAD	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Fencing/:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory			
TANK BATTERY	Satisfactory			
SEPARATOR	Satisfactory			

Equipment:					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Plunger Lift	16	Satisfactory			
Horizontal Heated Separator	17	Satisfactory	single separator at tank battery		
Bird Protectors	9	Satisfactory			

Facilities: <input type="checkbox"/> New Tank Tank ID: _____					
Contents	#	Capacity	Type	SE GPS	
CONDENSATE	2	300 BBLS	STEEL AST	,	
S/U/V:	Satisfactory		Comment:		
Corrective Action:					Corrective Date:

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action				Corrective Date	
Comment					

Facilities: <input type="checkbox"/> New Tank Tank ID: _____					
Contents	#	Capacity	Type	SE GPS	
PRODUCED WATER	2	300 BBLS	STEEL AST	,	
S/U/V:	Satisfactory		Comment:		
Corrective Action:					Corrective Date:

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Corrective Action				Corrective Date	
Comment					

Venting:		
Yes/No	Comment	

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 334745

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/U/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/U/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/U/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 294325 Type: WELL API Number: 045-15383 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Inspector Name: LONGWORTH, MIKE

Facility ID:	294327	Type:	WELL	API Number:	045-15384	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Facility ID:	294328	Type:	WELL	API Number:	045-15391	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Facility ID:	294330	Type:	WELL	API Number:	045-15392	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Facility ID:	294341	Type:	WELL	API Number:	045-15393	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Facility ID:	294343	Type:	WELL	API Number:	045-15394	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Facility ID:	294344	Type:	WELL	API Number:	045-15385	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Facility ID:	294347	Type:	WELL	API Number:	045-15386	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Facility ID:	294349	Type:	WELL	API Number:	045-15395	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Facility ID:	294352	Type:	WELL	API Number:	045-15396	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Facility ID:	294353	Type:	WELL	API Number:	045-15387	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Facility ID:	294355	Type:	WELL	API Number:	045-15397	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Facility ID:	294356	Type:	WELL	API Number:	045-15388	Status:	PR	Insp. Status:	PR

Producing WellComment: **Producing well**

Facility ID: 294357 Type: WELL API Number: 045-15398 Status: PR Insp. Status: PR

Producing WellComment: **Producing well**

Facility ID: 294358 Type: WELL API Number: 045-15389 Status: PR Insp. Status: PR

Producing WellComment: **Producing well**

Facility ID: 294359 Type: WELL API Number: 045-15390 Status: PR Insp. Status: PR

Producing WellComment: **Producing well****Environmental****Spills/Releases:**

Type of Spill: Description: Estimated Spill Volume:

Comment:

Corrective Action: Date:

Reportable: GPS: Lat Long

Proximity to Surface Water: Depth to Ground Water:

Water Well:

DWR Receipt Num: Owner Name: GPS : Lat Long

Field Parameters:

Sample Location:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use:

Comment:

1003a. Debris removed? CM

CA CA Date

Waste Material Onsite? CM

CA CA Date

Unused or unneeded equipment onsite? CM

CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors marked? _____ CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Inspector Name: LONGWORTH, MIKE

Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Ditches	Pass			
Gravel	Pass	Gravel	Pass			
Berms	Pass	Compaction	Pass			
Compaction	Pass	Culverts	Pass			
Seeding	Pass	Paving	Pass			

S/U/V: Satisfactory Corrective Date: _____

Comment: _____

CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT