

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



| | | | |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:
04/24/2014

Document Number:
668301297

Overall Inspection:

ACTION REQUIRED

FIELD INSPECTION FORM

| | | | | | |
|---------------------|---------------|---------------|-------------------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | 2A Doc Num: |
| | <u>203470</u> | <u>321509</u> | <u>JOHNSON, RANDELL</u> | <input type="checkbox"/> | |

Operator Information:

| | |
|-----------------------|--|
| OGCC Operator Number: | <u>100322</u> |
| Name of Operator: | <u>NOBLE ENERGY INC</u> |
| Address: | <u>1625 BROADWAY STE 2200</u> |
| City: | <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u> |

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------|--------------|-----------------------------|-----------------|
| Little, Josh | | jlittle@nobleenergyinc.com | All Inspections |
| Pavelka, Linda | 970-304-5217 | lpavelka@nobleenergyinc.com | All Inspections |
| Fogel, Heather | | hfogel@nobleenergyinc.com | All Inspections |

Compliance Summary:

| QtrQtr: | <u>NESW</u> | Sec: | <u>17</u> | Twp: | <u>1S</u> | Range: | <u>68W</u> |
|------------|-------------|------------|-------------|-------------------------------|-----------|----------------|-----------------|
| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
| 12/11/2013 | 600000397 | PR | SI | SATISFACTOR Y | P | | No |
| 12/09/2005 | 200082388 | PR | PR | SATISFACTOR Y | | Pass | No |
| 09/26/1997 | 500133197 | PR | PR | | | Fail | Yes |
| 09/08/1997 | 500133196 | CO | WO | | | Pass | No |
| 09/07/1997 | 500133195 | | | | | | |
| 07/03/1997 | 500133194 | CO | WO | | | Pass | No |
| 07/02/1997 | 500133192 | PR | PR | | | Pass | No |
| 07/01/1997 | 500133193 | | | | | | |
| 06/30/1997 | 500133190 | CO | | | | | |
| 12/16/1993 | 500133189 | | PR | | | | |

Inspector Comment:

Related Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|--|
| 203470 | WELL | PR | 02/24/1998 | OW | 014-09029 | FEDOROWICZ 1-17 | SI <input checked="" type="checkbox"/> |

Equipment:

Location Inventory

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

| Signs/Marker: | | | | |
|----------------------|------------------------------|---|---------------------------------------|------------|
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| TANK LABELS/PLACARDS | ACTION REQUIRED | Steel production tanks do not have the required contents or capacity signage/See attached photos on last page of document | Install sign to comply with rule 210. | 05/24/2014 |
| BATTERY | SATISFACTORY | | | |
| WELLHEAD | SATISFACTORY | | | |

Emergency Contact Number (S/A/V): SATISFACTORY Corrective Date: _____

Comment: _____

Corrective Action: _____

| Spills: | | | | |
|--|------|--------|-------------------|---------|
| Type | Area | Volume | Corrective action | CA Date |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |

| Fencing/: | | | | |
|------------------|------------------------------|------------------------------------|-------------------|---------|
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| WELLHEAD | SATISFACTORY | Chain link fencing w/privacy slats | | |
| SEPARATOR | SATISFACTORY | Chain link fencing | | |
| TANK BATTERY | SATISFACTORY | Chain link fencing | | |

| Equipment: | | | | | |
|-----------------------------|---|------------------------------|---------|-------------------|---------|
| Type | # | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| Horizontal Heated Separator | 1 | SATISFACTORY | | | |
| Plunger Lift | 1 | SATISFACTORY | | | |
| Gas Meter Run | 1 | SATISFACTORY | | | |

| | | | | | |
|--------------------|--------------|-----------------------------------|---------------------|-----------------------|--|
| Facilities: | | <input type="checkbox"/> New Tank | Tank ID: _____ | | |
| Contents | # | Capacity | Type | SE GPS | |
| PRODUCED WATER | 1 | <50 BBLS | BV CONCRETE | 39.962360,-105.028030 | |
| S/A/V: | SATISFACTORY | | Comment: 48 bbls | | |
| Corrective Action: | | | | Corrective Date: | |
| <u>Paint</u> | | | | | |
| Condition | | | | | |
| Other (Content) | _____ | | | | |
| Other (Capacity) | _____ | | | | |
| Other (Type) | _____ | | | | |
| <u>Berms</u> | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Corrective Action | | | | Corrective Date | |
| Comment | | | | | |

| | | |
|-----------------|---------|--|
| Venting: | | |
| Yes/No | Comment | |
| NO | | |

| | | | | |
|-----------------|------------------------------|---------|-------------------|---------|
| Flaring: | | | | |
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| | | | | |

Predrill

Location ID: 203470

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/A/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/A/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 203470 Type: WELL API Number: 014-09029 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

S/A/V: _____ CA Date: _____

CA: _____

Comment: Producing intermittently

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well: _____ Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters: _____

Sample Location: _____

Complaint:

| Tracking Num | Category | Assigned To | Description | Incident Date |
|--------------|-----------------------------|--------------|---|---------------|
| 786058 | ENVIRONM ENTAL DAMAGE | READE, ROBIN | Derrick on well pulled off today, when pulling up pipe. Oil started gushing out. Well was on property when they bought purchased the property and built their home. Clayton said they would replace the plants, complaint is that oil was spilled "all over the place". She is OK with allowing op to clean up. | 07/08/1997 |

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Pass CM _____

CA _____ CA Date _____

Waste Material Onsite? Pass CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass CM _____

CA _____ CA Date _____

Guy line anchors removed? Pass CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass
 Production areas have been stabilized? Pass Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|------------|
| Gravel | Pass | Gravel | Pass | | | |
| Compaction | Pass | Compaction | Pass | | | |
| Other | Pass | Other | Pass | | | Vegetation |

S/A/V: SATISFACTOR Corrective Date: _____
 Y _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--|---|
| 668301298 | Noble - Fedorowicz 1-17 (014-09029) - 1 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3328360 |
| 668301299 | Noble - Fedorowicz 1-17 (014-09029) - 2 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3328361 |