

Reference Area Photographs

Inspection Conducted on April 23, 2014

**Linn Energy LLC
Chevron 18-21D
Garden Gulch Rd
Location ID #335998**

Linn Energy LLC - Chevron 18-21D



Update Signs



Pit excavated. Some trash on the walls (pieces of liner).

Linn Energy LLC - Chevron 18-21D



Stockpile with material from the pit. Fluid from the stockpile seeping through the berm. Pieces of liner mixed with the material.



Pieces of liner mixed with the stockpile material.

Linn Energy LLC - Chevron 18-21D



Berm apparently made of the same material excavated from the pit



Fluids seeping through the berm.

Linn Energy LLC - Chevron 18-21D



Fluids seeping through the berm.



Close-up of a seep.