

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:

05/05/2014

Document Number:

663903129

Overall Inspection:

ACTION REQUIRED**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	336040	336040	LONGWORTH, MIKE	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 96155Name of Operator: WHITING OIL AND GAS CORPORATIONAddress: 1700 BROADWAY STE 2300City: DENVER State: CO Zip: 80290

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☒ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
YOKLEY, BILL		bill.yokley@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Lawson, Gary	970-878-4096	gary.lawson@whiting.com	EH&S Coordinator

Compliance Summary:QtrQtr: NESE Sec: 30 Twp: 2S Range: 97W**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
299467	WELL	XX	09/28/2011	LO	103-11409	Boies B-30H-H1	ND	<input checked="" type="checkbox"/>
299483	WELL	XX	10/06/2011	LO	103-11410	Boies B-30H-I3	ND	<input checked="" type="checkbox"/>
299484	WELL	XX	10/06/2011	LO	103-11411	Boies B-30H-I2	ND	<input checked="" type="checkbox"/>
299485	WELL	XX	10/06/2011	LO	103-11412	Boies B-30H-I1	ND	<input checked="" type="checkbox"/>
299486	WELL	XX	10/06/2011	LO	103-11413	BOIES B-30H-H4	ND	<input checked="" type="checkbox"/>
299487	WELL	XX	10/06/2011	LO	103-11414	Boies B-30H-H3	ND	<input checked="" type="checkbox"/>
299488	WELL	XX	10/06/2011	LO	103-11415	BOIES B-30H-H2	ND	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

<u>Lease Road:</u>				
Type	Satisfactory/Action Required	comment	Corrective Action	Date
Access	SATISFACTORY			

<u>Signs/Marker:</u>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
BATTERY	SATISFACTORY	Sign at entrance		

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

<u>Good Housekeeping:</u>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
DEBRIS	ACTION REQUIRED	Liner pieces, lumber, pvc piping, etc	Clean location of debris	05/31/2014
WEEDS	ACTION REQUIRED	Tall dead weeds	Clean of weeds	05/31/2014

<u>Spills:</u>				
Type	Area	Volume	Corrective action	CA Date

☐ Multiple Spills and Releases?

<u>Fencing/:</u>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
LOCATION	SATISFACTORY			

<u>Venting:</u>		
Yes/No	Comment	

<u>Flaring:</u>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 336040

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 299467 Type: WELL API Number: 103-11409 Status: XX Insp. Status: ND

Facility ID: 299483 Type: WELL API Number: 103-11410 Status: XX Insp. Status: ND

Facility ID: 299484 Type: WELL API Number: 103-11411 Status: XX Insp. Status: ND

Facility ID: 299485 Type: WELL API Number: 103-11412 Status: XX Insp. Status: ND

Facility ID: 299486 Type: WELL API Number: 103-11413 Status: XX Insp. Status: ND

Facility ID: 299487 Type: WELL API Number: 103-11414 Status: XX Insp. Status: ND

Facility ID: 299488 Type: WELL API Number: 103-11415 Status: XX Insp. Status: ND

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
 Comment: _____
 Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____
 Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____
 CA _____ CA Date _____
 Waste Material Onsite? _____ CM _____
 CA _____ CA Date _____
 Unused or unneeded equipment onsite? _____ CM _____
 CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors marked? _____ CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Inspector Name: LONGWORTH, MIKE

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Waddles	Pass					
Berms	Fail	Compaction	Pass			
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Culverts	Pass			
Seeding	Fail					
Ditches	Fail	Ditches	Pass			

S/A/V: **ACTION REQUIRED** Corrective Date: **05/31/2014**

Comment: _____

CA: **Maintain BMPs.**

Pits:	<input type="checkbox"/> NO SURFACE INDICATION OF PIT
--------------	---

COGCC Comments

Comment	User	Date
7 cellars, conductors and ratholes have been set on location. All drilling permits have expired as of 10/27/2013. Form 4(s) doc # 400573115 have been submitted for Intent to plug conductors Approximate start date 3/31/2014. Form 2(s) doc#400209686 expired 10/27/2013. Close all cellars, conductors and ratholes. Close cellars, conductors, and ratholes by 6/7/2014. Submit Form 42 when corrective actions are completed.	longworm	05/05/2014

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
663903146	Location sign at entrance	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3337809
663903147	Cellars and conductors	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3337810
663903148	Cellars and conductors	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3337811
663903149	Debris lumber & dead weeds	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3337812