

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

| DE | ET | OE | ES |
|----|----|----|----|
|----|----|----|----|

Inspection Date:

05/21/2014

Document Number:

668402211

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

| | | | | | |
|---------------------|-------------|--------|-----------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | 2A Doc Num: |
| | 229818 | 314880 | BROWNING, CHUCK | <input type="checkbox"/> | |

Operator Information:OGCC Operator Number: 16700Name of Operator: CHEVRON PRODUCTION COMPANYAddress: 100 CHEVRON RDCity: RANGELY State: CO Zip: 81648

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|--------------|----------------------------|-----------------------|
| Browning, Chuck | 970-433-4139 | chuck.browning@state.co.us | Field Inspector |
| Peterson, Diane | 970-675-3842 | dlpe@chevron.com | Regulatory Specialist |

Compliance Summary:QtrQtr: SESE Sec: 27 Twp: 2N Range: 102W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| 01/31/2014 | 673500509 | IJ | AC | SATISFACTOR Y | I | | No |
| 05/20/2013 | 668401165 | IJ | SI | SATISFACTOR Y | P | | No |
| 05/10/2013 | 668401123 | IJ | SI | SATISFACTOR Y | I | | No |
| 05/21/2012 | 662300558 | IJ | AC | SATISFACTOR Y | | | No |
| 01/31/2012 | 659300133 | IJ | SI | SATISFACTOR Y | P | | No |
| 05/19/2011 | 200310920 | RT | AC | SATISFACTOR Y | | | No |
| 05/18/2010 | 200258876 | RT | AC | SATISFACTOR Y | | | No |
| 06/09/2009 | 200213096 | RT | AC | SATISFACTOR Y | | | No |
| 05/27/2008 | 200198050 | RT | AC | SATISFACTOR Y | | | No |
| 05/10/2007 | 200113179 | RT | AC | SATISFACTOR Y | | Pass | No |
| 05/18/2006 | 200093245 | RT | AC | SATISFACTOR Y | | Pass | No |
| 05/02/2005 | 200071893 | MI | AC | SATISFACTOR Y | | Pass | No |
| 05/10/2004 | 200059721 | RT | AC | SATISFACTOR Y | | Pass | No |

Inspector Name: BROWNING, CHUCK

| | | | | | | | |
|------------|-----------|----|----|------------------|--|------|----|
| 05/21/2003 | 200043740 | RT | AC | SATISFACTOR Y | | Pass | No |
| 05/16/2002 | 200027463 | RT | AC | SATISFACTOR Y | | Pass | No |
| 05/22/2001 | 200019052 | RT | AC | SATISFACTOR Y | | Pass | No |
| 11/07/2000 | 200011310 | RT | AC | SATISFACTOR Y | | Pass | No |
| 07/31/2000 | 200009097 | RT | AC | SATISFACTOR Y | | Pass | No |

Inspector Comment:

UIC Routine inspection.

Related Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status | |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|-------------------------------------|
| 229818 | WELL | IJ | 12/16/2002 | DSPW | 103-07475 | LEVISON 32X | AC | <input checked="" type="checkbox"/> |

Equipment:

Location Inventory

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

| <u>Lease Road:</u> | | | | |
|---------------------------|---------------------------------|---------|-------------------|------|
| Type | Satisfactory/Action Required | comment | Corrective Action | Date |
| Main | SATISFACTORY | | | |
| Access | SATISFACTORY | | | |

| <u>Signs/Marker:</u> | | | | |
|-----------------------------|---------------------------------|---------|-------------------|---------|
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| WELLHEAD | SATISFACTORY | | | |

Emergency Contact Number (S/A/V): SATISFACTORY Corrective Date: _____

Comment: _____

Corrective Action: _____

| <u>Spills:</u> | | | | |
|--|------|--------|-------------------|---------|
| Type | Area | Volume | Corrective action | CA Date |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |

| <u>Venting:</u> | | |
|------------------------|---------|--|
| Yes/No | Comment | |
| NO | | |

| | | | | |
|-----------------|------------------------------|---------|-------------------|---------|
| Flaring: | | | | |
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| | | | | |

Predrill

Location ID: 229818

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:Name: _____ Address: _____
Phone Number: _____ Cell Phone: _____Operator Rep. Contact Information:Landman Name: _____ Phone Number: _____
Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 229818 Type: WELL API Number: 103-07475 Status: IJ Insp. Status: AC

Underground Injection Control

UIC Violation: _____

Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg 1509 Previous Test Pressure _____ MPP _____
 (e.g. 30 psig or -30" Hg) Inj Zone: WEBR

TC: Pressure or inches of Hg 20 Previous Test Pressure _____ Last MIT: 05/10/2013

Brhd: Pressure or inches of Hg _____ Previous Test Pressure _____ AnnMTReq: _____

Comment: UIC Routine inspection. Casing blowdown 60 sec.

Method of Injection: PUMP FEED

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____
 Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors marked? Pass CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____ P _____

Comment: _____

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms | Pass | Gravel | Pass | SI | Pass | |

Inspector Name: BROWNING, CHUCK

S/A/V: SATISFACTOR
Y

Corrective Date: _____

Comment:

CA:

Pits: ☐ NO SURFACE INDICATION OF PIT