

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

DE ET OE ES

Inspection Date:

05/16/2014

Document Number:

673900340

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

| | | | | | |
|---------------------|-------------|--------|-----------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | 2A Doc Num: |
| | 432656 | 432662 | Rains, Bill | <input type="checkbox"/> | |

Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1625 BROADWAY STE 2200City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------|-------|---------------------------|--------------------------------|
| HEATHER, FOGEL | | hfogel@nobleenergyinc.com | send all noble inp. to heather |

Compliance Summary:QtrQtr: NWNW Sec: 20 Twp: 6N Range: 62W**Inspector Comment:****Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status | |
|-------------|------|--------|-------------|------------|-----------|------------------------------|-------------|-------------------------------------|
| 432648 | WELL | DG | 10/29/2013 | LO | 123-37211 | WELLS RANCH USX AE 20-69-1HN | PR | <input checked="" type="checkbox"/> |
| 432649 | WELL | DG | 10/06/2013 | LO | 123-37212 | WELLS RANCH AE 20-67HN | PR | <input checked="" type="checkbox"/> |
| 432651 | WELL | DG | 09/28/2013 | LO | 123-37214 | WELLS RANCH AE 20-67-1HN | PR | <input checked="" type="checkbox"/> |
| 432653 | WELL | DG | 10/06/2013 | LO | 123-37216 | WELLS RANCH AE 20-68HN | PR | <input checked="" type="checkbox"/> |
| 432654 | WELL | DG | 10/15/2013 | LO | 123-37217 | WELLS RANCH AE 20-68-1HN | PR | <input checked="" type="checkbox"/> |
| 432656 | WELL | XX | 04/26/2013 | LO | 123-37219 | WELLS RANCH AE 20-66-1HN | PR | <input checked="" type="checkbox"/> |
| 432661 | WELL | DG | 11/06/2013 | LO | 123-37223 | WELLS RANCH AE 20-69HN | PR | <input checked="" type="checkbox"/> |
| 433243 | WELL | DG | 09/19/2013 | LO | 123-37561 | WELLS RANCH AE 20-66HN | PR | <input checked="" type="checkbox"/> |

Equipment:**Location Inventory**

Inspector Name: Rains, Bill

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: <u>8</u> | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: <u>8</u> |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

Signs/Marker:

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|----------------------|------------------------------|---------|-------------------|---------|
| CONTAINERS | SATISFACTORY | | | |
| TANK LABELS/PLACARDS | SATISFACTORY | | | |
| WELLHEAD | SATISFACTORY | | | |
| BATTERY | SATISFACTORY | | | |

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

| Type | Area | Volume | Corrective action | CA Date |
|------|------|--------|-------------------|---------|
|------|------|--------|-------------------|---------|

☐ Multiple Spills and Releases?

Fencing/:

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|----------|------------------------------|---------|-------------------|---------|
| WELLHEAD | SATISFACTORY | PIPE | | |
| LOCATION | SATISFACTORY | WIRE | | |

Equipment:

| Type | # | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|-----------------------------|----|------------------------------|----------------------------------|-------------------|---------|
| Compressor | 1 | SATISFACTORY | | | |
| Emission Control Device | 5 | SATISFACTORY | | | |
| Bird Protectors | 12 | SATISFACTORY | | | |
| Gas Meter Run | 15 | SATISFACTORY | | | |
| Flare | 3 | SATISFACTORY | | | |
| Vertical Separator | 20 | SATISFACTORY | | | |
| Horizontal Heated Separator | 6 | SATISFACTORY | | | |
| Plunger Lift | 8 | SATISFACTORY | | | |
| Ancillary equipment | 10 | SATISFACTORY | PROPAIN TANK, PORTABLE LIGHTS | | |

| | | | | | |
|------------------------|----------|-----------------------------------|---------------------|------------------|--|
| Facilities: | | <input type="checkbox"/> New Tank | | Tank ID: _____ | |
| Contents | # | Capacity | Type | SE GPS | |
| | | | CENTRALIZED PAD | | |
| S/A/V: | | | Comment: | | |
| Corrective Action: | | | | Corrective Date: | |
| <u>Paint</u> | | | | | |
| Condition | | | | | |
| Other (Content) _____ | | | | | |
| Other (Capacity) _____ | | | | | |
| Other (Type) _____ | | | | | |
| <u>Berms</u> | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| | | | | | |
| Corrective Action | | | | Corrective Date | |
| Comment | | | | | |
| Facilities: | | <input type="checkbox"/> New Tank | | Tank ID: _____ | |
| Contents | # | Capacity | Type | SE GPS | |
| OTHER | | | CENTRALIZED BATTERY | | |
| S/A/V: | | | Comment: | | |
| Corrective Action: | | | | Corrective Date: | |
| <u>Paint</u> | | | | | |
| Condition | | | | | |
| Other (Content) _____ | | | | | |
| Other (Capacity) _____ | | | | | |
| Other (Type) _____ | | | | | |
| <u>Berms</u> | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| | | | | | |
| Corrective Action | | | | Corrective Date | |
| Comment | | | | | |

| | | | | | |
|------------------------|--------------|-----------------------------------|---------------------|------------------|--|
| Facilities: | | <input type="checkbox"/> New Tank | | Tank ID: _____ | |
| Contents | # | Capacity | Type | SE GPS | |
| OTHER | 1 | 300 BBLS | STEEL AST | , | |
| S/A/V: | SATISFACTORY | | Comment: | | |
| Corrective Action: | | | | Corrective Date: | |
| <u>Paint</u> | | | | | |
| Condition | Adequate | | | | |
| Other (Content) _____ | | | | | |
| Other (Capacity) _____ | | | | | |
| Other (Type) _____ | | | | | |
| <u>Berms</u> | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Corrective Action | | | | Corrective Date | |
| Comment | | | | | |

| | | | | | |
|------------------------|--------------|-----------------------------------|---------------------|------------------|--|
| Facilities: | | <input type="checkbox"/> New Tank | | Tank ID: _____ | |
| Contents | # | Capacity | Type | SE GPS | |
| OTHER | 1 | <100 BBLS | BV CONCRETE | , | |
| S/A/V: | SATISFACTORY | | Comment: | | |
| Corrective Action: | | | | Corrective Date: | |
| <u>Paint</u> | | | | | |
| Condition | | | | | |
| Other (Content) _____ | | | | | |
| Other (Capacity) _____ | | | | | |
| Other (Type) _____ | | | | | |
| <u>Berms</u> | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Corrective Action | | | | Corrective Date | |
| Comment | | | | | |

| | | | | |
|------------------------|--------------|-----------------------------------|-----------------------------------|------------------|
| Facilities: | | <input type="checkbox"/> New Tank | Tank ID: _____ | |
| Contents | # | Capacity | Type | SE GPS |
| OTHER | 3 | 500 BBLS | STEEL AST | , |
| S/A/V: | SATISFACTORY | | Comment: MOBILE FRAC TANKS | |
| Corrective Action: | | | | Corrective Date: |
| <u>Paint</u> | | | | |
| Condition | Adequate | | | |
| Other (Content) _____ | | | | |
| Other (Capacity) _____ | | | | |
| Other (Type) _____ | | | | |
| <u>Berms</u> | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Corrective Action | | | | Corrective Date |
| Comment | | | | |

| | | | | |
|------------------------|--------------|-----------------------------------|---------------------|------------------|
| Facilities: | | <input type="checkbox"/> New Tank | Tank ID: _____ | |
| Contents | # | Capacity | Type | SE GPS |
| PRODUCED WATER | 4 | 500 BBLS | FIBERGLASS AST | , |
| S/A/V: | SATISFACTORY | | Comment: | |
| Corrective Action: | | | | Corrective Date: |
| <u>Paint</u> | | | | |
| Condition | Adequate | | | |
| Other (Content) _____ | | | | |
| Other (Capacity) _____ | | | | |
| Other (Type) _____ | | | | |
| <u>Berms</u> | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| | | | | |
| Corrective Action | | | | Corrective Date |
| Comment | | | | |

Inspector Name: Rains, Bill

| | | | | |
|--------------------|--------------|-----------------------------------|--|--------|
| Facilities: | | <input type="checkbox"/> New Tank | Tank ID: _____ | |
| Contents | # | Capacity | Type | SE GPS |
| OTHER | 5 | 500 BBLS | STEEL AST | , |
| S/A/V: | SATISFACTORY | | Comment: TANKS NOT IN USE AND WILL BE REMOVED. | |
| Corrective Action: | | | Corrective Date: | |

Paint

| | |
|-----------|----------|
| Condition | Adequate |
|-----------|----------|

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

| | | | | |
|-------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |

| | |
|-------------------|-----------------|
| Corrective Action | Corrective Date |
| Comment | |

| | | | | |
|--------------------|--------------|-----------------------------------|------------------|-----------------------|
| Facilities: | | <input type="checkbox"/> New Tank | Tank ID: _____ | |
| Contents | # | Capacity | Type | SE GPS |
| CRUDE OIL | 10 | 500 BBLS | STEEL AST | 40.472860,-104.341560 |
| S/A/V: | SATISFACTORY | | Comment: | |
| Corrective Action: | | | Corrective Date: | |

Paint

| | |
|-----------|----------|
| Condition | Adequate |
|-----------|----------|

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

| | | | | |
|-------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |

| | |
|-------------------|-----------------|
| Corrective Action | Corrective Date |
| Comment | |

| | | |
|-----------------|---------|--|
| Venting: | | |
| Yes/No | Comment | |
| NO | | |

| | | | | |
|-----------------|------------------------------|---------|-------------------|---------|
| Flaring: | | | | |
| Type | Satisfactory/Action Required | | | |
| | | Comment | Corrective Action | CA Date |
| | | | | |

| | | | | |
|--------------------------|--|-------------|--|-----------------------|
| Predrill | | | | |
| Location ID: 432656 | | | | |
| Site Preparation: | | | | |
| Lease Road Adeq.: _____ | | Pads: _____ | | Soil Stockpile: _____ |

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:**

| BMP Type | Comment |
|--|---|
| General Housekeeping | Housekeeping will consist of neat and orderly storage of materials and fluids. Wastes will be temporarily stored in sealed containers and regularly collected and disposed of at offsite, suitable facilities. If spills occur prompt cleanup is required to minimize any commingling of waste materials with stormwater runoff. Routine maintenance will be limited to fueling and lubrication of equipment. Drip pans will be used during routine fueling and maintenance to contain spills or leaks. Any waste product from maintenance will be containerized and transported offsite for disposal or recycling. There will be no major equipment overhauls conducted onsite. Equipment will be transported offsite for major overhauls. Cleanup of trash and discarded materials will be conducted at the end of each work day. Cleanup will consist of patrolling the roadway, access areas, and other work areas to pickup trash, scrap debris, other discarded materials, and any contaminated soil. These materials will be disposed of properly. |
| Material Handling and Spill Prevention | Spill Prevention Control and Countermeasures (SPCC) plans are in place to address any possible spill associated with Oil & Gas operations throughout the state of Colorado in accordance with CFR 112. |
| Storm Water/Erosion Control | Stormwater management plans (SWMP) are in place to address construction, drilling and operations associated with Oil & Gas development throughout the state of Colorado in accordance with Colorado Department of Public and Environment (CDPHE) General Permit No. COR-038637. BMP's will be constructed around the perimeter of the site prior to, or at the beginning of construction. BMP's used will vary according to the location, and will remain in place until the pad reaches final reclamation. |

S/A/V: _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 432648 Type: WELL API Number: 123-37211 Status: DG Insp. Status: PR

Producing Well

Comment: PR

Facility ID: 432649 Type: WELL API Number: 123-37212 Status: DG Insp. Status: PR

Producing Well

Comment: PR

Facility ID: 432651 Type: WELL API Number: 123-37214 Status: DG Insp. Status: PR

Producing Well

Comment: PR

Facility ID: 432653 Type: WELL API Number: 123-37216 Status: DG Insp. Status: PR

Producing Well

Comment: PR

Facility ID: 432654 Type: WELL API Number: 123-37217 Status: DG Insp. Status: PR

Producing Well

Comment: PR

Facility ID: 432656 Type: WELL API Number: 123-37219 Status: XX Insp. Status: PR

Producing Well

Comment: PR

Facility ID: 432661 Type: WELL API Number: 123-37223 Status: DG Insp. Status: PR

Producing Well

Comment: PR

Facility ID: 433243 Type: WELL API Number: 123-37561 Status: DG Insp. Status: PR

Producing Well

Comment: PR

Environmental**Spills/Releases:**

Type of Spill: Description: Estimated Spill Volume:

Comment:

Corrective Action: Date:

Reportable: GPS: Lat Long

Proximity to Surface Water: Depth to Ground Water:

Water Well:

DWR Receipt Num: Owner Name: GPS: Lat Long

Field Parameters:

Inspector Name: Rains, Bill

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1003a. Debris removed? _____ CM _____
CA _____ CA Date _____
Waste Material Onsite? _____ CM _____
CA _____ CA Date _____
Unused or unneeded equipment onsite? _____ CM _____
CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? _____ CM _____
CA _____ CA Date _____
Guy line anchors removed? _____ CM _____
CA _____ CA Date _____
Guy line anchors marked? _____ CM _____
CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____ In Process _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Inspector Name: Rains, Bill

Reminder:

Comment:

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment:

Corrective Action:

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | MHSP | Pass | |

S/A/V: SATISFACTOR
Y _____

Corrective Date: _____

Comment:

CA:

Pits: ☒ NO SURFACE INDICATION OF PIT