

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
05/28/2014

Document Number:
668200773

Overall Inspection:

VIOLATION

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	412248		LEONARD, MIKE	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>4680</u>
Name of Operator:	<u>DCP MIDSTREAM LP</u>
Address:	<u>370 17TH STREET - SUITE 2500</u>
City:	<u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Park, Paul	(970) 378-6372	PDPark@dcpmidstream.com	All Plant Inspections

Compliance Summary:

QtrQtr: _____ Sec: _____ Twp: _____ Range: _____

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
05/17/2014	668200760	AC	AC	SATISFACTOR Y			No
05/06/2014	668200767	AC	AC	SATISFACTOR Y			No
04/29/2014	668200765	AC	AC	SATISFACTOR Y			No
04/23/2014	668200764	AC	AC	SATISFACTOR Y			No
04/22/2014	668200762	AC	AC	SATISFACTOR Y			No

Inspector Comment:

Within ten days submit plan for mitigation to bring to compliant noise levels.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412248	GAS PROCESSING PLANT	AC	04/20/1998		-	MEWBOURN GAS PLANT 412248	AC <input checked="" type="checkbox"/>

Equipment:

Location Inventory

Location

Emergency Contact Number (S/A/V): _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills: _____

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

Multiple Spills and Releases?

Venting:	
Yes/No	Comment

Flaring:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 412248

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AV: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 412248 Type: GAS API Number: - Status: AC Insp. Status: AC

Complaint

Comment: Inspection performed in response to complaint #200406064. Sound Survey taken from 534 feet north of plant indicates levels are above limits for "A" Scale (see attached survey). See attached survey

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
 Comment: _____
 Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Complaint:

Tracking Num	Category	Assigned To	Description	Incident Date
200401845	NOISE	LEONARD, MIKE	The noise from the Mewbourn Gas Plant located east of Gilcrest Colorado on Cr 35 is a nuisance. These noise levels are interfering with my ability to use my residential property for it's intended purpose. The noise is also creating health and mental damage to me, my wife and our small children ages 3 and 5. The gas plant operates 24/7, 365 days a year and for periods of long duration over the last 2 years have been beyond acceptable levels.	04/10/2014
200403078	AESTHETIC S	LEONARD, MIKE	The gas plant does not meet regulation 804 regarding Visual Impact Mitigation. The Mewbourn Gas Plant is visible from HWY 85 as well as many public roads in the area. The plant is constructed of mostly reflective materials that are also contrasting against the surrounding landscape.	04/27/2014
200403078	LIGHTING	LEONARD, MIKE	regulation 803 is also being vioalted. the lighting cause galre on County Road 35 as well as the trailer house to the east of the plant that may be within 1,000 feet. DCP Midstream should offer at least a good will gesture to the surrounding property owners and the community by mitigating the light pollution regardless of structure vicinity. Although I am 3/4 of a mile away, the bright lights cause fatigue and visual stress at night which in turn is causing emotional, physical and mental stree and damage. Regulation 803 is also being vioalted during flaring. At night, the flare will light up the surrounding community for miles. Many public roadways and structures are subjected to this light pollution. It also scares the bejesus out of my kids ages 3 and 5. They scream "fire Daddy, fire" and come running inside. The above visual and light regulations are causing a decrease in property values and the quality of life for myself and the people of the State of Colorado and Weld County	04/27/2014
200406064	NOISE	LEONARD, MIKE	Mr. Ewing sent an email on May 27, 2014 saying the DCP plant is too loud	05/29/2014

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Inspector Name: LEONARD, MIKE

Debris removed _____ No disturbance /Location never built _____
 Access Roads Regraded _____ Contoured _____ Culverts removed _____
 Gravel removed _____
 Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____
 Compaction alleviation _____ Dust and erosion control _____
 Non cropland: Revegetated 80% _____ Cropland: perennial forage _____
 Weeds present _____ Subsidence _____
 Comment: _____
 Corrective Action: _____ Date _____
 Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____ Corrective Date: _____
 Comment: _____
 CA: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments		
Comment	User	Date
Within ten days submit plan for mitigation to bring to compliant noise levels.	leonardm	05/29/2014

Attached Documents
 You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
668200774	Sound Survey	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3352504