

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

DE ET OE ES

Inspection Date:

05/27/2014

Document Number:

673703621

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	236393	317108	Sherman, Susan	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 101101Name of Operator: SAGA PETROLEUM LIMITED LIABILITY CO OF COAddress: 600 17TH ST STE 1700NCity: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Reis, Jaimie	(303) 996-7766 X304	jreis@sagapetroleum.com	
Dunham, Tyson	307-388-2290	tdunham@sagapetroleum.com	

Compliance Summary:QtrQtr: SWNW Sec: 25 Twp: 3S Range: 51W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
06/02/2010	200254234	CO	PR	ACTION REQUIRED			No
10/15/2005	200078894	PR	PR	SATISFACTORY Y		Pass	No
09/05/2000	200030084	PR	PR	SATISFACTORY Y		Pass	No
05/17/1995	500159365	PR	PR				No

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
236393	WELL	PR	05/05/1974	OW	121-08883	JONES J W 2	PR	<input checked="" type="checkbox"/>

Equipment:**Location Inventory**

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Inspector Name: Sherman, Susan

Signs/Marker:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
CONTAINERS	SATISFACTORY			
WELLHEAD	SATISFACTORY			

Emergency Contact Number (S/A/V): SATISFACTORY Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
OTHER	SATISFACTORY	Barbed wire around electric box.		

Equipment:					
Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Submersible Pump	1	SATISFACTORY			
Ancillary equipment	7	SATISFACTORY	Four REA poles, transformer, 2 electric boxes, cathodic protection		
Deadman # & Marked	4	SATISFACTORY			

Facilities: ☐ New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
			CENTRALIZED BATTERY	39.768600,-103.055000

S/A/V: _____ Comment: _____

Corrective Action: _____ Corrective Date: _____

Paint

Condition	
-----------	--

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Corrective Action: _____ Corrective Date: _____

Comment: _____

Venting:

Yes/No	Comment

Inspector Name: Sherman, Susan

Flaring:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 236393

Site Preparation:

Lease Road Adeq.: Pads: Soil Stockpile:

S/A/V:

Corrective Action: Date: CDP Num.:

Form 2A COAs:

S/A/V: **Comment:**

CA: **Date:**

Wildlife BMPs:

S/A/V: **Comment:**

CA: **Date:**

Stormwater:

Comment:

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: Address:

Phone Number: Cell Phone:

Operator Rep. Contact Information:

Landman Name: Phone Number:

Date Onsite Request Received: Date of Rule 306 Consultation:

Request LGD Attendance:

LGD Contact Information:

Name: Phone Number: Agreed to Attend:

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 236393 Type: WELL API Number: 121-08883 Status: PR Insp. Status: PR

Producing Well

Comment: Mar 2014 last reported production data.

Environmental

Spills/Releases:

Type of Spill: Description: Estimated Spill Volume:

Inspector Name: Sherman, Susan

Comment:

Corrective Action:

Date:

Reportable:

GPS: Lat

Long

Proximity to Surface Water:

Depth to Ground Water:

Water Well:

Lat

Long

DWR Receipt Num:

Owner Name:

GPS :

Field Parameters:

Sample Location:

Emission Control Burner (ECB):

Comment:

Pilot:

Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started:

Date Interim Reclamation Completed:

Land Use:

Comment: pasture

1003a. Debris removed? Pass CM

CA

CA Date

Waste Material Onsite? Pass CM

CA

CA Date

Unused or unneeded equipment onsite? Pass CM

CA

CA Date

Pit, cellars, rat holes and other bores closed? CM

CA

CA Date

Guy line anchors removed? CM

CA

CA Date

Guy line anchors marked? Pass CM

CA

CA Date

1003b. Area no longer in use? Pass

Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped?

1003d. Drilling pit closed? Pass

Subsidence over on drill pit? Pass

Cuttings management:

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass

Production areas have been stabilized? Pass

Segregated soils have been replaced?

RESTORATION AND REVEGETATION

Cropland

Top soil replaced

Recontoured

Perennial forage re-established

Inspector Name: Sherman, Susan

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation Pass

1003 f. Weeds Noxious weeds? _____

Comment: mustard and cheatgrass

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	SI	Pass	
Compaction	Pass	Compaction	Pass	MHSP	Pass	

S/A/V: SATISFACTOR
Y

Corrective Date: _____

Comment: _____

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
673703644	SAGA JW Jones 2 well	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3355420
673703645	SAGA JW Jones 2 well	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3355421
673703646	SAGA JW Jones 2 well	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3355422