

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:

06/04/2014

Document Number:

668301610

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	203455	320326	JOHNSON, RANDELL	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 10261Name of Operator: BAYSWATER EXPLORATION AND PRODUCTION LLCAddress: 730 17TH ST STE 610City: DENVER State: CO Zip: 80202

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Barbula, Don		dbarbula@bayswater.us	
Blyth, Tom		tblyth@bayswater.us	Regulatory

Compliance Summary:QtrQtr: SWNW Sec: 4 Twp: 1S Range: 67W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
12/20/2013	600000496	PR	PR	ACTION REQUIRED	P		No
04/02/2013	668700584	PR	PR	ACTION REQUIRED	P		No
02/09/2006	200088490	PR	PR	ACTION REQUIRED		Fail	No
02/08/2006	200088486	PR	PR	ACTION REQUIRED		Fail	No
08/03/2001	200019024	BH	PR	SATISFACTORY		Pass	No
10/03/2000	896306	CO	PR	SATISFACTORY		Pass	No
09/05/2000	896305	CO	PR	ACTION REQUIRED		Fail	Yes
02/28/2000	895320	CO	PR	ACTION REQUIRED		Fail	Yes
05/25/1998	500133180	PR	PR			Fail	Yes

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203455	WELL	PR	04/23/1991	OW	001-09014	ZARLENGO B1	PR

Equipment:Location Inventory

Inspector Name: JOHNSON, RANDELL

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			

Emergency Contact Number (S/A/V): _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Fencing/:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY	Wire mesh fencing		

Equipment:

Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Prime Mover	1	SATISFACTORY	Gas engine		
Pump Jack	1	SATISFACTORY			

Facilities:		<input type="checkbox"/> New Tank		Tank ID: _____	
Contents	#	Capacity	Type	SE GPS	
			CENTRALIZED BATTERY	39.993920,-104.902820	
S/A/V:	SATISFACTORY		Comment:	See related inspection document #668301607 for information concerning shared facilities and equipment	
Corrective Action:					Corrective Date:
Paint					
Condition	Adequate				
Other (Content)	_____				
Other (Capacity)	_____				
Other (Type)	_____				
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Corrective Action					Corrective Date
Comment					
Venting:					
Yes/No	Comment				
NO					
Flaring:					
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date	

Predrill

Location ID: 203455

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 203455 Type: WELL API Number: 001-09014 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well:

Lat _____

Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Pass CM _____
 CA _____ CA Date _____
 Waste Material Onsite? Pass CM _____
 CA _____ CA Date _____
 Unused or unneeded equipment onsite? Pass CM _____
 CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? Pass CM _____
 CA _____ CA Date _____
 Guy line anchors removed? Pass CM _____
 CA _____ CA Date _____
 Guy line anchors marked? _____ CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? PassProduction areas have been stabilized? Pass Segregated soils have been replaced? _____**RESTORATION AND REVEGETATION**Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Inspector Name: JOHNSON, RANDELL

Comment: _____

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Other	Pass	Other	Pass			Vegetation
Compaction	Pass	Compaction	Pass			

S/A/V: SATISFACTOR
Y _____

Corrective Date: _____

Comment: _____

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT