

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

DE ET OE ES

Inspection Date:

06/09/2014

Document Number:

675200050

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	334507	334507	CONKLIN, CURTIS	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 66561Name of Operator: OXY USA INCAddress: PO BOX 27757City: HOUSTON State: TX Zip: 77227

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shuan.kellerby@state.co.us	
Clark, Chris		chris_clark@oxy.com	

Compliance Summary:QtrQtr: NWSE Sec: 2 Twp: 9S Range: 92W**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
277500	WELL	PR	10/29/2007	GW	077-08876	HELLS GULCH FEDERAL 2-9	PR	<input checked="" type="checkbox"/>
277501	WELL	PR	10/20/2010	GW	077-08875	HELLS GULCH FEDERAL 2-10	PR	<input checked="" type="checkbox"/>
277502	WELL	PR	10/24/2007	GW	077-08874	HELLS GULCH FEDERAL 2-15	PR	<input checked="" type="checkbox"/>
277503	WELL	PR	10/07/2007	GW	077-08873	HELLS GULCH FEDERAL 2-16	PR	<input checked="" type="checkbox"/>
281422	WELL	PR	10/25/2007	GW	077-08962	HELLS GULCH FEDERAL 2-7	PR	<input checked="" type="checkbox"/>
291795	WELL	AL	05/15/2012	LO	077-09376	Hell's Gulch Federal 1-12	AL	<input checked="" type="checkbox"/>
291798	WELL	AL	05/15/2012	LO	077-09377	Hell's Gulch Federal 2-11	AL	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date
Access	SATISFACTORY			

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
TANK LABELS/PLACARDS	SATISFACTORY			
WELLHEAD	SATISFACTORY			
CONTAINERS	SATISFACTORY	Foaming Agent		

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?**Fencing/:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
LOCATION	SATISFACTORY	Wire Fence		

Equipment:

Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Horizontal Heated Separator	5	SATISFACTORY			
Bird Protectors	2	SATISFACTORY			
Plunger Lift	5	SATISFACTORY			
Ancillary equipment	1	SATISFACTORY	Foaming Agent		

Facilities:		<input type="checkbox"/> New Tank		Tank ID: _____	
Contents	#	Capacity	Type	SE GPS	
METHANOL	1	OTHER	STEEL AST		
S/A/V:			Comment: Paint beginning to peel		
Corrective Action:				Corrective Date:	
<u>Paint</u>					
Condition	Adequate				
Other (Content) _____					
Other (Capacity) _____					
Other (Type) _____					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Corrective Action				Corrective Date	
Comment				Same as 300 bbl tanks	

Facilities:		<input type="checkbox"/> New Tank		Tank ID: _____	
Contents	#	Capacity	Type	SE GPS	
CONDENSATE	3	300 BBLS	STEEL AST	39.299820,-107.629650	
S/A/V:			Comment:		
Corrective Action:				Corrective Date:	
<u>Paint</u>					
Condition	Adequate				
Other (Content) _____					
Other (Capacity) _____					
Other (Type) _____					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Corrective Action				Corrective Date	
Comment					

Venting:				
Yes/No	Comment			

Flaring:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 334507

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Group	User	Comment	Date
Field Inspector	burgerc	Compliance will be documented with site inspection.	02/13/2014

S/A/V: _____ **Comment:** _____CA: _____ **Date:** _____**Wildlife BMPs:**S/A/V: _____ **Comment:** _____CA: _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:**Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Facility**

Facility ID: 277500 Type: WELL API Number: 077-08876 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Facility ID: 277501 Type: WELL API Number: 077-08875 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Facility ID: 277502	Type: WELL	API Number: 077-08874	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: PR

Facility ID: 277503	Type: WELL	API Number: 077-08873	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: PR

Facility ID: 281422	Type: WELL	API Number: 077-08962	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: PR

Facility ID: 291795	Type: WELL	API Number: 077-09376	Status: AL	Insp. Status: AL
---------------------	------------	-----------------------	------------	------------------

Facility ID: 291798	Type: WELL	API Number: 077-09377	Status: AL	Insp. Status: AL
---------------------	------------	-----------------------	------------	------------------

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____
 CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors marked? _____ CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Inspector Name: CONKLIN, CURTIS

Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Ditches	Pass			
Berms	Pass	Compaction	Pass	MHSP	Pass	
Sediment Traps	Pass	Sediment Traps	Pass			
Compaction	Pass	Culverts	Pass	VT	Pass	
Gravel	Pass	Gravel	Pass			
Slope Roughening	Pass					
Seeding	Pass	Rip Rap	Pass			

S/A/V: SATISFACTOR
Y _____

Corrective Date: _____

Comment: _____

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT