

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

| DE | ET | OE | ES |
|----|----|----|----|
|----|----|----|----|

Inspection Date:

06/12/2014

Document Number:

673704050

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

| | | | | | |
|---------------------|---------------|---------------|-----------------------|--------------------|--|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | |
| | <u>236435</u> | <u>317113</u> | <u>Sherman, Susan</u> | 2A Doc Num: | |

Operator Information:OGCC Operator Number: 24500Name of Operator: PADCO LLCAddress: P O BOX 5275City: BEVERLY HILLS State: CA Zip: 90209-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|---------------|----------------|----------------------|--------------------------|
| Richmond, Dan | (918) 630-9912 | dan_dsrinc@cox.net | Field Operations Manager |
| Crumley, Tim | (970) 768-5658 | tcrumley@comcast.net | |

Compliance Summary:QtrQtr: NWSW Sec: 22 Twp: 2S Range: 53W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| 01/22/2014 | 673700935 | PR | SI | SATISFACTOR Y | P | | No |
| 08/13/2008 | 200195802 | PR | PR | SATISFACTOR Y | | | No |
| 11/01/2007 | 200121568 | PR | PR | SATISFACTOR Y | | | No |
| 10/15/1998 | 500159387 | ES | PR | | | Pass | No |
| 05/13/1996 | 500159386 | PR | PR | | | Pass | No |
| 12/05/1995 | 500159385 | PR | PR | | | Pass | No |
| 09/20/1995 | 500159384 | PR | PR | | | Fail | Yes |

Inspector Comment:**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status | |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|-------------------------------------|
| 104593 | PIT | | 09/23/1999 | | - | WRIGHT 1-D | | <input type="checkbox"/> |
| 236435 | WELL | PR | 10/21/1980 | OW | 121-08925 | WRIGHT 1-D | SI | <input checked="" type="checkbox"/> |

Equipment:Location Inventory

Inspector Name: Sherman, Susan

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

Signs/Marker:

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|----------|------------------------------|---------|-------------------|---------|
| WELLHEAD | SATISFACTORY | | | |

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

| Type | Area | Volume | Corrective action | CA Date |
|------|------|--------|-------------------|---------|
|------|------|--------|-------------------|---------|

☐ Multiple Spills and Releases?

Venting:

| Yes/No | Comment |
|--------|---------|
| | |

Flaring:

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|------|------------------------------|---------|-------------------|---------|
| | | | | |

Predrill

Location ID: 236435

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:**Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Facility**

Facility ID: 236435 Type: WELL API Number: 121-08925 Status: PR Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

S/A/V: _____ CA Date: _____

CA: _____

Comment: MIT
Initial 350 psi, 5 min-350 psi, 10 min-350 psi, 15 min-350 psi. See attached Form 21.**Environmental****Spills/Releases:**

Inspector Name: Sherman, Susan

| | | |
|-----------------------------|------------------------|-------------------------|
| Type of Spill: | Description: | Estimated Spill Volume: |
| Comment: | | |
| Corrective Action: | Date: | |
| Reportable: | GPS: Lat | Long |
| Proximity to Surface Water: | Depth to Ground Water: | |

Water Well:

| | | | | |
|------------------|-------------|-------|-----|------|
| DWR Receipt Num: | Owner Name: | GPS : | Lat | Long |
|------------------|-------------|-------|-----|------|

Field Parameters:

Sample Location:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use:

Comment: corn field

| | | | | |
|--------|---|----|----|---------|
| 1003a. | Debris removed? | CM | CA | CA Date |
| | Waste Material Onsite? | CM | CA | CA Date |
| | Unused or unneeded equipment onsite? | CM | CA | CA Date |
| | Pit, cellars, rat holes and other bores closed? | CM | CA | CA Date |
| | Guy line anchors removed? | CM | CA | CA Date |
| | Guy line anchors marked? | CM | CA | CA Date |

1003b. Area no longer in use? Production areas stabilized ?

1003c. Compacted areas have been cross ripped?

1003d. Drilling pit closed? Subsidence over on drill pit?

Cuttings management:

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing?

Production areas have been stabilized? Segregated soils have been replaced?

RESTORATION AND REVEGETATION

Cropland

Inspector Name: Sherman, Susan

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

S/A/V: _____ Corrective Date: _____

Comment: Muddy from storm the night before.

CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-----------------------------|---|
| 673704057 | PADCO Wright 1D well sign | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3364924 |
| 673704058 | PADCO Wright 1D wellhead | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3364925 |
| 673704059 | PADCO Wright 1D MIT 6_12_14 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3364926 |