


North Platte J-24 Pad DWR Wells

Sec 24 T5N R63W

Bonanza Creek Energy Operating Company LLC



North Platte Pad DWR Well Status
Sec 24 T5N R63W
Bonanza Creek Energy Operating Company LLC

WELL DESCRIPTION	LOCATION	WELL INFORMATION				Well Status
		Depth	Top Perf	Bottom Perf	Aquifer	
Receipt=0014360A, Permit=0014360-MH- PURVIS GERALD	23 5 N-63W	0	0	0	GW	Not representative/not equipped (Monitoring hole)
Receipt=0014361, Permit=0014361-MH- NATIONAL FARMS 70	24 5 N-63W	0	0	0	GW	Not representative/not equipped (Monitoring hole)
Receipt=0042688, Permit=0042688-MH- NATIONAL HOG FARM	NENE 24 5 N-63W	0	0	0	GW	Not representative/not equipped (Monitoring hole)
Receipt=9065625, Permit=0081435-- ALLARD CATTLE COMPANY	NENE 24 5 N-63W	78	0	0	GW	Not equipped/not maintained - not on active list of wells provided by 70 Ranch mgr. (Stock well)
Receipt=9065622, Permit=0081432-- ALLARD CATTLE COMPANY	SWSW 24 5 N-63W	88	0	0	GW	Not equipped/not maintained - not on active list of wells provided by 70 Ranch mgr. (Stock well)
Receipt=0304177I, Permit=0035644-M- NATIONAL HOG FARMS	NENE 25 5 N-63W	72	20	71	GW	Abandoned
Receipt=0304177H, Permit=0035643-M- NATIONAL HOG FARMS	NENE 25 5 N-63W	90	20	90	GW	Abandoned
Receipt=2007113, Permit=2007113-AB- FIVE RIVERS RANCH CATTLE FEED LLC	NW 25 5 N-63W	80	0	0	GW	Abandoned
Receipt=0304177G, Permit=0035642-M- NATIONAL HOG FARMS	NW 25 5 N-63W	67	20	67	GW	Abandoned
Receipt=0023015, Permit=0023015-MH- NATIONAL HOG FARM	NE 26 5 N-63W	31	0	0	GW	Abandoned