


Antelope T-18 Pad DWR Wells

Sec 18 T5N R62W

Bonanza Creek Energy Operating Company LLC



Antelope T-18 Pad DWR Well Status
Sec 18 T5N R62W
Bonanza Creek Energy Operating Company LLC

| WELL DESCRIPTION | LOCATION | WELL INFORMATION | | | | Well Status |
|-----------------------------------------------------|----------|------------------|----------|-------------|---------|---------------------------------------------------|
| | | Depth | Top Perf | Bottom Perf | Aquifer | |
| Receipt=0016002, Permit=0016002-MH- | NW 17 | 0 | 0 | 0 | GW | Not representative/not equipped (Monitoring hole) |
| NATIONAL HOG FARMS | 5 N-62W | | | | | |
| Receipt=0314638L, Permit=0040922-M- | NENW 17 | 25 | 5 | 25 | GW | Abandoned |
| NATIONAL HOG FARMS INC | 5 N-62W | | | | | |
| Receipt=0314638E, Permit=0040915-M- | NWNE 18 | 40 | 10 | 40 | GW | Abandoned |
| NATIONAL HOG FARMS INC | 5 N-62W | | | | | |
| Receipt=0385493C, Permit=0188372-- | NESW 18 | 25 | 12 | 23 | GW | Not representative/not equipped (Monitoring hole) |
| NATIONAL HOG FARMS | 5 N-62W | | | | | |
| Receipt=0508477E, Permit=0188372--A | NESW 18 | 0 | 0 | 0 | GW | Not representative/not equipped (Monitoring hole) |
| NATIONAL HOG FARM KERSEY | 5 N-62W | | | | | |
| Receipt=0024456, Permit=0024456-MH- | NESW 18 | 0 | 0 | 0 | GW | Not representative/not equipped (Monitoring hole) |
| NATIONAL HOG FARMS | 5 N-62W | | | | | |
| Receipt=0041938, Permit=0041938-MH- | NESW 18 | 0 | 0 | 0 | GW | Not representative/not equipped (Monitoring hole) |
| NATIONAL HOG FARMS | 5 N-62W | | | | | |
| Receipt=9065621, Permit=0081431-- | NWSW 18 | 165 | 0 | 0 | GW | Not representative/not maintained (Stock) |
| ALLARD CATTLE COMPANY | 5 N-62W | | | | | |
| Receipt=3661337, Permit=0292287-- | NWNW 19 | 1,406 | 940 | 1,340 | GW | Not representative/not equipped (Monitoring hole) |
| 70 RANCH | 5 N-62W | | | | | |
| Receipt=0023005, Permit=0023005-MH- | NW 20 | 19 | 0 | 0 | GW | Abandoned |
| NATIONAL HOG FARM | 5 N-62W | | | | | |