

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:

06/16/2014

Document Number:

675200097

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	334542	334542	CONKLIN, CURTIS	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 66561Name of Operator: OXY USA INCAddress: PO BOX 27757City: HOUSTON State: TX Zip: 77227

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Clark, Chris		chris_clark@oxy.com	
Kellerby, Shaun		shuan.kellerby@state.co.us	

Compliance Summary:

QtrQtr:	<u>NESW</u>	Sec:	<u>6</u>	Twp:	<u>10S</u>	Range:	<u>94W</u>
Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
06/06/2014	675200036			ACTION REQUIRED			No

Inspector Comment:

This was a follow up inspection for Doc#675200036.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
283345	WELL	PR	06/24/2008	GW	077-09026	MY WAY RANCH FED. 6-15	PR	<input checked="" type="checkbox"/>
283346	WELL	PR	02/22/2006	GW	077-09025	MY WAY RANCH FED. 6-14	PR	<input checked="" type="checkbox"/>
283347	WELL	PR	06/24/2008	GW	077-09024	MY WAY RANCH FED. 6-12	PR	<input checked="" type="checkbox"/>
283349	WELL	PR	06/24/2008	GW	077-09023	MY WAY RANCH FED. 6-7	PR	<input checked="" type="checkbox"/>
283352	WELL	PR	02/22/2006	GW	077-09022	MY WAY RANCH FED. 6-2	PR	<input checked="" type="checkbox"/>
283354	WELL	PR	06/24/2008	GW	077-09021	MY WAY RANCH FED. 6-10	PR	<input checked="" type="checkbox"/>
283356	WELL	PR	08/27/2013	GW	077-09020	MY WAY RANCH FED. 6-9	PR	<input checked="" type="checkbox"/>
283360	WELL	PR	02/22/2006	GW	077-09019	MY WAY RANCH FED. 6-8	PR	<input checked="" type="checkbox"/>
283362	WELL	PR	02/22/2006	GW	077-09018	MY WAY RANCH FED. 6-6	PR	<input checked="" type="checkbox"/>

283364	WELL	PR	02/22/2006	GW	077-09016	MY WAY RANCH FED. 6-11	PR	<input checked="" type="checkbox"/>
--------	------	----	------------	----	-----------	---------------------------	----	-------------------------------------

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

LocationEmergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?**Venting:**

Yes/No	Comment

Flaring:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 334542

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 283345 Type: WELL API Number: 077-09026 Status: PR Insp. Status: PR

Facility ID: 283346 Type: WELL API Number: 077-09025 Status: PR Insp. Status: PR

Facility ID: 283347 Type: WELL API Number: 077-09024 Status: PR Insp. Status: PR

Facility ID: 283349 Type: WELL API Number: 077-09023 Status: PR Insp. Status: PR

Facility ID: 283352 Type: WELL API Number: 077-09022 Status: PR Insp. Status: PR

Facility ID: 283354 Type: WELL API Number: 077-09021 Status: PR Insp. Status: PR

Facility ID: 283356	Type: WELL	API Number: 077-09020	Status: PR	Insp. Status: PR
Facility ID: 283360	Type: WELL	API Number: 077-09019	Status: PR	Insp. Status: PR
Facility ID: 283362	Type: WELL	API Number: 077-09018	Status: PR	Insp. Status: PR
Facility ID: 283364	Type: WELL	API Number: 077-09016	Status: PR	Insp. Status: PR

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____

CA Date _____

1003b. Area no longer in use? _____

Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____

Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____

Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐Multi-Well Location ☐**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: SATISFACTOR

Corrective Date: _____

Y

Comment: Breech in berm has been repaired.

CA: _____

Inspector Name: CONKLIN, CURTIS

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Breech in berm has been properly repaired and debris have been removed from location.	conklinc	06/16/2014