

Federal KP 34-18
Inspection # 675200100

Rilling on cut
slope



Trash on
location.



Debris along
access road.

