

Malone- 67S92W 27SWNW

Inspection DOC# 675200130

Erosion and rilling in  
drain on North end of  
location.



Trash on location

