

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
06/26/2014

Document Number:
663903377

Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>335776</u>	<u>335776</u>	<u>LONGWORTH, MIKE</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>10456</u>
Name of Operator:	<u>CAERUS PICEANCE LLC</u>
Address:	<u>600 17TH STREET #1600N</u>
City:	<u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Winters, Ed		ewinters@caerusoilandgas.com	

Compliance Summary:

QtrQtr:	<u>SESE</u>	Sec:	<u>12</u>	Twp:	<u>6S</u>	Range:	<u>97W</u>
---------	-------------	------	-----------	------	-----------	--------	------------

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
09/05/2013	663902131			SATISFACTORY Y	F		No

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
269986	WELL	PR	05/31/2005	GW	045-09437	CHEVRON/TEXACO 44C-12D	PR	<input checked="" type="checkbox"/>
269987	WELL	PR	05/31/2005	GW	045-09433	CHEVRON/TEXACO 33C-12D	PR	<input checked="" type="checkbox"/>
269988	WELL	PR	05/31/2005	GW	045-09434	CHEVRON/TEXACO 43C-12D	PR	<input checked="" type="checkbox"/>
269989	WELL	PR	11/30/2007	GW	045-09436	CHEVRON/TEXACO 41C-13D	PR	<input checked="" type="checkbox"/>
435780	NONFACILIT Y	AC	01/09/2014		-	Chevron/Texaco 33C-12D 435780	AC	<input type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Signs/Marker:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
TANK LABELS/PLACARDS	SATISFACTORY			
WELLHEAD	SATISFACTORY			
BATTERY	SATISFACTORY			

Emergency Contact Number (S/A/V): SATISFACTORY Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
TANK BATTERY	SATISFACTORY			
SEPARATOR	SATISFACTORY			
WELLHEAD	SATISFACTORY			

Equipment:					
Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Horizontal Heated Separator	4	SATISFACTORY			
Plunger Lift	4	SATISFACTORY			
Bird Protectors	2	SATISFACTORY			

Facilities:		<input type="checkbox"/> New Tank	Tank ID: _____	
Contents	#	Capacity	Type	SE GPS
METHANOL	1	<50 BBLS	STEEL AST	,
S/A/V:	SATISFACTORY		Comment:	
Corrective Action:				Corrective Date:
<u>Paint</u>				
Condition	Adequate			
Other (Content)	_____			
Other (Capacity)	_____			
Other (Type)	_____			
<u>Berms</u>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Corrective Action				Corrective Date
Comment				

Facilities:		<input type="checkbox"/> New Tank	Tank ID: _____	
Contents	#	Capacity	Type	SE GPS
CONDENSATE	1	400 BBLS	STEEL AST	,
S/A/V:	SATISFACTORY		Comment:	
Corrective Action:				Corrective Date:
<u>Paint</u>				
Condition	Adequate			
Other (Content)	_____			
Other (Capacity)	_____			
Other (Type)	_____			
<u>Berms</u>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Corrective Action				Corrective Date
Comment				

Facilities:		<input type="checkbox"/> New Tank	Tank ID: _____		
Contents	#	Capacity	Type	SE GPS	
PRODUCED WATER	2	200 BBLS	PBV STEEL		
S/AV:	SATISFACTORY		Comment:		
Corrective Action:				Corrective Date:	
Paint					
Condition	Adequate				
Other (Content)	_____				
Other (Capacity)	_____				
Other (Type)	_____				
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Corrective Action					Corrective Date
Comment					
Venting:					
Yes/No	Comment				
Flaring:					
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date	

Predrill

Location ID: 335776

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AV: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 269986 Type: WELL API Number: 045-09437 Status: PR Insp. Status: PR

Producing Well

Comment: **Producing well**

Facility ID: 269987 Type: WELL API Number: 045-09433 Status: PR Insp. Status: PR

Producing Well

Comment: **Producing well**

Facility ID: 269988 Type: WELL API Number: 045-09434 Status: PR Insp. Status: PR

Producing Well

Comment: **Producing well**

Facility ID: 269989 Type: WELL API Number: 045-09436 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Environmental

Spills/Releases:

Type of Spill: Description: Estimated Spill Volume:
Comment:
Corrective Action: Date:
Reportable: GPS: Lat Long
Proximity to Surface Water: Depth to Ground Water:

Water Well:

DWR Receipt Num: Owner Name: GPS: Lat Long

Field Parameters:

Sample Location:

Emission Control Burner (ECB):
Comment:
Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: Date Interim Reclamation Completed:
Land Use:
Comment:
1003a. Debris removed? CM
CA CA Date
Waste Material Onsite? CM
CA CA Date
Unused or unneeded equipment onsite? CM
CA CA Date
Pit, cellars, rat holes and other bores closed? CM
CA CA Date
Guy line anchors removed? CM
CA CA Date
Guy line anchors marked? CM
CA CA Date
1003b. Area no longer in use? Production areas stabilized ?

1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment:

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment:

Corrective Action: Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap	Pass					
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Ditches	Pass			
Ditches	Pass	Culverts	Pass			
Check Dams	Pass					
Seeding	Pass	Gravel	Pass			
Berms	Pass	Check Dams	Pass			

Inspector Name: LONGWORTH, MIKE

S/A/V: SATISFACTOR
Y

Corrective Date: _____

Comment:

CA:

Pits: NO SURFACE INDICATION OF PIT