

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:

06/26/2014

Document Number:

675200147

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	334881	334881	CONKLIN, CURTIS	<input type="checkbox"/>	

**Operator Information:**OGCC Operator Number: 10071Name of Operator: BARRETT CORPORATION\* BILLAddress: 1099 18TH ST STE 2300City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shuan.kellerby@state.co.us	
Fallang, Tracey		tfallang@billbarrettcorp.com	All Inspections
Axelson, Aaron	970-230-0926	aaxelson@billbarrettcorp.com	Production Foreman
Hirtler, Christina	970-876-1959	chirtler@billbarrettcorp.com	All Inspections

**Compliance Summary:**QtrQtr: SENW Sec: 31 Twp: 6S Range: 91W**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
211493	WELL	AL	10/26/2000	LO	045-07253	GIBSON GULCH UNIT 7-31	AL	<input type="checkbox"/>
211517	WELL	PR	07/16/2009	GW	045-07277	GIBSON GULCH UNIT 6-31	PR	<input checked="" type="checkbox"/>
211518	WELL	PR	12/27/2007	GW	045-07278	GIBSON GULCH UNIT 5-31	PR	<input checked="" type="checkbox"/>
211519	WELL	PR	07/16/2009	OW	045-07279	GIBSON GULCH UNIT 6-31 C	PR	<input checked="" type="checkbox"/>
260610	WELL	PR	07/16/2009	OW	045-07878	GIBSON GULCH UNIT 6-31D	PR	<input checked="" type="checkbox"/>
260611	WELL	PR	07/16/2009	GW	045-07879	GIBSON GULCH UNIT 11-31	PR	<input checked="" type="checkbox"/>
261023	WELL	PR	07/16/2009	GW	045-07924	GIBSON GULCH 12-31	PR	<input checked="" type="checkbox"/>
291170	WELL	PR	03/15/2008	GW	045-14314	GGU MILLER 12A-31-691	PR	<input checked="" type="checkbox"/>
291171	WELL	PR	03/27/2008	GW	045-14309	GGU MILLER 23C-31-691	PR	<input checked="" type="checkbox"/>
291172	WELL	PR	03/15/2008	GW	045-14310	GGU MILLER 13D-31-691	PR	<input checked="" type="checkbox"/>
291173	WELL	PR	03/15/2008	GW	045-14311	GGU MILLER 22A-31-691	PR	<input checked="" type="checkbox"/>

Inspector Name: CONKLIN, CURTIS

291174	WELL	PR	02/10/2008	GW	045-14312	GGU MILLER 22D-31-691	PR	<input checked="" type="checkbox"/>
291175	WELL	PR	03/15/2008	GW	045-14313	GGU MILLER 13C-31-691	PR	<input checked="" type="checkbox"/>

**Equipment:**Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location****Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date
Main	SATISFACTORY			
Access	SATISFACTORY			

**Signs/Marker:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
CONTAINERS	SATISFACTORY			
TANK LABELS/PLACARDS	SATISFACTORY			
WELLHEAD	SATISFACTORY			

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

**Good Housekeeping:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
TRASH	ACTION REQUIRED	Some trash on location. See attached photos	Remove	07/25/2014

**Spills:**

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?**Fencing/:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY	Panels		
TANK BATTERY	SATISFACTORY	Panels		
SEPARATOR	SATISFACTORY	Panels		

<b>Equipment:</b>					
Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Ancillary equipment	2	SATISFACTORY	Chem units w/ containment		
Horizontal Heated Separator	12	SATISFACTORY	No containment		
Emission Control Device	1	SATISFACTORY	Lit at time of inspection		
Plunger Lift	12	SATISFACTORY			
Gathering Line	1	SATISFACTORY			
Deadman # & Marked	8	SATISFACTORY			
Bird Protectors	10	SATISFACTORY			

**Facilities:** ☐ New Tank Tank ID: \_\_\_\_\_

Contents	#	Capacity	Type	SE GPS
CONDENSATE	2	500 BBLS	STEEL AST	39.485140,-107.599910

S/A/V: SATISFACTORY Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Paint

Condition	Adequate
-----------	----------

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action \_\_\_\_\_ Corrective Date \_\_\_\_\_

Comment \_\_\_\_\_

**Facilities:** ☐ New Tank Tank ID: \_\_\_\_\_

Contents	#	Capacity	Type	SE GPS
CONDENSATE	2	500 BBLS	HEATED STEEL AST	,

S/A/V: SATISFACTORY Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Paint

Condition	Adequate
-----------	----------

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Corrective Action \_\_\_\_\_ Corrective Date \_\_\_\_\_

Comment **Same**

<b>Venting:</b>		
Yes/No	Comment	
YES	Bradenhead valves open	

<b>Flaring:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

**Predrill**

Location ID: 334881

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/A/V:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Wildlife BMPs:****S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Stormwater:****Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 211517 Type: WELL API Number: 045-07277 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Facility ID:	211518	Type:	WELL	API Number:	045-07278	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Facility ID:	211519	Type:	WELL	API Number:	045-07279	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Facility ID:	260610	Type:	WELL	API Number:	045-07878	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Facility ID:	260611	Type:	WELL	API Number:	045-07879	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Facility ID:	261023	Type:	WELL	API Number:	045-07924	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR. Staining under wing valve								
Facility ID:	291170	Type:	WELL	API Number:	045-14314	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR. Staining under wing valve.								
Facility ID:	291171	Type:	WELL	API Number:	045-14309	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Facility ID:	291172	Type:	WELL	API Number:	045-14310	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR. Audible leak at wing valve.								
Facility ID:	291173	Type:	WELL	API Number:	045-14311	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Facility ID:	291174	Type:	WELL	API Number:	045-14312	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Facility ID:	291175	Type:	WELL	API Number:	045-14313	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
<b>Environmental</b>									

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_  
 Comment: \_\_\_\_\_  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_  
 Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_  
 Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

Lat \_\_\_\_\_ Long \_\_\_\_\_  
 DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Debris removed? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Waste Material Onsite? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Unused or unneeded equipment onsite? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Pit, cellars, rat holes and other bores closed? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Inspector Name: CONKLIN, CURTIS

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	MHSP	Pass	
Slope Roughening	Pass					
Gravel	Pass	Ditches	Pass			
Seeding	Pass	Gravel				

S/A/V: SATISFACTOR \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Y

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
Staining under three wellheads, with one having an audible leak. Some trash on location. See attached photos.	conklinc	06/26/2014

**Attached Documents**

Inspector Name: CONKLIN, CURTIS

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675200147	INSPECTION APPROVED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3376044">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3376044</a>
675200157	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3376025">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3376025</a>