

API: 057- 06128

06/17/2014

Site Inspection pictures (4 total)



Pad access road sparse of vegetation.



Pad with gravel, compaction and sparse vegetation.



Debris left on site.



Debris on site. Cattle will pose reclamation issues (recommend fencing of location and access road).