

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
06/25/2014

Document Number:
673704470

Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>233166</u>	<u>316914</u>	<u>Sherman, Susan</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>7800</u>
Name of Operator:	<u>BEREN CORPORATION</u>
Address:	<u>2020 N BRAMBLEWOOD STREET</u>
City:	<u>WICHITA</u> State: <u>KS</u> Zip: <u>67206</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Reynolds, Rodney	(620) 345-9878	reynoldsr@berexco.com	

Compliance Summary:

QtrQtr: NENW Sec: 7 Twp: 4S Range: 53W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
08/13/2013	664001203	IJ	AC	SATISFACTOR Y			No
07/27/2012	663700052	IJ	AC	SATISFACTOR Y			No
07/13/2012	663400598	IJ	AC	ACTION REQUIRED	P		No
09/12/2011	200320641	MI	TA	SATISFACTOR Y			No
08/22/2011	200319727	MI	SI	ACTION REQUIRED			Yes
09/10/2010	200271059	MI	SI	SATISFACTOR Y			No
08/19/2010	200268036	MI	SI	SATISFACTOR Y			Yes
08/13/2010	200266870	MI	AC	ACTION REQUIRED			Yes
08/26/2009	200217347	MI	AC	SATISFACTOR Y			No
07/10/2009	200215327	RT	AC	SATISFACTOR Y			No
08/05/2008	200193690	MI	SI	SATISFACTOR Y			No
06/15/2007	200115783	MI	SI	SATISFACTOR Y		Pass	No
04/27/2006	200089816	MI	AC	SATISFACTOR Y		Pass	No
08/25/2005	200075995	MI	AC	SATISFACTOR Y		Pass	No

Inspector Name: Sherman, Susan

08/10/2004	200058483	MI	AC	SATISFACTOR Y	Pass	No
07/16/2003	200041681	MI	AC	SATISFACTOR Y	Pass	No
08/21/2002	200029718	MI	AC	SATISFACTOR Y	Pass	No
08/15/2001	200019245	MI	AC	SATISFACTOR Y	Pass	No
06/27/2000	200008059	MI	SI	SATISFACTOR Y	Fail	Yes
03/09/1995	500158142	RT	AC			No

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
150017	UIC DISPOSAL	AC	07/09/1973		-	SCOTT 1	AC
233166	WELL	IJ	07/27/2001	OW	121-05190	SCOTT 1-WD	AC

Equipment:

Location Inventory

Special Purpose Pits: _____ Drilling Pits: _____ Wells: _____ Production Pits: _____
 Condensate Tanks: _____ Water Tanks: _____ Separators: _____ Electric Motors: _____
 Gas or Diesel Mortors: _____ Cavity Pumps: _____ LACT Unit: _____ Pump Jacks: _____
 Electric Generators: _____ Gas Pipeline: _____ Oil Pipeline: _____ Water Pipeline: _____
 Gas Compressors: _____ VOC Combustor: _____ Oil Tanks: _____ Dehydrator Units: _____
 Multi-Well Pits: _____ Pigging Station: _____ Flare: _____ Fuel Tanks: _____

Location

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY	see attached photo		

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

Multiple Spills and Releases?

Venting:

Yes/No	Comment

Flaring:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 233166

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AV: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 233166 Type: WELL API Number: 121-05190 Status: IJ Insp. Status: AC

Underground Injection Control

UIC Violation: _____

Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg _____
(e.g. 30 psig or -30" Hg)

Previous Test Pressure _____

MPP _____

Inj Zone: JSND

TC: Pressure or inches of Hg _____

Previous Test Pressure _____

Last MIT: 08/13/2013

Brhd: Pressure or inches of Hg _____

Previous Test Pressure _____

AnnMTRReq: _____

Comment: _____

Method of Injection: GRAVITY FEED

Test Type: 5 Year

Tbg psi: 350

Csg psi: 0

BH psi: _____

Insp. Status: Pass

Comment: Annual test required because of cemented tubing per pumper. MIRU Canary. Initial-350 psi, 5 min-350 psi, 10 min-350 psi, 15 min-350 psi. 0 psi lost. PASS.

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673704555	Beren Scott 1 WD well sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3376932
673704556	Beren Scott 1 WD wellhead for MIT	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3376933
673704557	Berne Scott 1 WD MIT 6/25/2014	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3376934