

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



| | | | |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:
06/27/2014

Document Number:
668301840

Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

| | | | | | |
|---------------------|-------------|--------|------------------|---|-------------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection <input type="checkbox"/> | 2A Doc Num: _____ |
| | 300224 | 336365 | JOHNSON, RANDELL | | |

Operator Information:

OGCC Operator Number: 100185

Name of Operator: ENCANA OIL & GAS (USA) INC

Address: 370 17TH ST STE 1700

City: DENVER State: CO Zip: 80202-

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|--------------|--------------------------------|----------------------------|
| House, Chris | 303-774-3972 | larry.house@encana.com | Strategic Projects Advisor |
| Group, Email | | cogcc.djinspections@encana.com | Group Email |

Compliance Summary:

QtrQtr: NENW Sec: 12 Twp: 2N Range: 68W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| 01/13/2010 | 200236323 | OI | ND | SATISFACTORY Y | | | No |

Inspector Comment:

Related Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status | |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|-------------------------------------|
| 278977 | WELL | PR | 10/02/2006 | OW | 123-23120 | JOHNSON 21-12 | SI | <input checked="" type="checkbox"/> |
| 300219 | WELL | PR | 05/04/2011 | GW | 123-29655 | JOHNSON 2-0-12 | SI | <input checked="" type="checkbox"/> |
| 300224 | WELL | PR | 05/04/2011 | GW | 123-29658 | JOHNSON 4-2-12 | SI | <input checked="" type="checkbox"/> |

Equipment:

Location Inventory

| | | | |
|------------------------------|-------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: <u>1</u> | Wells: <u>3</u> | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: <u>3</u> | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

| Signs/Marker: | | | | |
|----------------------|------------------------------|---------|-------------------|---------|
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| WELLHEAD | | | | |

Emergency Contact Number (S/A/V): SATISFACTORY Corrective Date: _____

Comment: _____

Corrective Action: _____

| Spills: | | | | |
|--|------|--------|-------------------|---------|
| Type | Area | Volume | Corrective action | CA Date |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |

| Fencing/: | | | | |
|------------------|------------------------------|-----------------------------------|-------------------|---------|
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| WELLHEAD | SATISFACTORY | Chain-link w/privacy slat fencing | | |

| Equipment: | | | | | |
|-------------------|---|------------------------------|---------|-------------------|---------|
| Type | # | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| Plunger Lift | 3 | SATISFACTORY | | | |

Facilities: New Tank Tank ID: _____

| Contents | # | Capacity | Type | SE GPS |
|----------|---|----------|---------------------|-----------------------|
| | | | CENTRALIZED BATTERY | 40.156400,-104.955120 |

S/A/V: SATISFACTORY Comment: See related inspection document #668301839 for information concerning shared facilities and equipment

Corrective Action: _____ Corrective Date: _____

Paint

| | |
|-----------|----------|
| Condition | Adequate |
|-----------|----------|

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |

Corrective Action _____ Corrective Date _____

Comment _____

| Venting: | |
|-----------------|---------|
| Yes/No | Comment |
| NO | |

| Flaring: | | | | |
|-----------------|------------------------------|---------|-------------------|---------|
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| | | | | |

Predrill

Location ID: 300224

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

| Group | User | Comment | Date |
|--------|--------|---|------------|
| Agency | scottp | Location is in a sensitive area because of shallow groundwater; therefore, either a lined drilling pit or closed loop system is required. | 01/05/2010 |

S/A/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/A/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 278977 Type: WELL API Number: 123-23120 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

S/A/V: _____ CA Date: _____

CA: _____

Comment: Producing intermittently

Facility ID: 300219 Type: WELL API Number: 123-29655 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____
S/A/V: _____ CA Date: _____
CA: _____
Comment: **Producing intermittently**

Facility ID: 300224 Type: WELL API Number: 123-29658 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____
S/A/V: _____ CA Date: _____
CA: _____
Comment: **Producing intermittently**

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
Comment: _____
Corrective Action: _____ Date: _____
Reportable: _____ GPS: Lat _____ Long _____
Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS: _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____
Comment: _____
Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____
Land Use: IRRIGATED
Comment: _____
1003a. Debris removed? Pass CM _____
CA _____ CA Date _____
Waste Material Onsite? Pass CM _____
CA _____ CA Date _____
Unused or unneeded equipment onsite? Pass CM _____
CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? Pass CM _____

CA _____ CA Date _____
 Guy line anchors removed? Pass CM _____
 CA _____ CA Date _____
 Guy line anchors marked? _____ CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass
 Production areas have been stabilized? Pass Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____
 Comment: _____

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: IRRIGATED

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|------------|
| Other | Pass | Other | Pass | | | Vegetation |

Inspector Name: JOHNSON, RANDELL

| | | | | | | |
|------------|------|------------|------|--|--|--|
| Compaction | Pass | Compaction | Pass | | | |
| Gravel | Pass | Gravel | Pass | | | |

S/A/V: SATISFACTOR Corrective Date: _____
Y _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT