

Shideler – 68S92W 6SENE

Inspection DOC# 675200169

Debris near wellhead



Trash behind tank containment



Unused culvert

