

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
07/14/2014

Document Number:
668602844

Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>205978</u>	<u>321081</u>	<u>QUINT, CRAIG</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>61650</u>
Name of Operator:	<u>MURFIN DRILLING COMPANY INC</u>
Address:	<u>250 N WATER ST STE 300</u>
City:	<u>WICHITA</u> State: <u>KS</u> Zip: <u>67202</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Esquivel, James	620-272-4913 cell	280189@pld.com	

Compliance Summary:

QtrQtr: NWNW Sec: 1 Twp: 35S Range: 46W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
04/30/2013	668600703	IJ	AC	SATISFACTORY Y			No
07/27/2011	200316372	MI	AC	SATISFACTORY Y			No
06/22/2010	200257321	RT	AC	SATISFACTORY Y			No
08/03/2009	200216139	RT	AC	SATISFACTORY Y			No
08/21/2008	200194108	RT	AC	SATISFACTORY Y			No
07/16/2008	200193308	RT	AC	ACTION REQUIRED			Yes
07/11/2007	200114821	RT	AC	SATISFACTORY Y		Pass	No
08/02/2006	200094753	MI	AC	SATISFACTORY Y		Pass	No
02/10/2005	200066914	RT	AC	SATISFACTORY Y		Pass	No
08/10/2004	200058037	RT	AC	SATISFACTORY Y		Pass	No
07/28/2003	200042214	RT	AC	SATISFACTORY Y		Pass	No
08/08/2002	200029685	RT	AC	SATISFACTORY Y		Pass	No
08/23/2001	200019489	MI	AC	SATISFACTORY Y		Pass	No
02/23/2001	200015415	PR	AC	SATISFACTORY Y	I	Pass	No

Inspector Name: QUINT, CRAIG

03/03/2000	200005087	RT	AC	SATISFACTORY	I	Pass	No
04/26/1999	500136302	PR	AC			Pass	No
06/11/1998	500136301	PR	AC			Pass	No
02/13/1997	500136300	PR	AC			Pass	No

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
205978	WELL	IJ	03/02/1994	OW	009-06393	S E CAMPO UNIT 601W	AC	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Action Required	comment	Corrective Action	Date
Access	SATISFACTORY	GRAVEL ROAD THROUGH PASTURE.		

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY	LEASE SIGN BY WELL		

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

Multiple Spills and Releases?

Fencing/:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY	STEEL PANELS AROUND ALL EQUIPMENT		

Facilities:		<input type="checkbox"/> New Tank	Tank ID: _____		
Contents	#	Capacity	Type	SE GPS	
			CENTRALIZED BATTERY	37.031760,-102.549700	
S/A/V:			Comment:		
Corrective Action:				Corrective Date:	
Paint					
Condition					
Other (Content)	_____				
Other (Capacity)	_____				
Other (Type)	_____				
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Corrective Action				Corrective Date	
Comment					
Venting:					
Yes/No	Comment				
Flaring:					
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date	

Predrill

Location ID: 205978

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AV: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AV: _____ **Comment:**

CA: **Date:** _____

Wildlife BMPs:

S/AV: _____ **Comment:**

CA: **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 205978 Type: WELL API Number: 009-06393 Status: IJ Insp. Status: AC

Underground Injection Control

UIC Violation: _____

Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg 320
(e.g. 30 psig or -30" Hg)

Previous Test Pressure _____

MPP _____

Inj Zone: LNSNG

TC: Pressure or inches of Hg 0

Previous Test Pressure _____

Last MIT: 07/27/2011

Brhd: Pressure or inches of Hg _____

Previous Test Pressure _____

AnnMTReq: NO

Comment: **CASING WAS DEAD, TBG IJ @ 320 PSIG**

Method of Injection: PUMP FEED

Test Type: _____

Tbg psi: _____

Csg psi: _____

BH psi: _____

Insp. Status: _____

Comment: _____

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Pass CM _____

CA _____ CA Date _____

Waste Material Onsite? Pass CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass CM _____

CA _____ CA Date _____
 Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors marked? Pass CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced Pass Recontoured Pass 80% Revegetation Pass

1003 f. Weeds Noxious weeds? _____ P _____

Comment: **UNUSED AREAS OF THE LOCATION ARE PASTURE.**

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Inspector Name: QUINT, CRAIG

Gravel	Pass	Gravel	Pass			
--------	------	--------	------	--	--	--

S/A/V: SATISFACTOR Corrective Date: _____
Y _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT