

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
07/14/2014

Document Number:
668602849

Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection <input type="checkbox"/>
	206048	321102	QUINT, CRAIG	2A Doc Num: _____

Operator Information:

OGCC Operator Number: <u>10330</u>
Name of Operator: <u>INVESTMENT EQUIPMENT LLC</u>
Address: <u>17509 COUNTY ROAD 14</u>
City: <u>FT MORGAN</u> State: <u>CO</u> Zip: <u>80701</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Rebol, Dave		investmentequipment@cox.net	

Compliance Summary:

QtrQtr: NWSE Sec: 2 Twp: 35S Range: 46W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
08/15/2013	668601218	IJ	SI	SATISFACTORY Y			No
07/11/2013	668601066	IJ	SI	ACTION REQUIRED	P		No
07/27/2011	200316361	RT	SI	ACTION REQUIRED			Yes
06/22/2010	200257307	RT	SI	ACTION REQUIRED			Yes
08/03/2009	200216171	RT	SI	ACTION REQUIRED			Yes
02/17/2009	200207482	ES	AC	ACTION REQUIRED			Yes
07/16/2008	200193290	RT	SI	SATISFACTORY Y			No
09/20/2007	200119162	MI	SI	SATISFACTORY Y			No
05/02/2007	200110311	RT	UN	ACTION REQUIRED		Fail	Yes
08/01/2006	200094743	RT	AC	ACTION REQUIRED		Fail	Yes
02/10/2005	200066922	RT	AC	SATISFACTORY Y		Pass	No
08/10/2004	200058051	RT	AC	SATISFACTORY Y		Pass	No
07/29/2003	200042206	MI	AC	SATISFACTORY Y		Pass	No
08/08/2002	200029682	RT	AC	SATISFACTORY Y		Pass	No

Inspector Name: QUINT, CRAIG

08/23/2001	200019480	RT	AC	SATISFACTORY Y		Pass	No
02/23/2001	200015391	PR	AC	SATISFACTORY Y	I	Pass	No
03/03/2000	200005082	RT	AC	SATISFACTORY Y	I	Pass	No
05/04/1999	500136415	PR	AC			Pass	No
06/11/1998	500136414	PR	AC			Pass	No
02/13/1997	500136413	PR	AC			Pass	No

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
206048	WELL	SI	05/27/2014	OW	009-06464	TSRU 204W	SI	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____ Drilling Pits: _____ Wells: _____ Production Pits: _____
 Condensate Tanks: _____ Water Tanks: _____ Separators: _____ Electric Motors: _____
 Gas or Diesel Mortors: _____ Cavity Pumps: _____ LACT Unit: _____ Pump Jacks: _____
 Electric Generators: _____ Gas Pipeline: _____ Oil Pipeline: _____ Water Pipeline: _____
 Gas Compressors: _____ VOC Combustor: _____ Oil Tanks: _____ Dehydrator Units: _____
 Multi-Well Pits: _____ Pigging Station: _____ Flare: _____ Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Action Required	comment	Corrective Action	Date
Access	SATISFACTORY	GRAVEL ROAD THROUGH PASTURE WITH A CATTLE GUARD.		

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY	LEASE SIGN BY WELL		

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY	STEEL PANELS AROUND ALL WELLHEAD EQUIPMENT		

Venting:	
Yes/No	Comment

Flaring:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 206048

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AV: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 206048 Type: WELL API Number: 009-06464 Status: SI Insp. Status: SI

Underground Injection Control

UIC Violation: _____

Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg -20.5" HG
(e.g. 30 psig or -30" Hg)

Previous Test Pressure _____ MPP _____
Inj Zone: LNSNG

TC: Pressure or inches of Hg 0 PSIG

Previous Test Pressure _____ Last MIT: 08/15/2013

Brhd: Pressure or inches of Hg _____

Previous Test Pressure _____ AnnMTRReq: NO

Comment: **WELL WAS NOT INJECTING AT TIME OF INSPECTION, CASING HAD A LIGHT BLOW THAT DIED IMMEDIATELY, TBG HAD 20.5" VACUUM.**

Method of Injection: PUMP FEED

Test Type: _____

Tbg psi: _____

Csg psi: _____

BH psi: _____

Insp. Status: _____

Comment: _____

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS: _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Pass CM _____

CA _____ CA Date _____

Waste Material Onsite? Pass CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass

Production areas have been stabilized? Pass Segregated soils have been replaced? Pass

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced Pass Recontoured Pass 80% Revegetation Pass

1003 f. Weeds Noxious weeds? _____ P _____

Comment: UNUSED AREAS OF THE LOCATION ARE PASTURE.

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment:

Corrective Action: Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Other	Pass			

Inspector Name: QUINT, CRAIG

Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

S/A/V: SATISFACTOR Corrective Date: _____
Y _____

Comment: ACCESS AND LOCATION ARE PARTIALLY COVERED WITH GRASS.

CA: _____

Pits: NO SURFACE INDICATION OF PIT