

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

DE ET OE ES

Inspection Date:

07/17/2014

Document Number:

675200244

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	334232	334232	CONKLIN, CURTIS	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
, Encana		cogcc.inspections@encana.com	All Inspections
Kellerby, Shaun		shuan.kellerby@state.co.us	NW Supervisor

Compliance Summary:QtrQtr: SESE Sec: 26 Twp: 7S Range: 93W**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
405	WELL	PR	07/27/2008	GW	045-15499	SHIDELER 26-9D (P26W)	PR	<input checked="" type="checkbox"/>
280539	WELL	PR	07/02/2006	GW	045-11285	SHIDELER 26-9 (P26W)	PR	<input checked="" type="checkbox"/>
280541	WELL	PR	07/02/2006	GW	045-11286	SHIDELER 26-16 (P26W)	PR	<input checked="" type="checkbox"/>
294562	WELL	PR	07/19/2008	GW	045-15523	SHIDELER 25-13D (P26W)	PR	<input checked="" type="checkbox"/>
294563	WELL	PR	07/21/2008	GW	045-15522	SHIDELER FEDERAL 36-12C (P26W)	PR	<input checked="" type="checkbox"/>
294565	WELL	PR	07/22/2008	GW	045-15520	SHIDELER FEDERAL 35-9D(P26W)	PR	<input checked="" type="checkbox"/>
294567	WELL	PR	07/25/2008	GW	045-15521	SHIDELER 26-16D (P26W)	PR	<input checked="" type="checkbox"/>

Equipment:**Location Inventory**

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date
Main	SATISFACTORY			
Access	SATISFACTORY			

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
CONTAINERS	SATISFACTORY			
WELLHEAD	SATISFACTORY			
TANK LABELS/PLACARDS	SATISFACTORY			

Emergency Contact Number (S/A/V): _____

Corrective Date: _____

Comment: **Nearest public access not listed**

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?**Fencing/:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
LOCATION	SATISFACTORY	Wire fence		
TANK BATTERY	SATISFACTORY	Panels		

Equipment:

Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Vertical Heated Separator	7	SATISFACTORY	No containment		
Gas Meter Run	1	SATISFACTORY			
Pig Station	1	SATISFACTORY			
Gathering Line	1	SATISFACTORY			
Bird Protectors	2	SATISFACTORY			
Ancillary equipment	2	SATISFACTORY	Chem units w/ containments		
Plunger Lift	7	SATISFACTORY			

Facilities:		<input type="checkbox"/> New Tank		Tank ID: _____	
Contents	#	Capacity	Type	SE GPS	
METHANOL	1	OTHER	STEEL AST	,	
S/A/V:			Comment:		
Corrective Action:				Corrective Date:	
<u>Paint</u>					
Condition					
Other (Content) _____					
Other (Capacity) 24bbl _____					
Other (Type) _____					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
		Walls Sufficient	Base Sufficient	Adequate	
Corrective Action				Corrective Date	
Comment					
Facilities:		<input type="checkbox"/> New Tank		Tank ID: _____	
Contents	#	Capacity	Type	SE GPS	
CONDENSATE	5	300 BBLS	STEEL AST	,	
S/A/V:	SATISFACTORY		Comment:		
Corrective Action:				Corrective Date:	
<u>Paint</u>					
Condition	Adequate				
Other (Content) _____					
Other (Capacity) _____					
Other (Type) _____					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Corrective Action				Corrective Date	
Comment					
Venting:					
Yes/No		Comment			
NO					
Flaring:					
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date	

Predrill

Location ID: 334232

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 405 Type: WELL API Number: 045-15499 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Facility ID: 280539 Type: WELL API Number: 045-11285 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Facility ID: 280541 Type: WELL API Number: 045-11286 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Facility ID: 294562 Type: WELL API Number: 045-15523 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Facility ID: 294563 Type: WELL API Number: 045-15522 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Facility ID: 294565 Type: WELL API Number: 045-15520 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Facility ID: 294567 Type: WELL API Number: 045-15521 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Environmental**Spills/Releases:**

Type of Spill: Description: Estimated Spill Volume:

Comment:

Corrective Action: Date:

Reportable: GPS: Lat Long

Proximity to Surface Water: Depth to Ground Water:

Water Well:

Lat Long

DWR Receipt Num: Owner Name: GPS :

Field Parameters:

Sample Location:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use:

Comment:

1003a. Debris removed? CM

CA CA Date

Waste Material Onsite? CM

CA CA Date

Unused or unneeded equipment onsite? _____ CM _____
 CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors marked? _____ CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____
 Debris removed _____ No disturbance /Location never built _____
 Access Roads Regraded _____ Contoured _____ Culverts removed _____
 Gravel removed _____
 Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____
 Compaction alleviation _____ Dust and erosion control _____
 Non cropland: Revegetated 80% _____ Cropland: perennial forage _____
 Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Inspector Name: CONKLIN, CURTIS

Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Check Dams	Pass			
Berms	Pass	Compaction	Pass	MHSP	Pass	
Seeding	Pass	Ditches	Pass			
Slope Roughening	Pass	Rip Rap	Pass			
Gravel	Pass	Culverts	Pass			

S/A/V: SATISFACTOR
Y _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT