

**FORM INSP**  
Rev 05/11

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:  
07/18/2014

Document Number:  
678300011

Overall Inspection:  
SATISFACTORY

**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>434830</u>	<u>434830</u>	<u>GINTAUTAS, PETER</u>	<input type="checkbox"/>	

**Operator Information:**

OGCC Operator Number:	<u>10084</u>
Name of Operator:	<u>PIONEER NATURAL RESOURCES USA INC</u>
Address:	<u>1401 17TH ST STE 1200</u>
City:	<u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

**Compliance Summary:**

QtrQtr: NWNW Sec: 4 Twp: 33S Range: 67W

**Inspector Comment:**

**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
434831	WELL	WO	07/09/2014	LO	071-09916	San Pablo 11-4 WD	WO	<input checked="" type="checkbox"/>

**Equipment:**

Location Inventory

Special Purpose Pits: <u>1</u>	Drilling Pits: <u>1</u>	Wells: <u>1</u>	Production Pits: _____
Condensate Tanks: _____	Water Tanks: <u>2</u>	Separators: _____	Electric Motors: <u>1</u>
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: <u>1</u>	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**

Emergency Contact Number (S/A/V): \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

**Spills:**

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

Multiple Spills and Releases?

**Venting:**

Yes/No	Comment

<b>Flaring:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

**Predrill**

Location ID: 434830

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/AV:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

Group	User	Comment	Date
OGLA	notojohn	Special purpose pit shall be constructed and managed in accordance with provisions detailed in Form 15, Earthen Pit Permit/Report.	09/10/2013

**S/AV:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Wildlife BMPs:**

BMP Type	Comment
Material Handling and Spill Prevention	Spill response equipment shall be available in the event of a spill or release. Pioneer shall investigate spills to ensure proper clean-up/remediation measures & required reporting protocol is implemented.
Storm Water/Erosion Control	Note: Pioneers complete BMP is too extensive for this form and is on file at Pioneer's Denver Office. Following is a summary of the plan:  A diversion ditch will be installed on the cut side to divert the rain water/snow melt from the location. Erosion control devices will be installed on the fill side of the location to contain any erosion from the fill part of the location.
Interim Reclamation	All the areas of the location will be contoured to the original stage

**S/AV:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Stormwater:**

**Comment:** \_\_\_\_\_

**Staking:**

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

Facility ID: 434831    Type: WELL    API Number: 071-09916    Status: WO    Insp. Status: WO

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_  
 Comment:   
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_  
 Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_  
 Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location:

Emission Control Burner (ECB): \_\_\_\_\_  
 Comment: \_\_\_\_\_  
 Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_  
 Land Use: TIMBER  
 Comment:   
 1003a. Debris removed? \_\_\_\_\_ CM \_\_\_\_\_  
       CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Waste Material Onsite? \_\_\_\_\_ CM \_\_\_\_\_  
       CA \_\_\_\_\_ CA Date \_\_\_\_\_  
       Unused or unneeded equipment onsite? \_\_\_\_\_ CM \_\_\_\_\_  
       CA \_\_\_\_\_ CA Date \_\_\_\_\_  
       Pit, cellars, rat holes and other bores closed? \_\_\_\_\_ CM \_\_\_\_\_  
       CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_  
       CA \_\_\_\_\_ CA Date \_\_\_\_\_  
       Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_  
       CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_  
 1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation  In Process

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: TIMBER

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation  Well Release on Active Location  Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Culverts	Pass	MHSP	Pass	uncovered and opened materials removed
Rip Rap	Pass					
Ditches	Pass					

S/A/V: SATISFACTOR Corrective Date: \_\_\_\_\_  
Y

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

Pit Type: <u>Drilling Pit</u>	Lined: <u>YES</u>	Pit ID: _____	Lat: _____	Long: _____
<b>Lining:</b>				
Liner Type: <u>PVC</u>	Liner Condition: <u>Adequate</u>			
Comment: _____				
<b>Fencing:</b>				
Fencing Type: <u>Livestock</u>	Fencing Condition: <u>Adequate</u>			
Comment: _____				
<b>Netting:</b>				
Netting Type: _____	Netting Condition: _____			
Comment: _____				
Anchor Trench Present: <u>YES</u>	Oil Accumulation: <u>NO</u>	2+ feet Freeboard: _____		
Pit (S/AV): <u>ACTION</u>	Comment: <span style="border: 1px solid red; padding: 2px;">Lined two compartment drilling pit present drilling pits must be closed within 6 months after drilling and completion activities are done</span>			
Corrective Action: <span style="border: 1px solid red; padding: 2px;">close or permit pit (permit pending in Eforms system)</span>				Date: <span style="border: 1px solid red; padding: 2px;">02/02/2015</span>

**COGCC Comments**

Comment	User	Date
Workover rig on site. In process of swabbing Entrada Fm to obtain sample of formation water for analysis as part of permitting of injection well.	gintautp	07/21/2014

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
678300011	INSPECTION APPROVED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3390985">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3390985</a>