

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
07/22/2014

Document Number:
674700065

Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>335851</u>	<u>335851</u>	<u>LONGWORTH, MIKE</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>100185</u>
Name of Operator:	<u>ENCANA OIL & GAS (USA) INC</u>
Address:	<u>370 17TH ST STE 1700</u>
City:	<u>DENVER</u> State: <u>CO</u> Zip: <u>80202-</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Goodwin, Amanda		amanda.goodwin@state.co.us	
Insp., General	970-285-2665	cogcc.inspections@encana.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	
YOKLEY, BILL		bill.yokley@state.co.us	

Compliance Summary:

QtrQtr: SWSE Sec: 10 Twp: 5S Range: 96W

Inspector Comment:

Sign at lease road. Lease road and pad have been built. No evidence of wells being drilled.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
285043	WELL	AL	10/13/2011	LO	045-12353	N PARACHUTE WF04B O10A 596	AL	<input checked="" type="checkbox"/>
285044	WELL	AL	10/13/2011	LO	045-12354	N PARACHUTE WF03B O10A 596	AL	<input checked="" type="checkbox"/>
285045	WELL	AL	10/13/2011	LO	045-12355	N PARACHUTE MF04D O10A 596	AL	<input checked="" type="checkbox"/>
285046	WELL	AL	10/13/2011	LO	045-12356	N PARACHUTE WF06B O10A 596	AL	<input checked="" type="checkbox"/>
285047	WELL	AL	10/13/2011	LO	045-12357	N PARACHUTE WF12D O10A 596	AL	<input checked="" type="checkbox"/>
285062	WELL	AL	10/13/2011	LO	045-12368	N PARACHUTE WF12B O10A 596	AL	<input checked="" type="checkbox"/>
285107	WELL	AL	10/13/2011	LO	045-12375	N PARACHUTE WF08D O10A 596	AL	<input checked="" type="checkbox"/>
285108	WELL	AL	10/13/2011	LO	045-12374	N PARACHUTE WF09D O10A 596	AL	<input checked="" type="checkbox"/>
285109	WELL	AL	10/13/2011	LO	045-12373	N PARACHUTE WF13B O10A 596	AL	<input checked="" type="checkbox"/>

285110	WELL	AL	10/13/2011	LO	045-12372	N PARACHUTE WF13D O10A 596	AL	<input checked="" type="checkbox"/>
285111	WELL	AL	10/13/2011	LO	045-12371	N PARACHUTE WF14B O10A 596	AL	<input checked="" type="checkbox"/>
285112	WELL	AL	02/04/2013	LO	045-12370	N PARACHUTE WF16D O10A 596	AL	<input checked="" type="checkbox"/>

Equipment: Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number (S/A/V): _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Venting:

Yes/No	Comment

Flaring:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 335851

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AV: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 285043 Type: WELL API Number: 045-12353 Status: AL Insp. Status: AL

Facility ID: 285044 Type: WELL API Number: 045-12354 Status: AL Insp. Status: AL

Facility ID: 285045 Type: WELL API Number: 045-12355 Status: AL Insp. Status: AL

Facility ID: 285046 Type: WELL API Number: 045-12356 Status: AL Insp. Status: AL

Facility ID: 285047 Type: WELL API Number: 045-12357 Status: AL Insp. Status: AL

Facility ID: 285062 Type: WELL API Number: 045-12368 Status: AL Insp. Status: AL

Facility ID: <u>285107</u>	Type: <u>WELL</u>	API Number: <u>045-12375</u>	Status: <u>AL</u>	Insp. Status: <u>AL</u>
Facility ID: <u>285108</u>	Type: <u>WELL</u>	API Number: <u>045-12374</u>	Status: <u>AL</u>	Insp. Status: <u>AL</u>
Facility ID: <u>285109</u>	Type: <u>WELL</u>	API Number: <u>045-12373</u>	Status: <u>AL</u>	Insp. Status: <u>AL</u>
Facility ID: <u>285110</u>	Type: <u>WELL</u>	API Number: <u>045-12372</u>	Status: <u>AL</u>	Insp. Status: <u>AL</u>
Facility ID: <u>285111</u>	Type: <u>WELL</u>	API Number: <u>045-12371</u>	Status: <u>AL</u>	Insp. Status: <u>AL</u>
Facility ID: <u>285112</u>	Type: <u>WELL</u>	API Number: <u>045-12370</u>	Status: <u>AL</u>	Insp. Status: <u>AL</u>

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment:

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location:

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment:

1003a. Debris removed? _____ CM _____ CA _____ CA Date _____

Waste Material Onsite? _____ CM _____ CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____ CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____
 Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors marked? _____ CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Sign at lease road. Lease road and pad have been built. No evidence of wells being drilled.	longworm	07/22/2014

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674700068	Location sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3392405
674700069	Lease road and location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3392406