

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:

07/21/2014

Document Number:

674900044

Overall Inspection:

ACTION REQUIRED**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	209020	381617	Hughes, Jim	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 100178Name of Operator: SIMMONS, INC.* D. J.Address: 1009 RIDGEWAY PL STE 200City: FARMINGTON State: NM Zip: 87401

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Arthur, Denise		denise.arthur@state.co.us	
FISCHER, ALEX		alex.fischer@state.co.us	
Roy, Catherine		catherine.roy@state.co.us	
Maclaren, Joe		joe.maclaren@state.co.us	
LABOWSKIE, STEVE		steve.labowskie@state.co.us	
Seale, Rod		rseale@djsimmons.com	Pet. Eng./Operations Mgr
Tucker, Laura		ltucker@djsimmons.com	
Lopez, Chris		clopez@djsimmons.com	Regulatory Specialist

Compliance Summary:QtrQtr: NESW Sec: 19 Twp: 39N Range: 19W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
06/04/2014	667700368	PA	PA	ACTION REQUIRED		I	No
08/21/2013	663401140	PA	PA	SATISFACTOR Y		I	No
08/14/2012	669400040	PA	PA	ACTION REQUIRED	I	I	No
04/17/2012	664000490	PA	PA	ACTION REQUIRED		Fail	No
08/18/2011	200318751	HR	PA	ACTION REQUIRED	F	Fail	Yes
08/18/2011	200325767	HR	PA	ACTION REQUIRED	F	Pass	Yes
08/24/2009	200219922	HR	PA	SATISFACTOR Y	P	Pass	No
07/17/2002	200029540	MI	AC	ACTION REQUIRED		Fail	Yes
08/22/2001	200020123	RT	AC	SATISFACTOR Y		Pass	No

Inspector Name: Hughes, Jim

09/01/2000	200009634	RT	AC	SATISFACTOR Y		Pass	No	
------------	-----------	----	----	------------------	--	------	----	--

Inspector Comment:

On July 17, 2014 COGCC staff members Alex Fischer and Jim Hughes conducted a follow up field inspection of the D.J. Simmons Pribble A-1. Please refer to document #667700368 for the most recent field inspection report. The operator has retained the services of an environmental consultant to assist with closure of this location. Samples were collected on July 11, 2014, results are pending. Sample locations were verified in the field by COGCC staff at the time of this inspection. A debris pile located near the southwest corner of the location has been noted on previous inspections. Should the operator claim that this debris pile is not within their responsibility for final reclamation, written documentation of its origins may be required by the reclamation specialist prior to bond release. An oil stained area was noted near the southwestern corner of the eastern barren area, as well as various other apparent spill locations.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
150103	UIC DISPOSAL	CL	01/30/2003		-	PRIBBLE A-1	CL	<input type="checkbox"/>
209020	WELL	PA	01/30/2003	DSPW	033-40004	PRIBBLE A-1	PA	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date
Main	SATISFACTORY			

Emergency Contact Number (S/A/V): _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
TRASH	ACTION REQUIRED	Trash was observed spread over entire location including rags, gloves, drive belts, scrap concrete, etc.	Remove trash from location.	08/17/2014
OTHER	ACTION REQUIRED	Approximately 12' by 1' area of oily soil and rock.	Remove oil stained soils and dispose of properly.	08/17/2014

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☒ Multiple Spills and Releases?

Inspector Name: Hughes, Jim

Venting:	
Yes/No	Comment

Flaring:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 209020

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/A/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/A/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 209020 Type: WELL API Number: 033-40004 Status: PA Insp. Status: PA

Environmental

Inspector Name: Hughes, Jim

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
Comment: _____
Corrective Action: _____ Date: _____
Reportable: _____ GPS: Lat _____ Long _____
Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____
DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____
CA _____ CA Date _____
Waste Material Onsite? _____ CM _____
CA _____ CA Date _____
Unused or unneeded equipment onsite? _____ CM _____
CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? _____ CM _____
CA _____ CA Date _____
Guy line anchors removed? _____ CM _____
CA _____ CA Date _____
Guy line anchors marked? _____ CM _____
CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Inspector Name: Hughes, Jim

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: SATISFACTOR _____ Corrective Date: _____

Y

Comment: _____

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Soil samples have been collected from the Pribble A-1 location, by an independent environmental consultant. Upon reviewing analytical results, should additional remediation be required, a Form 27 Site Investigation and Remediation Work Plan shall be submitted to COGCC EPS staff.	hughesj	07/25/2014

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Inspector Name: Hughes, Jim

Document Num	Description	URL
674900062	Oil stained rock and soil	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3395185
674900063	Apparent soil sample location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3395186
674900064	Debris pile near SW corner of location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3395187
674900065	Soil sample location map	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3395188