

Gasaway Fed-66S99W 26NWSW

Inspection DOC# 675200311

Trash in containment.



Trash on location.



Unused equipment.



Unused equipment.

