

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:

07/25/2014

Document Number:

673704948

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	
	237585	317264	Sherman, Susan	2A Doc Num:	

**Operator Information:**OGCC Operator Number: 88370Name of Operator: TIMKA RESOURCES LTDAddress: 2116 EAST HIGHWAY 402City: LOVELAND State: CO Zip: 80537

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
Pivonka, Todd	(970) 667-9861	timkaresources@hotmail.com	

**Compliance Summary:**QtrQtr: SWSE Sec: 17 Twp: 3N Range: 51W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
07/16/2013	664001111	IJ	AC	SATISFACTORY Y			No
08/16/2012	663400761	IJ	SI	ACTION REQUIRED	P		No
04/21/2011	200308156	RT	AC	ACTION REQUIRED			No
06/22/2010	200257014	RT	AC	SATISFACTORY Y			No
06/22/2009	200213550	RT	AC	SATISFACTORY Y			No
04/16/2008	200130350	RT	AC	SATISFACTORY Y			No
06/22/2007	200115816	MI	SI	SATISFACTORY Y		Pass	No
05/21/2007	200112014	MI	AC	ACTION REQUIRED		Fail	Yes
08/14/2006	200094813	RT	AC	SATISFACTORY Y		Pass	No
07/19/2005	200075038	RT	AC	SATISFACTORY Y		Pass	No
03/17/2004	200051502	RT	AC	SATISFACTORY Y		Pass	No
08/06/2003	200042508	RT	AC	SATISFACTORY Y		Pass	No
06/11/2002	200027279	MI	AC	SATISFACTORY Y		Pass	No
08/24/2001	200022812	RT	AC	SATISFACTORY Y		Pass	No

Inspector Name: Sherman, Susan

06/27/2000	200008062	RT	AC	SATISFACTORY		Pass	No
07/22/1997	500159840	MT	AC			Pass	No
07/15/1997	500159839	ID	SI			Fail	Yes
11/03/1995	500159838		TA			Pass	No
10/03/1995	500159837	ID	SI			Fail	Yes

**Inspector Comment:**

**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
105911	PIT	CL	09/23/1999		-	RICKIE A. WOOD TRUST 1	CL	<input type="checkbox"/>
150413	UIC DISPOSAL	AC	07/31/1997		-	RICKIE A. WOOD TRUST #3	AC	<input type="checkbox"/>
237585	WELL	IJ	06/14/2013	DSPW	121-10088	R.A. WOOD TRUST 3	AC	<input checked="" type="checkbox"/>

**Equipment:**

Location Inventory

Special Purpose Pits: \_\_\_\_\_ Drilling Pits: \_\_\_\_\_ Wells: \_\_\_\_\_ Production Pits: \_\_\_\_\_  
 Condensate Tanks: \_\_\_\_\_ Water Tanks: \_\_\_\_\_ Separators: \_\_\_\_\_ Electric Motors: \_\_\_\_\_  
 Gas or Diesel Motors: \_\_\_\_\_ Cavity Pumps: \_\_\_\_\_ LACT Unit: \_\_\_\_\_ Pump Jacks: \_\_\_\_\_  
 Electric Generators: \_\_\_\_\_ Gas Pipeline: \_\_\_\_\_ Oil Pipeline: \_\_\_\_\_ Water Pipeline: \_\_\_\_\_  
 Gas Compressors: \_\_\_\_\_ VOC Combustor: \_\_\_\_\_ Oil Tanks: \_\_\_\_\_ Dehydrator Units: \_\_\_\_\_  
 Multi-Well Pits: \_\_\_\_\_ Pigging Station: \_\_\_\_\_ Flare: \_\_\_\_\_ Fuel Tanks: \_\_\_\_\_

**Location**

<b>Signs/Marker:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

<b>Good Housekeeping:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
UNUSED EQUIPMENT	ACTION REQUIRED	This action was noted on the 8/16/2012 inspection also. See attached photo.	Remove pumping unit from location.	08/25/2014

<b>Spills:</b>				
Type	Area	Volume	Corrective action	CA Date

☐ Multiple Spills and Releases?

Inspector Name: Sherman, Susan

<b>Equipment:</b>					
Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Other	1	SATISFACTORY	Electric box		

<b>Facilities:</b> <input type="checkbox"/> New Tank Tank ID: _____					
Contents	#	Capacity	Type	SE GPS	
			CENTRALIZED BATTERY	40.221250,-103.107730	
S/A/V:			Comment:		
Corrective Action:				Corrective Date:	

<b>Paint</b>	
Condition	
Other (Content) _____	
Other (Capacity) _____	
Other (Type) _____	

<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Corrective Action			Corrective Date	
Comment				

<b>Venting:</b>		
Yes/No	Comment	

<b>Flaring:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

**Predrill**

Location ID: 237585

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/A/V:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Wildlife BMPs:****S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Stormwater:****Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 237585 Type: WELL API Number: 121-10088 Status: IJ Insp. Status: AC

**Underground Injection Control**

UIC Violation: \_\_\_\_\_

Maximum Injection Pressure: \_\_\_\_\_

**UIC Routine**Inj./Tube: Pressure or inches of Hg -18  
(e.g. 30 psig or -30" Hg)Previous Test Pressure \_\_\_\_\_ MPP \_\_\_\_\_  
Inj Zone: DSND

TC: Pressure or inches of Hg 0

Previous Test Pressure \_\_\_\_\_ Last MIT: 08/16/2012

Brhd: Pressure or inches of Hg \_\_\_\_\_

Previous Test Pressure \_\_\_\_\_ AnnMTReq: \_\_\_\_\_

Comment: \_\_\_\_\_

Method of Injection: \_\_\_\_\_

Test Type: \_\_\_\_\_

Tbg psi: \_\_\_\_\_

Csg psi: \_\_\_\_\_

BH psi: \_\_\_\_\_

Insp. Status: \_\_\_\_\_

Comment: \_\_\_\_\_

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Debris removed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Waste Material Onsite? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_  
 1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
 Cuttings management: \_\_\_\_\_  
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
 Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Inspector Name: Sherman, Susan

S/A/V: \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

Pits: ☐ NO SURFACE INDICATION OF PIT

#### COGCC Comments

Comment	User	Date
This inspection only includes this injection well and not the battery. The tank battery is included with 121-09902's inspection.	ShermaSe	07/29/2014

#### Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673704982	Timka Wood Trust 3 well sign	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3396600">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3396600</a>
673704983	Timka Wood Trust 3 wellhead	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3396601">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3396601</a>
673704984	Timka Wood Trust 3 well IR/crop/DM	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3396602">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3396602</a>
673705001	Timka Wood Trust 3 well unused equipment	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3396603">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3396603</a>