

Federal SP 13-13

Inspection DOC# 675200327

Erosion on cut slope.



First area of erosion on fill slope.



Second area of erosion
on fill slope.



View of second area of
erosion from pad.



Erosion and rilling along
access road.



Sediment in vegetation
from erosion on access
road.

