

Federal 67S95W 12SESE

Inspection DOC# 675200329

Trash on location.




Area of subsidence.



Signs peeled off
container.



Same API number on both wells.



Erosion and rilling along access road.

Sediment in vegetation
from erosion on access
road.

