

Site Photos (05-001-09529) 7/31/14

Pad inaccessible due to ponding.



Significant ponding on well pad.






Site Photos (05-001-09529) 7/31/14

Vegetation transect on top of soil stockpile.



Vegetation transect facing East.





Site Photos (05-001-09529) 7/31/14

Ground cover at 50'.



Facing North.





Site Photos (05-001-09529) 7/31/14

Facing South.



Facing West.

